



February 18, 2025

Kosette Smith
935 Catalonia Ave
Apartment 8
Coral Gables, Florida 33134

RE: 935 Catalonia Ave, Apt. 8, Coral Gables, FL 33134
SUBJECT: Report of Limited Moisture and Mold Assessment
RESULTS: Elevated Mold Growth Identified; Remediation Recommended

Dear Ms. Smith:

Thank you for this opportunity to serve you. We inspected the subject building on February 11, 2024, at 3:30 PM. The subject structure is a one-story apartment, approximately 700 square feet, originally built in 1926.

Elevated mold growth was identified within the subject residence. Remediation recommendations are made in the detailed report that follows.

We hope this information assists you. Please do not hesitate to contact us if you have any further questions regarding this matter or if we may be of any further assistance. Thank you again for this opportunity to serve you.

Sincerely,
Coastal Indoor Environmental Consultants

Kimberly Dunn

Kimberly Cinaroglu-Dunn, RN, MRSA
Florida Registered Nurse #9358838
Florida Licensed Mold Assessor MRSA2251



I. Conditions at Time of Inspection

People present at inspection:

- **Ms. Kosette Smith, Tenant, Client**
- **Ms. Kimberly Dunn, Mold Assessor, Coastal Indoor Environmental Consultants**

The building was occupied and furnished at the time of the inspection.

II. Observations & Findings

The subject structure is a one-story apartment, approximately 700 square feet, circa 1926. We obtained access to the reported moisture-damaged interior locations and inspected suspicious adjacent areas that the reported cause of moisture intrusion may have impacted. The purpose of the inspection was to visually evaluate areas of the residence for possible microbial growth and/or associated water damage, leading to elevated fungal spore counts detected in the living areas.

We collected samples as part of this inspection. The samples were submitted to Daane Labs of Naples, FL, our independent Accredited Laboratory, for analysis. A copy of the laboratory report is attached to this report. We noted the following:

History and Information

It was reported that the residence had experienced water damage with suspected mold growth. There was MVOC (Microbial Volatile Organic Compound) odor present throughout the residence at the time of this assessment. Due to concerns about a possible mold problem, the client has retained Coastal Indoor Environmental Consultants to assess the residence's fungal ecology.



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.

Miami, FL 33157

305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 2 of 16

Exterior Conditions:

- The front elevation/door faces west.
- The weather is partly cloudy
- An outside bioaerosol sample was collected to compare with the inside bioaerosol samples collected.

<u>Area</u>	<u>Temp *F</u>	<u>RH %</u>	<u>Dew Point *F</u>
Outside	81.0°F	70.0%	70.3°F



Front Elevation



Apartment 8

Moisture: There are observations of moisture stains or activity noted in this area.

- There are visible moisture stains and damage noted on all the exterior walls and ceilings of the apartment, the wall adjacent to the kitchen window, the north wall adjacent to the bathroom shower, and the bedroom south wall opposing the bathroom shower. Elevated moisture content was detected with a moisture meter in these areas.
- There is moisture intrusion from the exterior envelope entering the unit and affecting the adjacent building materials. Identify and repair roof/exterior envelope.
- There is a possible shower pan leak affecting the bathroom and bedroom base walls. Identify and repair shower pan. Seek professional plumbing contractor for an assessment.

Mold: Visual observations of mold growth are noted in this area.

- There is visible mold growth on the wall adjacent to the kitchen window, the wall adjacent to the shower, and the bedroom wall. There was MVOC (Microbial Volatile Organic Compound) odor present throughout the residence at the time of this assessment.

Samples: Bioaerosol - A bioaerosol sample was collected from this area to determine if fungal amplification is occurring.

Findings and Sample Results: The following is a summary of the findings and the sample results.

- The laboratory results for the bioaerosol sample/s collected in this area are elevated; mold remediation is recommended for this area. Please see the mold remediation recommendations section of this report for details.
- Elevated moisture content was detected with a moisture meter in the areas noted above. Based on the minimum standards of practice set forth by the IICRC S-500 and S-520, any materials that have been wet for more than 72 hours should be removed.
- Visible mold growth was noted in this area; please see the remediation recommendations section of this report.

<u>Area</u>	<u>Temp in *F</u>	<u>RH %</u>	<u>Dew Point *F</u>
	75°F	71%	71°F



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.


Miami, FL 33157

305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 4 of 16



Entry



Kitchen



Damage And Mold Growth



Base Wall Below Window



Elevated Moisture Content Detected with A Moisture Meter



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.


Miami, FL 33157

305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 5 of 16



**Elevated Moisture Content Detected with A
Moisture Meter**



Visible Moisture Stains



Bathroom



Visible Mold Growth



Visible Mold Growth



Damage And Mold Growth



Elevated Moisture Content Detected with A Moisture Meter




Shower



Bedroom



Base Wall



Elevated Moisture Content Detected with A Moisture Meter



Elevated Moisture Content Detected with A Moisture Meter



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.

Miami, FL 33157

305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 7 of 16



Moisture Stains Noted on Base Wall



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.

Miami, FL 33157

305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 8 of 16

General Notes

- Two (2) indoor bio-aerosol samples were collected and submitted for evaluation to Daane Labs of Naples, our independent accredited laboratory. The samples were collected from:
 1. LIVING ROOM
 2. BEDROOM
- An additional bio-aerosol control sample was also collected outside at the dwelling's front entrance to compare.
- The laboratory evaluation results are attached to this report and summarized below.
- This inspection is limited to visual observations of exposed surfaces only. No intrusive or destructive methods are used to observe hidden areas such as wall cavities, ceiling cavities, and certain components that are not accessible. Although thorough attempts are made to identify all potential problems that may contribute to mold growth, there is always a possibility that hidden mold growth may be present, including any non-viable mold that may be present from a prior moisture event that has dried out and is no longer detectable.



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.
Miami, FL 33157
305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 9 of 16

III. Discussion & Laboratory Evaluation Results

The laboratory evaluation results for the air samples collected are commensurate with the physical inspection findings, indicating evidence of elevated microbial growth or aerosolization occurring indoors.

The analysis of the sample results indicates that the elevated mold spore counts per cubic meter show an elevated statistical probability for indoor fungal amplification. Please see the following "Summary of Sample Analysis Results" as well as the attached complete laboratory report for details regarding these sample results.

A satisfactory mold clearance inspection consists of no visual observations of microbial growth inside the subject property, no active source of moisture is present, and air sample results are positively evaluated by comparing the total indoor counts with the exterior or reference counts and then comparing the types of microbial spores identified inside versus outside. Interior levels should be the same or lower than exterior levels, and the types of spores identified indoors should be similar in nature to the types of spores found outdoors.

We recommend reviewing the entire Daane Labs laboratory report (attached) in addition to this Limited Mold and Moisture Assessment.



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.
Miami, FL 33157
305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 10 of 16

The laboratory results for the bio-aerosol samples collected are shown to have a HIGHER amount of total count aggregated results than that of their outdoor counterpart, and the individual indoor reported “**Aspergillus/Penicillium-Like**” Genera are in amounts greater than that of their outdoor counterparts. These results indicate a high probability of elevated aerosolization (fungal amplification). The areas noted above are considered to be in a state of **ELEVATED** fungal ecology; professional remediation efforts are recommended to return the subject areas back to a state of normal fungal ecology.

Lab ID Number	237824-1			237824-2			237824-3		
Collection Date	2/11/25			2/11/25			2/11/25		
Volume	75			75			75		
Location	Outside			Living Room			Bedroom		
% Slide Analyzed	100			100			100		
Spore Identification	Raw Count	Spore/m ³	% of Total	Raw Count	Spore/m ³	% of Total	Raw Count	Spore/m ³	% of Total
Aspergillus/ Penicillium		0	0	37	493	88	126	1680	98
Chaetomium	0	0	0	0	0	0	0	0	0
Stachybotrys	0	0	0	0	0	0	0	0	0
Alternaria	0	0	0	0	0	0	0	0	0
Arthrinium	0	0	0	0	0	0	0	0	0
Ascospores	6	80	33	0	0	0	0	0	0
Basidiospores	0	0	0	0	0	0	0	0	0
Cladosporium	0	0	0	0	0	0	0	0	0
Cercospora	0	0	0	0	0	0	0	0	0
Curvularia	4	53	22	1	53	10	2	27	2
Dreschlera/ Bipolaris	0	0	0	0	0	0	0	0	0
Epicoecum	0	0	0	0	0	0	0	0	0
Fusarium	0	0	0	1	13	2	0	0	0
Ganoderma	0	0	0	0	0	0	0	0	0
Memnoniella	0	0	0	0	0	0	0	0	0
Myxomyces/ Smut	3	40	17	0	0	0	0	0	0
Nigrospora	3	40	17	0	0	0	0	0	0
Pithomyces	2	27	11	0	0	0	0	0	0
Rust	0	0	0	0	0	0	0	0	0
Spezzzia	0	0	0	0	0	0	0	0	0
Torula	0	0	0	0	0	0	0	0	0
Ulocladium	0	0	0	0	0	0	0	0	0
Other	0	0	0	0	0	0	0	0	0
Total Fungi	18	240	100	42	560	100	128	1787	100
Hyphal Fragment	2	27	N/A	1	13	N/A	0	0	N/A
Background Debris (1-5)*	3			4			4		



IV. Summary

Our visual observations together with the laboratory results for the air samples collected indicate evidence of the elevated microbial presence in the living areas.

- Elevated moisture content was detected with a moisture meter at the areas noted above. Based on the minimum standards of practice set forth by the IICRC S-500 and S-520 any materials that have been wet for more than 72 hours should be removed.
- Visible mold growth was noted in this area; please see the remediation recommendations section of this report.
- The laboratory sample results for the areas sampled are as follows:
 - The laboratory results for the bioaerosol sample/s collected in this area are elevated; mold remediation is recommended.

It appears that the above-noted issues are providing the conditions conducive for mold growth to occur.

This inspection is limited to visual observations of exposed surfaces only. There are no intrusive or destructive methods used to observe hidden areas such as wall cavities, ceiling cavities and certain components that are not accessible. Although thorough attempts are made to identify all potential problems that may contribute to mold growth, there is always a possibility that hidden mold growth may be present, including any non-viable mold that may be present from a prior moisture event that has dried out and is no longer detectable.

The following remedial recommendations are being made for the subject areas noted above:



V. Remediation Recommendations

THIS SECTION IS ALSO KNOWN AS “THE PROTOCOL” AND IS SPECIFICALLY WRITTEN AS A GUIDANCE FOR THE REMEDIATION CONTRACTOR

The following references are the basis for the remediation recommendations herein. The New York City Department of Health Guidelines on *Assessment and Remediation of Fungi in Indoor Environments*; The Institute of Inspection, Cleaning and Restoration Certificate (IICRC) S500 and S520; The E.P.A. Guidelines for Mold; The US Occupational Safety and Health Administration (OSHA); any other applicable state, or local regulations. Whenever there is a conflict or overlap among or between the above references, the most stringent provisions shall apply.

- Remedy apparent moisture source at the following areas:
- Isolate all HVAC components throughout the affected area prior to any repair or remediation activities. All HVAC equipment in or passing through any containment area shall be shut down, and preventative measures are taken to prevent accidental start-ups. All intake and exhaust openings shall be sealed with at least one (1) layer of 6-mil polyethylene sheeting. The seals shall be installed in such a manner as to guarantee that the seals shall remain in place for the duration of the project.
- Full **containment* with an airlock chamber**, of the areas surrounding the remediated area, including negative pressurization of the work area with HEPA-filtered air scrubbers is required for the following areas:

1. THE APARTMENT

- Movable Objects – All movable objects (furniture, pictures, accessories, and free-standing shelving) shall be cleaned and removed from the containment area(s) as specified in the scope of work.
- Upon adequate containment isolation, begin removal of the affected drywall/wallboard/plaster, wood framing, baseboards, etc. going two feet beyond any visible mold and/or moisture damage.
 - In the event additional areas of contamination are identified, contact the assessor immediately for re-assessment (Kimberly Cinaroglu-Dunn 786-587-5418).
 - Additionally, any exposed attic insulation and aluminum/wood studs that are affected should be removed.
 - Conduct a visual inspection of any wood framing materials present and if they are affected removal should occur.



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.
Miami, FL 33157
305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 13 of 16

Specific areas to be removed:

APARTMENT 8: The affected areas of the ceiling and walls, the bathroom shower and flooring, going out 2' beyond the edge of any visible mold including any affected adjacent/opposing walls of any adjacent/opposing rooms.

- **Any affected materials not removed**, due to structural concerns or materials adjacent to removed affected materials, shall be sanded, scrubbed, and micro-cleaned with a detergent solution. Any mold substances that cannot be removed shall be encapsulated.
- **Place ample dehumidification equipment** within the containment areas and clean storage areas to maintain relative humidity at 50% (+/-5%) during the remediation process. Dehumidification should allow for <14% moisture in all construction materials.
- **Air scrubbing** is required in the containment areas noted above, along with HEPA vacuum and damp wipe all the surfaces, furniture and contents and micro-cleaning with antimicrobial agents. Distribute and isolate all air filtration devices throughout the affected areas. Ensure during the project that no old, contaminated or incorrectly installed filters are used to minimize post remediation testing failures or potentially cross-contaminating other areas of the residence.
- **Cleaning of the HVAC system** AHU evaporator coils, blower compartment, fan, housing, supply plenum, ducting, and vents are recommended.
- Micro-cleaning of all areas where remediation occurs is recommended.
- All remediation should be performed by a Florida Licensed Mold Remediator.
- A licensed HVAC contractor should address the air handler unit, the A/C ducting, and the plenums. Following the guidelines of the *"National Air Duct Cleaners Association"* – ACR, 2006 addition "Assessment, Cleaning & Restoration of HVAC Systems" or the latest guidelines established by *"The American Society of Heating, Refrigeration, and Air-Conditioning Engineers."*
- Continued monitoring of areas for moisture issues is recommended.
- Prior to any restoration activities, the remediated sections of the residence should be sampled (**additional fees apply**) to assure post-remediation clearance criteria have been achieved. Clearance sampling should be undertaken prior to any application of sealants or encapsulating medium to the remediated surfaces.
- Post-remediation clearance criteria shall be successful at a level of less than 1,000 aggregate fungal spores/cm² for direct surface samples and at a level of less than 1,000 aggregate fungal spores per cubic meter of air collected in a 75-liter aerosol spore trap.



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.
Miami, FL 33157
305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 14 of 16

Containment Protocol:

- The containment must be built using polyethylene sheeting of 6-mil thickness that is clear or opaque and moisture resistant duct tape and spray on glue capable of continuously sealing polyethylene through project's remediation duration.
- The designated onsite clean storage area must be outside.
- PVC or wood supporting frames shall be utilized to ensure that the containments remain intact during the entire remediation and post-remediation procedures.
- Polyethylene bags of 6-mil thickness such as those used for asbestos-containing waste.
- A wet-vac vacuum cleaner and HEPA-filtered vacuum cleaner. All areas should be cleaned and sanitized and new filters installed prior to beginning the project. All filters shall be disposed of as contaminated waste material at the end of this project.
- Remove all contents from the affected areas that will be contained. All applicable contents must be HEPA vacuumed and damp wiped with a mild detergent solution prior to removal. In the event, some contents cannot be removed e.g. large furnishings ensure they have been cleaned properly and are sealed with polyethylene sheeting of 6-mil thickness. Electronic equipment should be HEPA vacuumed only.
- Ground Fault Circuit Interrupters (GFCI) are to be used on all electrical equipment within the containment.
- Air Filtration devices with HEPA filtration and in a sufficient number to provide a negative pressure between the containment and outside areas shall be operated continuously from the time containment is established through the time all demolition is completed.
- Once all the affected materials have been removed, HEPA vacuum to remove remaining dust and debris from the containment. Additionally, wipe down the interior of the containment to remove any particulate matter that may statically bind to the walls of the containment.



Coastal Indoor Environmental Consultants

18909 SW 80 Ct.
Miami, FL 33157
305-709-1177

kim@coastaliec.com

Ref – 935 Catalonia Ave, Coral Gables, FL 33134

Page 15 of 16

We hope this information assists you. Please do not hesitate to contact us if you have any further questions regarding this matter or if we may be of any further assistance. Thank you again for this opportunity to serve you.

The above report is a summary of project conditions based on visual site observations. Coastal Indoor Environmental Consultants and their representatives will not be held liable for any assumptions made based on these findings. As a routine matter, to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure. This inspection is not a complete inspection of all systems or components of the residence and issues no warranty or guarantees for any part of the subject structure or systems. Conditions inside wall cavities are not visible and unknown.

Sincerely,
Coastal Indoor Environmental Consultants

Kimberly Dunn

Kimberly Cinaroglu-Dunn, RN, MRSA
Florida Registered Nurse #9358838
Florida Licensed Mold Assessor MRSA2251

CERTIFICATE OF ANALYSIS

PREPARED FOR:

COASTAL IEC
18909 SW 80TH CT
MIAMI, FL, 33157

PROJECT ADDRESS:

935 CATALONIA AVE
CORAL GABLES, FL 33134

REPORT DATE:

FEBRUARY 14, 2025

REPORT CODE: M-DUNN-237824

Company		Coastal Environmental Consultants					Project Name			935 Catalonia Ave	
Address		18909 SW 80 Ct., Miami, FL 33157									
Contact		Terry & Kim Dunn					Project Address			935 Catalonia Ave, Coral Gables, FL 33134	
Phone		941-281-2958									
Email		terry@coastalec.com					Analyzed by/ Date			SR	2/14/2025
Lab ID Number		237824-1		237824-2			237824-3			Intentionally Left Blank	
Collection Date		2/11/25		2/11/25			2/11/25				
Volume		75		75			75				
Location		Outside		Living Room			Bedroom				
% Slide Analyzed		100		100			100				
Spore Identification		Raw Count	Spore/m ³	% of Total	Raw Count	Spore/m ³	% of Total	Raw Count	Spore/m ³	% of Total	
	Aspergillus/ Penicillium		0	0	37	493	88	126	1680	98	
	Chaetomium		0	0		0	0		0	0	
	Stachybotrys		0	0		0	0		0	0	
	Alternaria		0	0		0	0		0	0	
	Arthrinium		0	0		0	0		0	0	
	Ascospores	6	80	33		0	0		0	0	
	Basidiospores		0	0		0	0		0	0	
	Cladosporium		0	0		0	0		0	0	
	Cercospora		0	0		0	0		0	0	
	Curvularia	4	53	22	4	53	10	2	27	2	
	Dreschlera/ Bipolaris		0	0		0	0		0	0	
	Epicoccum		0	0		0	0		0	0	
	Fusarium		0	0	1	13	2		0	0	
	Ganoderma		0	0		0	0		0	0	
	Memnoniella		0	0		0	0		0	0	
	Myxomycetes/ Smut	3	40	17		0	0		0	0	
	Nigrospora	3	40	17		0	0		0	0	
	Pithomyces	2	27	11		0	0		0	0	
	Rust		0	0		0	0		0	0	
	Spegazzinia		0	0		0	0		0	0	
	Torula		0	0		0	0		0	0	
	Ulocladium		0	0		0	0		0	0	
	Other		0	0		0	0		0	0	
Total Fungi		18	240	100	42	560	100	128	1707	100	
Hyphal Fragment		2	27	N/A	1	13	N/A		0	N/A	
Background Debris (1-5)*		3			4			4			
Background Debris is a subjective assessment of the debris level (i.e., house dust) present in the sample, ranked from 1 to 5. A higher number corresponds to a higher level of debris.											
*Higher Background Debris may interfere with the analyst's ability to identify spores											
1 = 0-5% debris; 2 = 5-25% debris; 3 = 25-75% debris; 4 = 75-90% debris; 5 = 90-100% debris											
		The presence of these organisms indoors is typically an indicator of a water source and/or water damage. These organisms are known to flourish indoors and are an indicator of overall indoor air quality.									
		These organisms are commonly found outdoors and their presence indoors is likely due to passive air flow through an open window or door. These organisms are not typically known to flourish indoors.									
Surface Sample Enumeration Key											
Rare = 1-10 spores; Low = 11-100 spores; Medium = 101-1,000 spores; High = >1,000 spores											
The Laboratory is not responsible for project sampling. Customer provided information: Project Name, Project Number, Project ID, Project Address, Collection Date, Volume, and Location											

MOLD GLOSSARY

This portion of the report is intended to give a brief overview of the mold types identified in the reported samples. The information provided here is by no means fully inclusive. Many identifiable mold types represent a large, highly diverse group of fungi and it is difficult to fully capture the nature of these fungi in such a simplified description.

ASPERGILLUS/ PENICILLIUM

ALLERGIC POTENTIAL	Type I (hay fever, asthma), Type III (hypersensitivity)
MODE OF DISSEMINATION	Wind, insects
NATURAL HABITAT	Ubiquitous
INDOOR SUBSTRATES	Foods, dust, fabrics, wallpaper, wallpaper glue, leather. Prevalent in water-damaged buildings.

ALTERNARIA

ALLERGIC POTENTIAL	Type I (hay fever, asthma), Type III (hypersensitivity)
MODE OF DISSEMINATION	Airborne
NATURAL HABITAT	Ubiquitous
INDOOR SUBSTRATES	Various wetted substrates

ARTHRIUM

ALLERGIC POTENTIAL	Some species recognized as allergenic
MODE OF DISSEMINATION	Wind
NATURAL HABITAT	Decaying plant material, soil
INDOOR SUBSTRATES	Materials containing cellulose

ASCOSPORES

ALLERGIC POTENTIAL	Varies with genus and species
MODE OF DISSEMINATION	Forcible ejection or passive release, disseminated by wind or insects
NATURAL HABITAT	Ubiquitous
INDOOR SUBSTRATES	Depends on genus and species

BASIDIOSPORES

ALLERGIC POTENTIAL	Rarely Type I (hay fever, asthma)
MODE OF DISSEMINATION	Wind
NATURAL HABITAT	Forest floors, plants, lawns
INDOOR SUBSTRATES	Wood products, generally does not grow indoors

CERCOSPORA

ALLERGIC POTENTIAL	No allergic potential identified
MODE OF DISSEMINATION	Insects, wind, rain, irrigation water
NATURAL HABITAT	Plants
INDOOR SUBSTRATES	Not known to grow indoors

CHAETOMIUM

ALLERGIC POTENTIAL	Type I (hay fever, asthma)
MODE OF DISSEMINATION	Wind, insects, water droplets
NATURAL HABITAT	Soil, straw, seeds, animal waste
INDOOR SUBSTRATES	Paper, sheetrock, wall paper

CLADOSPORIUM

ALLERGIC POTENTIAL	Type I (hay fever, asthma)
MODE OF DISSEMINATION	Airborne
NATURAL HABITAT	Detritus, soil, woody plants
INDOOR SUBSTRATES	Paint, fabrics, textiles, fiberglass. Prevalent in water-damaged buildings

CURVULARIA

ALLERGIC POTENTIAL	Type I (hay fever, asthma)
MODE OF DISSEMINATION	Wind
NATURAL HABITAT	Soil, plant litter, decaying plants, detritus, leaves
INDOOR SUBSTRATES	Variety of building materials

EPICOCCUM

ALLERGIC POTENTIAL	Rarely Type I (hay fever, asthma)
MODE OF DISSEMINATION	Wind
NATURAL HABITAT	Soil, plant debris
INDOOR SUBSTRATES	Textiles, paper

FUSARIUM

ALLERGIC POTENTIAL	Type I (asthma, hay fever)
MODE OF DISSEMINATION	Insects, wind, water droplets
NATURAL HABITAT	Soil, plants
INDOOR SUBSTRATES	Humidifiers, wet cellulose building materials

GANODERMA

ALLERGIC POTENTIAL	Rarely Type I (hay fever, asthma)
MODE OF DISSEMINATION	Wind, insects
NATURAL HABITAT	Parasitic on plants, notably hardwood trees
INDOOR SUBSTRATES	Not typically found indoors

MEMNONIELLA

ALLERGIC POTENTIAL	Unknown
MODE OF DISSEMINATION	Wind
NATURAL HABITAT	Plant materials, soils
INDOOR SUBSTRATES	Wet building materials

MYXOMYCETES, PERICONIA, SMUT

ALLERGIC POTENTIAL	Type I (hay fever, asthma)
MODE OF DISSEMINATION	Wind, insects, water
NATURAL HABITAT	Detritus, dung, mulch, lawns
INDOOR SUBSTRATES	Rotting wood, not typically found indoors

NIGROSPORA

ALLERGIC POTENTIAL	Type I allergies (hay fever, asthma)
MODE OF DISSEMINATION	Forcibly ejected, wind
NATURAL HABITAT	Grass, soil, seeds
INDOOR SUBSTRATES	Not known to grow indoors

PITHOMYCES

ALLERGIC POTENTIAL	No allergic potential identified
MODE OF DISSEMINATION	Wind
NATURAL HABITAT	Tree bark, soil, leaf litter, detritus
INDOOR SUBSTRATES	Paper

SPEGAZZINIA

ALLERGIC POTENTIAL	Rarely Type I (hay fever, asthma)
MODE OF DISSEMINATION	Wind
NATURAL HABITAT	Dead leaves, herbaceous dead stems, soil, occasionally estuarine sediments
INDOOR SUBSTRATES	Not known to grow indoors

STACHYBOTRYS

ALLERGIC POTENTIAL	Type I (asthma, hay fever)
MODE OF DISSEMINATION	Insects, water, wind
NATURAL HABITAT	Detritus, soil
INDOOR SUBSTRATES	Wet building materials

TORULA

ALLERGIC POTENTIAL	Type I(hay fever, asthma)
MODE OF DISSEMINATION	Wind
NATURAL HABITAT	Leaves, plant roots, detritus, soil, wood
INDOOR SUBSTRATES	Wicker furniture, wood, baskets, paper

ULOCADIUM

ALLERGIC POTENTIAL	Type I (hay fever, asthma), Type III (hypersensitivity)
MODE OF DISSEMINATION	Wind, insects
NATURAL HABITAT	Soil, dung, grass, fibers, wood, detritus
INDOOR SUBSTRATES	Gypsum, wallpaper, and various wetted substrates



4795 Enterprise Ave
Naples, Florida 34104
login@daanelabs.com
www.daanelabs.com

daaneLABS		CHAIN OF CUSTODY - ELECTRONIC SUBMISSION		1.078 REV 08		
Customer Information		Project Information				
Company:	Coastal Indoor Environmental Consultants	Project/ Client Name:	935 Catalonia Ave	Date Sampled:	2/11/2025	
Contact:						
Contact Phone:		Project Address:	935 Catalonia Ave, Coral Gables, FL 33134	Turn-Around Time	Standard (Same Day)	
Contact Email:	info@coastalenv.com					
Address:		Project Number:		Attach COC to Report?	Yes	
Sample Information						
Lab ID	Sample Location	Sample ID	Sample Type	Volume	Analysis	Comments
2028041	OUTSIDE	4638	Air Cassette	75 Liters	Mold Microscopy	
	LIVING ROOM	4654	Air Cassette	75 Liters	Mold Microscopy	
	BEDROOM	2180	Air Cassette	75 Liters	Mold Microscopy	
Submitted By: Date/Time: 2/14/2025 12:35:36						
Received By: Date/Time: [Signature] 2/14/2025						
Analyzed By: Date: [Signature]						
* - Turnaround Times are relative to when samples are received by the lab, not when samples are dropped off. Daane Labs cuts off sample receipt at 2:00 pm for analytical and reporting purposes.						
Comments:						
Report Style: Data Only						