City of Coral Gables

Gondola Building Reconstruction

1200 ANASTASIA AVE. CORAL GABLES, FL 33134

Project Number:


22119

Date:

November 20, 2924

Historic Preservation Division Presentation

GURRIMATUTE



PROJECT LOCATION

1200 ANASTASIA AVE. CORAL GABLES, FL 33134

ANASTASIA AVE.

S.W. 57th AVE.

SITE

S.W. 40TH ST.

G



HISTORICAL PHOTOS

Ca.1930s









CURRENT CONDITIONS

In 2021, the building collapsed almost entirely and needs a full reconstruction. Therefore, this project seeks to rebuild a replica of the Gondola Building in the same location and with the same design and materials as closely as possible while still meeting the Florida Building Code.



GONDOLA BUILDING RECONSTRUCTION

SCOPE OF WORK


The scope of the work is to reconstruct the historic building as a replica of the original structure which has partially collapsed. The building will follow the Secretary of the Interior's Standards for Rehabilitation of Historic Buildings. Portions of the original building that were salvaged will be reconstructed or reinstalled if possible. The building will be used as a rain shelter and is intended to remain open.

SITE PLAN KEY

- 1. RE-PAVED ASPHALT PATH
- 2. EXISTING POWER POLE TO REMAIN
- EXISTING CONCRETE PAD TO REMAIN
- 4. EXISTING TREES TO REMAIN
- 5. NEW CONCRETE PAD
- 6. EXISTING WALL TO BE REPAIRED
- 7. APPROXIMATE EDGE OF WATER



PROPOSED FLOOR PLAN




FLOOR PLAN KEY

- 1. NEW CONCRETE PAD
- 2. RE-PAVED ASPHALT PATH
- 3. DECORATIVE BARN DOOR STYLE SHUTTERS (TYP.)
- 4. SHUTTER TRACK ABOVE (TYP.)
- 5. INSWING WOOD SHUTTER



T


PROPOSED REFLECTED CEILING PLAN



REFLECTED CEILING PLAN KEY

- RAIN LEADER
- 2. EXPOSED 2X14 WOOD JOISTS
- STRIP LIGHTS
- 4. OVERFLOW PIPE
- BARN DOOR SLIDING DOOR RAIL TRACK SYSTEM

PROPOSED ROOF PLAN



ROOF PLAN KEY

- 1. ROOF DRAIN
- 2. 2-PLY SBS MEMBRANE ROOFING
- 3. OVERFLOW ROOF DRAIN



FAÇADE COMPONENTS (SALVAGE & MOLDING)

On the exterior facade of the Gondola building, the character defining masonry features of the original facades (i.e. decorative parapet, urns, engaged columns, etc.), will be replicated to match the original structure as closely as possible.



- 1. CAST STONE URN
- CEMENT PLASTER ORNAMENTAL RELIEFS
- **CAST STONE WINDOWSILL & CORBELS**
- CAST STONE CROWN ORNAMENT
- **CROWN MOLDING**
- WOOD SHUTTER
- DECORATIVE BARN DOOR SHUTTER
- CAST STONE WINDOW HEAD
- 9. STUCCO SKIP-HAND TROWEL TEXTURED FINISH





















3. EAST ELEVATION

FAÇADE COMPONENTS (SALVAGE & MOLDING)
















- 1. CAST STONE URN
- 2. CEMENT PLASTER ORNAMENTAL RELIEFS
- 3. CAST STONE WINDOWSILL & CORBELS
- 4. CAST STONE CROWN ORNAMENT
- 5. CROWN MOLDING
- 6. WOOD SHUTTER
- 7. DECORATIVE BARN DOOR SHUTTER
- 8. CAST STONE WINDOW HEAD
- 9. STUCCO SKIP-HAND TROWEL TEXTURED FINISH








4. WEST ELEVATION

INTERIOR ELEVATIONS









4

3

INTERIOR ELEVATION KEY

- 1. PAINTED EXPOSED CMU BLOCK
- 2. SEALED CONCRETE FLOOR
- 3. DECORATIVE BARN SHUTTERS
- 4. BARN DOOR SLIDING DOOR RAIL TRACK SYSTEM
- 5. WOOD SHUTTERS
- 6. INSWING WOOD SHUTTER



FINISHES

On the exterior of the Gondola building, the wall finish and color will be replicated to match the original structure as closely as possible. The interior of the Gondola building will also replicate its original interior finish with painted exposed CMU block structure, exterior-graded wood beams, and sealed concrete flooring. All exterior and interior paint colors will be matched to the existing colors after the paint analysis has been completed by the retained conservator.











PROPOSED

EXISTING



EXTERIOR GRADE LVL BEAM



PAINTED EXPOSED CMU



PLANK T & G V GROOVE BOTH SIDES



STUCCO SKIP-HAND TROWEL TEXTURED FINISH



PAINTED WOOD PLANK



STEEL TROWEL CONCRETE FLOOR FINISH

City of Coral Gables

Gondola Building Reconstruction

Historic Preservation Presentation

THANK YOU.

GURRIMATUTE

