MIAMI-DADE COUNTY HISTORIC PRESERVATION AD-VALOREM TAX EXEMPTION

PART 1 – PRECONSTRUCTION APPLICATION

I	US 1	ΓR	Ū	CT	10	NS:

Type or print clearly in black ink. You may attach additional sheets if more space is needed.

l.	PROPERTY IDENTIFICATION AND LOCATION							
	Historic/Site Name:							
	Property Address: 717 N. GREENWAY DRIVE, WRAL GABVES 33134							
	Folio Number: 03-4108-001-4040							
	Legal Description: LORAL GABLES SEC B PB 5-111							
	Please check all that apply:							
	Designated as a local historic landmark or site Designated as a contributing structure within a local historic district Individually listed in the National Register of Historic Places Is a contributing structure in a National Register District Name of District DUNNEY CLUB OF LOLAR GABLES HISTORIC DISTRICT							
	Please attach the designation report and resolution as proof the property is designated.							
II.	OWNER INFORMATION:							
	Name(s) of Owner(s): LAIRENCE + KATHY - ANN MARLIN							
	Mailing Address: 717 N. GREENWAY DRIVE, LORAL BABVES,							
	ROUDA 33134							
	Phone: 305-799-1035 2 nd Phone:							
	Email: Kwmarin 1 agmail. com							
	If the property has multiple owners, please attach a list of all owners and their mailing addresses.							

III. CURRENT PHYSICAL DESCRIPTION OF PROPERTY:

A. General Information

Date of Construction: 1927 Architect (if known): H.B. TAYLOR

Alterations: Please provide the date and description of any physical alterations to the property. [Example: Original casement windows were replaced with jalousie windows around 1974.] OP-161NAL WOOD WINDOWS IN SOME PEPUATED WITH AWMINIM WINDOWS IN 1957. OUGNAL GALAGE WINDERTED INTO PLAYEROM IN 1963. TWO WINDOWS ON EAST SIDE OF HOME REMOVED IN 1981.

Additions: Please provide date and description of any additions which may have been made. [Example: A rear bedroom and bath were added to the house in 1981.]

A POOL AND WIERED PORCH ALEA ADDED TO NORTH SIDE IN 1963. WEONGER IN 1993.

B. Exterior Description

Roof Type: HIP	_ Roof Material:	BARRELTILE			
Example: hip, gable, flat, etc	Example: barrel tile, asphalt shingle, etc				
Number of Stories: 2	Detached Garage? (Y/N)				
Basic Floor Plan: REUTANGULAN					
Example: square, "L" shaped, "U" sh	aped, rectangular,	irregular, etc			
Main Window Type(s):	NT, MALE H.	ING+ JANNE			
Example: casement, fixed, single hui	ng sash, jalousie, a	wning, etc			
Siding Material(s): SNCCO					
Example: stucco wood frame brick					

Briefly describe any distinguishing Exterior Architectural Features:

[Example: the placement of the windows, chimneys, porches, columns, etc]

STAINED BUX NEARYOM WINDOWS ABOVE DELLINAL WOOD

CATEMENT WINDOWS; OLIGINAL EXPERIOR LIBHT FIXNESS; OLIGINAL WRONGHT IRON AT BAWDNIES AND PORCHES; PORCH WITH MARBUE FLOOPING; DELORATIVE COLUMNS AT FRONT OF PROPERTIES OF 16

DELORATIVE TRIM; ORIGINAL DELORATIVE WOOFER GUTTERS.

EXTERIOR ARCHITECTURAL FEATURES

The following represents an itemization of work to be accomplished. List each principal architectural feature affected and describe the impact that restoration/rehabilitation will have on it. Label which elevation(s) contains that feature, and include a corresponding photograph for each. Please attach additional sheets if necessary.

FEATURE 1: UNIGINAL CATEMENT WINDOWS WITH STAINED GLASS

Elevation: JOUTH, NORTH FAST AND WEST

Photo Number: #1, #2

Plan Number: A-401, A-402, A-403, A-404

Describe Work and Impact on Existing Feature: THE DAY INTO WINDOW ARE A UNIQUE FEARINE ON THIS HOME. THEY ARE TOPPED WITH STAINED GLASS transoms. THE WINDOWS ARE OFFERING FROM WOOD ROT AND SOME OF ME GLATS IS DAMAGED. WINDOWS WILL BE DESTRATED TO DEIGINGE CONDITION.

FEATURE 2: OPIGINAL WENDERT 120 NWEEK

Elevation: SOUTH, EAST Photo Number: 许3, 年4

Plan Number: A MOI,

Describe Work and Impact on Existing Feature: THE ENTRY TO THE HOME FEATURES A WROUGHT IRAN ARCH WITH DRIGINAL MEHT FIXMRE. THE WHOUGHT IRON I RUSTED AND CRUMBUNG, THE WROUGHT I RON WILL BE REMOVED, RESTORED AND REINLEAUED

FEATURE 3: RE-ESTABLISHING DEIGINAL GARAGE

Elevation: NORTH Photo Number: # 5 Plan Number: A 1405

Describe Work and Impact on Existing Feature: THE OFIBINAL GARAGE WAT CONVENTED to A PUTYROOM IN 1963. WE PHN TO RE-ENTABUSH A TWO CAR GARATOF.

FEATURE 4: PE-ESTAGUHING REMOVED WINDOWS

Elevation: EAST Photo Number: # 6 Plan Number: A MOY

Describe Work and Impact on Existing Feature: WIND AN WELE REMOTED FROM THE SELOND FLOOR KINDOOM IN 1981. WE PLANTO RE-ESTABLIM THE REMOVED WNDOWS.

A. EXTERIOR ARCHITECTURAL FEATURES (CONTINUED)

FEATURE 5: EXTERIOR (PEAR OF HOME)

Elevation: NORTH AND GOVITH

Photo Number: #19, #20, #21, #22, #23, #24, #25, #26, #27
Plan Number: A 101 And A 403
Describe Work and Impact on Existing Feature: FEMOVAL OF NON-HUTORIC ADDITIONS AT HOUSE INCLUDING BEFAKFAST FOOM, WOODEN STRUCKRES, LANDRY ROOM ADDITION, POOLEN WORRE MADE OF UNIVERSE AND ALUMINUM, ALUMINUM PENLE, OUDDOR VHOWER AND LONGETE WALL

FEATURE 6: ACCESSORY BUILDING

Elevation: NOCTH

Photo Number: #28, #29, #30,#31, #32

Plan Number: A - 405

Describe Work and Impact on Existing Feature: REMINAL OF NON-HISTORIC ADDITIONS P OPIGINAL ACCESSORY BUILDING. INCLUDES REMOVAL OF WOODEN ADDITION, AWMINNA AND PLATTIC WALKWAY ADJACENT TO ACCENTORY BUILDING.

FEATURE 7:

Elevation:

Photo Number:

Plan Number:

Describe Work and Impact on Existing Feature:

FEATURE 8:

Elevation:

Photo Number:

Plan Number:

Describe Work and Impact on Existing Feature:

B. INTERIOR ARCHITECTURAL FEATURES

FEATURE 1: OCIDINAL MARBIE FLOORS

Room: UVING POOM Photo Number: 片7, 片8 Plan Number: A・201

Describe Work and Impact on Existing Feature: WE PLAN TO RESPOSE THE ONIGHT MADBLE

FLOORS TO THEIR ONUINA CONDITION.

FEATURE 2: ONI SINA TERAMO FRORS

Room: WNFO DM
Photo Number: # 9
Plan Number: A 702

Describe Work and Impact on Existing Feature: WE PURN TO RESTORE THE OCUINAL

TERATED FLOORS TO THEIR OCHUINGS CONDITION.

FEATURE 3: DEIBINAL WOOD FLOOPS

Room: BED ROOMS

Photo Number: \$\psi_0, \pi_11

Plan Number: A \cdot \cd

Describe Work and Impact on Existing Feature: THE OPIGINAL WOOD FLOORS ARE DAMAGED.

WE PLAN TO RESTORE THE WOOD FROOK TO THEIR ORIGINAL UNDITION

FEATURE 4: OPIGINAL STAIRCATE

Room: FOYER
Photo Number: # 12
Plan Number: A-202

Describe Work and Impact on Existing Feature: THE ORIGINAL STAIRCATE IS IN BAD WADINON.
THE BUSS RAILING NEEDS REPAIRING AND THE ORIGINAL WOOD FLUOR
ONTHE STAIRCATE WILLBE RESTORED TO THEIR ORIGINAL WINDITION.

B. INTERIOR ARCHITECTURAL FEATURES (CONTINUED)

FEATURE 5: RE-ESTABULATING DAGINAL TOYER HEIGHT

ROOM: FOYER

Photo Number: #13, #14, #15

Plan Number: A - 202

Describe Work and Impact on Existing Feature: OCIGINAL TRIPLE HEIGHT FOYER WAS
CLOSED JP AND A MATTER SATUROOM ON JEWND FROUL WAS ADDED DIRING
A PREVIOUS RENDVATION. WE PLAN TO REMOVE THE BATHROOM AND EXPOSE
THE OPIGINAL FOYER HEIGHT TO HIGHLIGHT THE TOWER FRANCE ATTHE
ENTRANCE TO THE HOME.

FEATURE 6: RE-ESTABUSTING ORIGINAL SUNFOOM ONSECOND FROOR

ROOM: SINRIAM

Photo Number: #16, #17, #18

Plan Number: A -202

DISTRIBUTED AND PARTITIONED INTO TWO BEDROOMS DIVING A PREVIOUS RENOVATION. WE PLAN TO REMOVE THE PARTITION AND RE-ESTABLISH THE LARGE UPSTAIRS SNROOM THAT WAT ORIGINAL TO THE HOUSE.

FEATURE 7:

Room:

Photo Number:

Plan Number:

Describe Work and Impact on Existing Feature:

FEATURE 8:

Room:

Photo Number:

Plan Number:

Describe Work and Impact on Existing Feature:

C. LANDSCAPE FEATURES

Please	list	any	restorative	work	to be	done	to	original	landscape	features,	including
pathwa	ys,	walls	, fountains,	etc. Ind	clude	a site p	lan	or sketch	n if necessai	γ.	

FEATURE 1:

Photo Number:

Describe Work and Impact on Existing Feature:

FEATURE 2:

Photo Number:

Describe Work and Impact on Existing Feature:

FEATURE 3:

Photo Number:

Describe Work and Impact on Existing Feature:

OWNER ATTESTATION: I hereby attest that the information provided in this application is, to the best of my knowledge, correct, and that I own the property described above or that I am legally the authority in charge of the property. Further, by submission of this Application, I agree to allow access to the property by representatives of the appropriate official in which the property is located, for the purpose of verification of information provided in this Application. I also understand that, if the requested exemption is granted, I will be required to enter into a Covenant with the municipality and Miami-Dade County in which I must agree to maintain the character of the property and the qualifying improvements for the term of the exemption.

Print Name

| Control | Co

[Please attach the photographic documentation on subsequent pages. Submit a copy of all photographs on a CD as well, if possible.]

PRE-CONSTRUCTION APPLICATION REVIEW TO BE FILLED OUT BY THE LOCAL HISTORIC PRESERVATION OFFICER

Street Address of property 117 N. Green Way Drive
Folio number 03 - 4108 - 00 - 4040
The local Historic Preservation Officer has reviewed Part 1 (Preconstruction Application) of the Historic Preservation Property Tax Exemption Application for the above named property and hereby:
Certifies that the above referenced property qualifies as a historic property consistent with the provisions of s. 196.1997 (11), F.S.
[] Certifies that the above referenced property <u>does not qualify</u> as a historic property consistent with the provisions of s. 196.1997 (11), F.S.
Determines that improvements to the above referenced property <u>are consistent</u> with the Secretary of Interior Standard's for Rehabilitation and Guidelines for Rehabilitating Historic Buildings and the criteria set forth in Chapter 1A-38, F.A.C.
[] Determines that improvements to the above referenced property <u>are not consistent</u> with the Secretary of Interior Standard's for Rehabilitation and Guidelines for Rehabilitating Historic Buildings and the criteria set forth in Chapter 1A-38, F.A.C.
Please list any Review Comments here:
Additional Review Comments attached? Yes No
Signature: Kaya Kautz Typed or printed name: Kaya Kautz
Title: <u>Interim Hstoric Preservation office</u>
Date of Review: 31 - 07- 2021