

AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 1: ORIGINAL WINDOWS WITH STAINED GLASS -
REPAIRED & RESTORED



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 1: ORIGINAL WINDOWS WITH STAINED GLASS - REPAIRED & RESTORED (CONTINUED)



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 2: ORIGINAL WROUGHT IRONWORK -

REPAIRED & RESTORED



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 2: ORIGINAL WROUGHT IRONWORK -

REPAIRED & RESTORED (CONTINUED)



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 3: RE-ESTABLISHING ORIGINAL GARAGE



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 6: ACCESSORY BUILDING (CONTINUED)



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 3: RE-ESTABLISHING ORIGINAL GARAGE -

(CONTINUED)



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 4: RE-ESTABLISHING REMOVED WINDOWS



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 4: RE-ESTABLISHING REMOVED WINDOWS

(CONTINUED)



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 5: EXTERIOR - REAR OF HOME



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 5: EXTERIOR - REAR OF HOME

(CONTINUED)



AFTER PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE # 6: ACCESSORY BUILDING

