

## City of Coral Gables Development Services Department

## CONSTRUCTION REGULATION BOARD CASE RESUME

**HEARING DATE:** November 18, 2024

BUILDING ADDRESS: 20 Santillane Ave CASE NO.: 24-8221 RECT-24-09-0403

**FOLIO NUMBER:** 03-4108-009-1290

**OWNER:** ALBERT F MUZAURIETA and ANNA B MUZAURIETA

**USE:** multifamily # **OF LIVING UNITS:** 4

PENDING RECERTIFICATION: 2024 LAST RECERTIFICATION: 2014

**YEAR BUILT:** 1944

**DESCRIPTION AND DEFECTS OF BUILDING:** The Building Official has inspected the records relating to the Structure in accordance with Article III, Chapter 105 of the City Code, pertaining to unsafe structures, and Section 8-11 of the Miami-Dade County Code, as applicable in the City, pertaining to existing buildings. **The Structure is hereby declared unsafe** by the Building Official and is presumed unsafe pursuant to Section 105-89 (10)(m) of the City Code for failure to timely comply with the maintenance and recertification requirements of the Florida Building Code or Section 8-11 of the Miami-Dade County Code; as follows: To date, the Owner has not submitted an inspection report conforming to the minimum inspection procedural guidelines as issued by the Miami-Dade County Board of Rules and Appeals, pursuant to Section 8-11(f) of the Miami-Dade County Code ("Report").

## **DATES AND ACTIVITIES:**

01/31/24	First Notice from the City advising Recertification is required mailed, delivered.
05/10/24	Second Notice from the City advising Recertification is pending mailed, status not available.
06/17/24	Final Notice from the City advising Recertification is pending mailed, status not available.
11/04/24	Notice of Hearing posted on Structure and at City Hall.
11/05/24	Notice of Unsafe Structure Violation for Failure to Recertify and Notice of Hearing mailed with
	return receipt
11/18/24	Board Hearing

**TO DATE THE OWNER HAS:** NOT submitted a Recertification Report for the City's review.

**BUILDING OFFICIAL'S RECOMMENDATION:** A. Submit a letter from a structural Engineer within seven (7) days of the Board's meeting attesting the structure is safe for occupancy B. Submit a revised Recertification Report prepared by a licensed Architect or Engineer within sixty (60) days of the Board's Order Recertifying the property. C. A \$250 daily fine be imposed, if any of these deadlines are not met.

**PERMIT ACTIVITY:** No current permits associated with the Building Recertification