ML

Building • Manuel Lopez - Building • Approved
Assigned

10/11/2021
Due

10/11/2021
Complete

10/14/2021
Priority

10
Required

EM

Public Works • Emily Muñoz - Public Works • Approved

Assigned

10/28/2021

Due

Yes

10/28/2021

Complete

10/28/2021

Priority

10

Required

Yes

WA

Historic • Warren Adams - Historic • Not Required

Assigned

10/11/2021

Due

10/11/2021

Complete

12/03/2021

Priority

10

Required

Yes

PG

Structural • Paul Guth - Structural • Disapproved

1) Please indicate which wood members are to be replaced – decking, joists, or stringers. Is this a replacement of all dock framing members or just a partial replacement? 2) Please include existing drawing D-2 as part of the permit documents, as this sheet shows member connection requirements and material specifications. 3) The dock member sizes shown on sheet D-1 (2x8 joists, 2x12 stringers) do not appear to match the permitted drawings (3x8 joists, 3x12 stringers). If the proposed repair member sizes are to be different than what is shown on the permitted plans, then signed-and-sealed structural calculations are required to show that the proposed member sizes can adequately resist the required design loads.

Assigned

10/11/2021

Due

10/18/2021

Complete

11/23/2021

Priority

10

Required

Yes

AR

City Architect • Ana Restrepo - Board of Architects • Approved

Assigned

10/11/2021

Due

10/20/2021

Complete

12/02/2021

Priority

10

Required

Yes

ED

Zoning • Elisa Darna - Zoning • Approved

Assigned

10/11/2021

Due

10/11/2021

Complete

10/11/2021

Priority

10

Required

Yes