

City of Coral Gables Development Services Department

CONSTRUCTION REGULATION BOARD CASE RESUME

HEARING DATE: January 9, 2023

CASE NO.: 22-5119

BUILDING ADDRESS: 81 Edgewater Dr.,

FOLIO NUMBER: 03-4129-070-0001

OWNER: Edgewater of Coral Gables Condominium Association, Inc.

USE: Multifamily

OF LIVING UNITS: 8

PENDING RECERTIFICATION: 2022 LAST RECERTIFICATION DATE: 2012

(not found in our records)

YEAR BUILT: 1962

DESCRIPTION AND DEFECTS OF BUILDING: The Building Official has inspected the records relating to the Structure in accordance with Article III, Chapter 105 of the City Code, pertaining to unsafe structures, and Section 8-11 of the Miami-Dade County Code, as applicable in the City, pertaining to existing buildings. The Structure is hereby declared unsafe by the Building Official for failure to timely comply with the maintenance and recertification requirements of the Florida Building Code.

DATES AND ACTIVITIES:

01/03/22	First Notice from the City advising Recertification is required mailed with return receipt, delivered
04/04/22	Second Notice from the City advising Recertification is required mailed with return receipt, delivered
06/09/22	Final Notice from the City advising Recertification is required mailed with return receipt, delivered
06/29/22	Notice of Unsafe Structure Violation for Failure to recertify and Notice of Hearing mailed
	with return receipt.
06/29/22	Notice of Hearing posted on Structure and at City Hall.
07/11/22	Board Hearing: case withdrawn due to report submittal
08/23/22	Recertification Report rejected; repairs required (Building & Electrical)
08/23/22	60 days extension granted to do repairs.
10/22/22	EXTENSION EXPIRED
12/22/22	Notice of Unsafe Structure Violation for Failure to recertify and Notice of Hearing mailed
	with return receipt.
12/22/22	Notice of Hearing posted on Structure and at City Hall.

01/09/23 Board Hearing

TO DATE THE OWNER HAS: NOT submitted a revised Recertification Report for the City's review.

BUILDING OFFICIAL'S RECOMMENDATION: A. Submit an updated letter from a structural Engineer within seven (7) days of the Board's meeting attesting the structure is safe for occupancy **B**. Submit a Recertification Report prepared by a licensed Architect or Engineer within sixty (60) days of the Board's Order Recertifying the property. C. A \$250 daily fine be imposed, if any of these deadlines are not met.

PERMIT ACTIVITY: No current permits associated with the Building Recertification