Actions Page 1 of 4



Actions Page 2 of 4

responsible for the original review and approval of this Project. Submit the sets to the Building Department together with 2 signed and sealed copies of a Certification Letter from the Peer Review Engineer.

PLAN REVIEW prstr - STRUCTURAL PLAN REVIEW dreczek

10/02/2018 REJECTED

Comments by consulting reviewer responsible for review of the original Permit: 1. All changes must be clouded - there are many changes that are not clouded. 2. Submit all sheets and update all necessary details for new condition. 3. Provide copy of original set of calculations and calculations for any new items. 4. Remove all references to existing structure applies to all sheets. CLOUD all changes 5. Modify details on S-11 as needed for new structure 6. Provide detail for MP-2 how are they capped and braced 7. S2-A - Appears there are section cuts missing (For example RTB-4 and RB-19) 8. 4/S-7 consider revising for new condition. Also, as detailed the beam is not the depth designed please review beam depths and fix details accordingly. 9. Add F-6.5 to schedule. 10. Review terminated - additional comments may arise after additional information and all clouds properly provided.

PLAN REVIEW prstr - STRUCTURAL PLAN REVIEW carguinzon 10/15/2018 10/15/2018 REJECTED

CONSULTANT JEM (DESIREE PERAZZO P.E.) Comments from my review of the resubmission: 10-15-18 1. All changes must be clouded - there are many changes that are not clouded.

Actions Page 3 of 4

REMAINS - STILL AREAS THAT **CHANGED THAT** ARE NOT CLOUDED. PLEASE **REVIEW ALL** DRAWINGS, **COMPARE TO** ORIGINAL PERMIT SET AND CLOUD ALL CHANGES. 2. SATISFIED 3. Provide copy of original set of calculations and calculations for any new items. - A. PLEASE PROVIDE **CALCULATIONS** FOR THE **NORTHWEST** "TOWER" AND THE COMPLETE LOAD PATH. PROVIDE **SUPPORT** CLARIFICATION FOR THE PLYWOOD SOFFIT (EXTERIOR) SHOWN IN 1/S-10 - WHAT IS IT SUPPORTED BY? IF **NEW MEMBERS ARE** PROVIDED ALSO **PROVIDE** CALCULATIONS. PROVIDE CHECK OF NEW BEAMS, **COLUMNS AND** FOUNDATIONS. 4. SATISFIED 5. SATISFIED 6. SATISFIED 7. S2-A - Appears there are section cuts missing (For example RTB-4 and RB-19) - NEW SECTION MARKS ARE NOT CLOUDED 8. SATISFIED. 9. Add F-6.5 to schedule. PROVIDE CALCULATIONS AND LOAD TAKEDOWN FOR **NEW FOOTING F6.5** 10. Review terminated additional comments may arise after additional information and all clouds properly provided *COMMENT REMAINS* **NEW COMMENTS 10-15-18** 11. CLARIFY **ELEVATION** CHANGES ON UPPER ROOF SLAB AND EAST EYEBROW SLAB-NO **ARCHITECTURAL** CHANGES WILL BE

COMMENT

Page 4 of 4 Actions

> ACCEPTED 12. **PROVIDE** CALCULATIONS FOR RB-25 & RB-26 13. ADD POINT LOAD OF RB-25 TO THE RB-22 **CALCULATIONS** AND CONFIRM DESIGN 13. **ELEVATION OF** RB-7 AND RB-8 IN SCHEDULE DOES NOT MATCH SECTION 2/S-7 -PLEASE REVIEW AND CORRECT AS NEEDED

PLAN prstr - STRUCTURAL PLAN REVIEW 11/06/2018 APPROVED

CONSULTANT JEM **REVIEW** (DESIREE PERAZZO P.E. -REVISION CLOUD #7 ONLY

(STRUCTURAL) PLAN prstr - STRUCTURAL PLAN REVIEW 11/06/2018 RE REVIEW carguinzon

REVIEW FEE

PLAN ppappl -

PROCESSING APPLICATION/LICENSE/OWNERSHIP **VERIFICATION**

carguinzon PLAN ppappl -11/06/2018 INCOMPLETE MISSING THE

PROCESSING APPLICATION/LICENSE/OWNERSHIP PERMIT VERIFICATION APPLICATION

PI AN calc fees - CALCULATE FEES 11/06/2018 COMPLETED carguinzon

PROCESSING

CASHIER collect - COLLECT FEES

The City's online services are protected with an **SSL encryption certificate**. For technical assistance, please call 305-569-2448 (8am-5pm, M-F).