

City of Coral Gables Development Services Department

CONSTRUCTION REGULATION BOARD CASE RESUME

CASE NO.: 21-2945 **HEARING DATE:** October 18, 2021

BUILDING ADDRESS: 266 PALERMO AVE

FOLIO NUMBER: 03-4117-005-6360

OWNER:. 266 PALERMO PROFESSIONAL

BUILDING INC

USE: COMMERCIAL BUILDING # OF LIVING UNITS: 0

PENDING RECERTIFICATION: 2021 LAST RECERTIFICATION DATE: 2001

YEAR BUILT: 1951

DESCRIPTION AND DEFECTS OF BUILDING: The Building Official has inspected the records relating to the Structure in accordance with Article III, Chapter 105 of the City Code, pertaining to unsafe structures, and Section 8-11 of the Miami-Dade County Code, as applicable in the City, pertaining to existing buildings. The Structure is hereby declared unsafe by the Building Official for failure to timely comply with the maintenance and recertification requirements of the Florida Building Code.

DATES AND ACTIVITIES:

02/08/21	First Notice from the City advising Recertification is pending mailed with return receipt, delivered.
05/10/21	Second Notice from the City advising Recertification is pending mailed with return receipt and return receipt, delivered.
06/09/21	Final Notice from the City advising Recertification is pending mailed with return receipt and return receipt, returned to sender.
07/09/21	First Notice from the City advising Recertification is pending mailed with return receipt, delivered
	to new owner.
08/30/21	Notice of Unsafe Structure Violation for Failure to Recertify and Notice of Hearing mailed with
	return receipt.
08/30/21	Notice of Hearing posted on Structure and at City Hall
09/13/21	Board Hearing. Case withdrawn, new owner.
10/05/21	Notice of Unsafe Structure Violation for Failure to Recertify and Notice of Hearing mailed with
	return receipt.
10/05/21	Notice of Hearing posted on Structure and at City Hall
10/18/21	Board Hearing

TO DATE THE OWNER HAS: NOT submitted a Recertification Report for the City's review.

BUILDING OFFICIAL'S RECOMMENDATION: A. Submit a letter from a structural Engineer within seven (7) days of the Board's meeting attesting the structure is safe for occupancy. **B**. Submit a Recertification Report prepared by a licensed Architect or Engineer within sixty (60) days of the Board's Order Recertifying the property. C. A \$250 daily fine be imposed if property is not recertified within the sixty (60) day deadline

PERMIT ACTIVITY: No current permits associated with the Building Recertification