

Main Contractors Custom Fields Plan Routing Rofing Status Fee Summary Actions Routing History

Group	Action Code	Action Description	Completion Date	Complete Code
6	INSP01	INSPECTION CHECK	01/12/2022 02:26:19 PM	part
6	INSP00	INSPECTION CHECK	01/08/2022 02:16:15 PM	part
6	INSP00	INSPECTION CHECK	02/09/2022 02:23:10 PM	part
6	IN71	INSULATION 01 FLOOR	09/22/2021 02:47:38 PM	part
6	IN71	INSULATION 01 FLOOR	01/21/2022 02:40:04 PM	aprvd
6	IN72	INSULATION 02 FLOOR	09/22/2021 02:47:39 PM	part
6	IN72	INSULATION 02 FLOOR	01/21/2022 02:40:04 PM	aprvd
6	IN14	POURED CELLS 01 FLOOR		
6	IN45	SCREW FOR GYPSUM BOARD 01 FLOOR		
6	IN45	SCREW FOR GYPSUM BOARD 01 FLOOR	02/02/2022 02:15:48 PM	reject
6	IN46	SCREW FOR GYPSUM BOARD 02 FLOOR		
6	IN46	SCREW FOR GYPSUM BOARD 02 FLOOR	02/02/2022 02:15:48 PM	reject
6	IN73	SHOP DRAWINGS - EXTERIOR DOORS		
6	IN30	SHOP DRAWINGS - WINDOWS	09/28/2021 10:31:36 AM	cc
6	pw981	STORMWATER, EROSION & SEDIMENT		
6	pw807	SUBGRADE		
6	IN258	WINDOW/DOOR ANCHORS 01 FLOOR	05/11/2021 02:26:39 PM	reject
6	IN258	WINDOW/DOOR ANCHORS 01 FLOOR	05/13/2021 01:57:43 PM	reject
6	IN258	WINDOW/DOOR ANCHORS 01 FLOOR	01/19/2022 03:08:56 PM	aprvd
6	IN259	WINDOW/DOOR ANCHORS 02 FLOOR		
6	IN259	WINDOW/DOOR ANCHORS 02 FLOOR	05/11/2021 02:26:39 PM	reject
6	IN259	WINDOW/DOOR ANCHORS 02 FLOOR	05/13/2021 01:57:43 PM	reject
6	IN259	WINDOW/DOOR ANCHORS 02 FLOOR	10/01/2021 09:55:22 AM	cancel
6	IN259	WINDOW/DOOR ANCHORS 02 FLOOR	01/19/2022 03:08:56 PM	aprvd
6	IN275	WINDOW/DOOR BUCK 01 FLOOR - SHO	05/11/2021 02:26:39 PM	reject
6	IN275	WINDOW/DOOR BUCK 01 FLOOR - SHO	05/13/2021 01:57:43 PM	reject
6	IN275	WINDOW/DOOR BUCK 01 FLOOR - SHO	01/19/2022 03:08:56 PM	aprvd
6	IN276	WINDOW/DOOR BUCK 02 FLOOR - SHO	05/11/2021 02:26:39 PM	reject
6	IN276	WINDOW/DOOR BUCK 02 FLOOR - SHO	05/13/2021 01:57:43 PM	reject
6	IN276	WINDOW/DOOR BUCK 02 FLOOR - SHO	01/19/2022 03:08:56 PM	aprvd
7	PLAN PROCESSING			