

PERMIT CORRECTIONS REPORT (BLDR-22-03-1139) FOR CITY OF CORAL GABLES

PERMIT ADDRESS: 471 LORETTO AVE PARCEL: 0341200231240

Coral Gables, FL 33146

APPLICATION DATE: 03/14/2022 SQUARE FEET: 0.00 DESCRIPTION: REPLACE ROTTED DECK BOARDS & ADJACENT

EXPIRATION DATE: VALUATION: \$500.00 TRELLIS ON EXISTING WOOD DECK

CONTACTS NAME COMPANY ADDRESS

Applicant Thomas Murphy 471 Loretto AVE

Coral Gables, FL 33146

FBC Residential - Seawall

REVIEW ITEM STATUS REVIEWER

Building v.1 Disapproved Manuel Lopez - Building Ph: 460-5242 email: mlopez@coralgables.com

CG - Building

Correction: Building Correction - Manuel Lopez - Building (3/16/22) - Not Resolved

Comments: 1. PROVIDE DETAILS OF REPAIRS.

Corrective Action: N/A

Building v.2 Disapproved Manuel Lopez - Building Ph: 460-5242 email: mlopez@coralgables.com

CG - Building

Correction: Building Correction - Manuel Lopez - Building (5/20/22) - Not Resolved

Comments: 1. PROVIDE DETAILS OF REPAIRS.

Correction: Building Correction - Manuel Lopez - Building (5/20/22) - Not Resolved

Comments: 1. PROVIDE DETAILS OF REPAIRS.

Corrective Action: N/A

City Architect v.1 Disapproved Ana Restrepo - Board of Architects Ph: 569-1857 email:

arestrepo@coralgables.com

CG - City Architect Final

Correction: City Architect Correction - Ana Restrepo - Board of Architects (3/22/22) - Not Resolved

Comments: City Architect Corrections:

- 1- CLARIFY SCOPE OF WORK
- 2- PROVIDE COLOR PHOTOGRAPHS OF EXISTING RESIDENCE
- 3- PROVIDE TYPE OF WOOD FOR DECK
- 4- PROVIDE TYPE OF WOOD, COLOR AND FINISH. CLARIFY WOOD TRELLIS PAINT OR STAIN FINISH. WOOD SHALL BE ANCHORED TO A

CONCRETE FOUNDATION WITH APPROVED METAL CLIPS. PROVIDE CONCEALED CONNECTIONS FOR TRELLIS STRUCTURE

5- FURTHER REVIEW AFTER RESUBMITTAL

Corrective Action: N/A

City Architect v.2 Disapproved Ana Restrepo - Board of Architects Ph: 569-1857 email:

arestrepo@coralgables.com

CG - City Architect Final

Correction: City Architect Correction - Ana Restrepo - Board of Architects (5/20/22) - Not Resolved

Comments: City Architect Corrections:

- 1- CLARIFY SCOPE OF WORK
- 2- PROVIDE COLOR PHOTOGRAPHS OF EXISTING RESIDENCE
- 3- PROVIDE TYPE OF WOOD FOR DECK
- 4- PROVIDE TYPE OF WOOD, COLOR AND FINISH. CLARIFY WOOD TRELLIS PAINT OR STAIN FINISH. WOOD SHALL BE ANCHORED TO A CONCRETE FOUNDATION WITH APPROVED METAL CLIPS. PROVIDE CONCEALED CONNECTIONS FOR TRELLIS STRUCTURE
- 5- FURTHER REVIEW AFTER RESUBMITTAL

Correction: City Architect Correction - Ana Restrepo - Board of Architects (5/31/22) - Not Resolved

Comments: City Architect Corrections

- 1- PROVIDE SURVEY
- 2- INFORMATION ABOUT TRELLIS NOT FOUND ON SET
- 3- SEE PREVIOUS COMMENTS

Corrective Action: N/A

Structural v.1 Disapproved Dariusz Reczek - Structural Ph: 460-5290 email:

dreczek@coralgables.com

CG - Structural

Correction: Structural Correction - Dariusz Reczek - Structural (3/28/22) - Not Resolved

Comments: 1. Provide details on wood species, size and fasteners.

Corrective Action: N/A

PERMIT CORRECTIONS REPORT (BLDR-22-03-1139)

Suramy Cabrera Ph: 305-569-1850 email: scabrera@coralgables.com Structural v.2 Disapproved

CG - Structural

Correction: Structural Correction - Dariusz Reczek - Structural (5/20/22) - Not Resolved

Comments: 1. Provide details on wood species, size and fasteners.

CG - Zoning Final

Zoning v.1

Correction: Zoning Correction - Elisa Darna - Zoning (3/21/22) - Not Resolved

Comments: Zoning corrections

ZONING COMMENT #1

- 1. PROVIDE A SITE PLAN SHOWING EXISTING CONDITIONS AND PROPOSED WORK. SURVEY CAN NOT BE USED AS A SITE PLAN.
- 2. ON THE SITE PLAN, LIST PROPOSED WORK UNDER THIS PERMIT. BE SPECIFIC. DESCRIPTION OF WORK INDICATES TRELLIS REPA IS NO TRELLIS SHOWN ON SURVEY.

Elisa Darna - Zoning Ph: 476-7238 email: edarna@coralgables.com

Elisa Darna - Zoning Ph: 476-7238 email: edarna@coralgables.com

- 3. AREA OF WORK SHOWN ON SURVEY IS LARGER THAN EXISTING DECK. CLARIFY WORK AREA.
- 4. INDICATE PROPOSED WOOD TYPE. SEE SECTION 5-310 FOR ALLOWED MATERIALS AND SPECIFICATIONS.

Disapproved

Disapproved

- INDICATE THAT SUPPORTING MEMBERS SHALL BE ANCHORED TO THE CONCRETE WITH METAL CLIPS TO PROHIBIT THE WOOD FI TOUCHING THE CONCRETE.
- FOR TRELLISES REQUIREMENTS SEE SECTION 5-309. INDICATE COMPLIANCE AS APPLICABLE.

ZONING REVIEWER: ELISA DARNA EDARNA@CORALGABLES.COM

PH: 305-476-7238 Corrective Action: N/A

CG - Zoning Final

Zoning v.2

Correction: Zoning Correction - Elisa Darna - Zoning (5/20/22) - Not Resolved

Comments: Zoning corrections

ZONING COMMENT #1

- 1. PROVIDE A SITE PLAN SHOWING EXISTING CONDITIONS AND PROPOSED WORK. SURVEY CAN NOT BE USED AS A SITE PLAN.
- 2. ON THE SITE PLAN, LIST PROPOSED WORK UNDER THIS PERMIT. BE SPECIFIC. DESCRIPTION OF WORK INDICATES TRELLIS REPA IS NO TRELLIS SHOWN ON SURVEY.
- 3. AREA OF WORK SHOWN ON SURVEY IS LARGER THAN EXISTING DECK. CLARIFY WORK AREA.
- INDICATE PROPOSED WOOD TYPE. SEE SECTION 5-310 FOR ALLOWED MATERIALS AND SPECIFICATIONS.
- INDICATE THAT SUPPORTING MEMBERS SHALL BE ANCHORED TO THE CONCRETE WITH METAL CLIPS TO PROHIBIT THE WOOD FI TOUCHING THE CONCRETE.
- 6. FOR TRELLISES REQUIREMENTS SEE SECTION 5-309. INDICATE COMPLIANCE AS APPLICABLE.

ZONING REVIEWER: ELISA DARNA

EDARNA@CORALGABLES.COM

PH: 305-476-7238

Correction: Zoning Correction - Elisa Darna - Zoning (5/26/22) - Not Resolved

Comments: Zoning corrections

ZONING COMMENTS #2

- SURVEY PREVIOUSLY PROVIDED IS NOT IN FOLDER.
- PROVIDE A COMPLETE SITE PLAN SHOWING EXISTING CONDITIONS AS PER SURVEY. 2.
- PROVIDE ALL REQUIRED SETBACKS FOR DECK AND TRELLIS.
- PROVIDE PERMIT NUMBER FOR EXISTING TRELLIS TO REPAIR.
- NEED TO SHOW EXISTING TRELLIS ON SITE PLAN. FOR TRELLISES REQUIREMENTS SEE SECTION 5-309. INDICATE COMPLIANCE A APPLICABLE.

ZONING REVIEWER: ELISA DARNA EDARNA@CORALGABLES.COM

PH: 305-476-7238 Corrective Action: N/A