

City of Coral Gables Development Services Department

### CONSTRUCTION REGULATION BOARD CASE RESUME

**HEARING DATE:** September 11, 2023,

**CASE NO**.: 23-6271 RECT-23-08-0218

BUILDING ADDRESS: 218 ANTIQUERA AVE

FOLIO NUMBER: 03-4108-009-0620

OWNER: Calabria 230, LLC

USE: Multifamily

PENDING RECERTIFICATION: 2023

## **# OF LIVING UNITS:** 10

# LAST RECERTIFICATION: 2013

## YEAR BUILT: 1953

**DESCRIPTION AND DEFECTS OF BUILDING:** The Building Official has inspected the records relating to the Structure in accordance with Article III, Chapter 105 of the City Code, pertaining to unsafe structures, and Section 8-11 of the Miami-Dade County Code, as applicable in the City, pertaining to existing buildings. The Structure is hereby declared unsafe by the Building Official for failure to timely comply with the maintenance and recertification requirements of the Florida Building Code.

## DATES AND ACTIVITIES:

| 01/30/23 | First Notice from the City advising Recertification is required mailed with return receipt, delivered.                  |
|----------|---|
| 04/30/23 | Second Notice from the City advising Recertification is pending mailed with return receipt, moving through the network. |
| 06/12/23 | Final Notice from the City advising Recertification is pending mailed with return receipt, delivered.                   |
| 08/29/23 | Notice of Unsafe Structure Violation for Failure to Recertify and Notice of Hearing mailed with                         |
| 00/27/25 | return receipt  |
| 08/29/23 | Notice of Hearing posted on Structure and at City Hall.   |
| 09/01/23 | Revised Notice of Unsafe Structure Violation for Failure to Recertify (revised meeting location)                        |
|          | and Notice of Hearing mailed with return receipt.   |
| 09/01/23 | Revised Notice of Hearing posted on Structure and at City Hall (revised meeting location).                              |
| 09/11/23 | Board Hearing   |

TO DATE THE OWNER HAS: NOT submitted a Recertification Report for the City's review.

**BUILDING OFFICIAL'S RECOMMENDATION:** A. Submit a letter from a structural Engineer within seven (7) days of the Board's meeting attesting the structure is safe for occupancy B. Submit a Recertification Report prepared by a licensed Architect or Engineer within sixty (60) days of the Board's Order Recertifying the property. C. A \$250 daily fine be imposed, if any of these deadlines are not met.

**PERMIT ACTIVITY:** No current permits associated with the Building Recertification