
Alhambra Circle Entrance on Douglas Road

June 10, 2025






PLAN VIEW





_____)





- Uneven surface through historical entrance
- Royal Poinciana tree branch blocking entrance walkway on North side
- Tree trimming will expose tree to potential decay
- Recommend tree removal



