

City of Coral Gables Development Services Department

$\frac{\textbf{CONSTRUCTION REGULATION BOARD}}{\textbf{CASE RESUME}}$

HEARING DATE: January 9, 2023 **CASE NO.:** 22-4462

BUILDING ADDRESS: 520 VALENCIA AVE

FOLIO NUMBER: 03-4117-008-2290

OWNER: Valencia 520 524 LLC

USE: Multifamily # **OF LIVING UNITS:** 6

PENDING RECERTIFICATION: 2022 LAST RECERTIFICATION DATE: 2012

YEAR BUILT: 1972

DESCRIPTION AND DEFECTS OF BUILDING: The Building Official has inspected the records relating to the Structure in accordance with Article III, Chapter 105 of the City Code, pertaining to unsafe structures, and Section 8-11 of the Miami-Dade County Code, as applicable in the City, pertaining to existing buildings. The Structure is hereby declared unsafe by the Building Official for failure to timely comply with the maintenance and recertification requirements of the Florida Building Code.

First Notice from the City advising Recertification is required mailed with return receipt, in transit

DATES AND ACTIVITIES:

01/03/22

	to next facility.
04/04/22	Second Notice from the City advising Recertification is pending mailed with return receipt,
	delivered.
06/09/22	Final Notice from the City advising Recertification is pending mailed with return receipt,
	delivered.
07/10/22	Letter from a structural Engineer submitted attesting the structure is safe for occupancy.
07/27/22	Notice of Unsafe Structure Violation for Failure to recertify and Notice of Hearing mailed
	with return receipt, delivered
07/27/22	Notice of Hearing posted on Structure and at City Hall.
08/08/22	Board Hearing: case withdrawn due to report submittal
08/23/22	Recertification Report rejected; repairs required (Building & Electrical).
08/30/22	60 days extension granted to do repairs.
10/29/22	EXTENSION EXPIRED
12/22/22	Notice of Unsafe Structure Violation for Failure to recertify and Notice of Hearing mailed
	with return receipt.
12/22/22	Notice of Hearing posted on Structure and at City Hall.
01/09/23	Board Hearing

TO DATE THE OWNER HAS: NOT submitted a revised Recertification Report for the City's review.

BUILDING OFFICIAL'S RECOMMENDATION: A. Submit an updated letter from a structural Engineer within seven (7) days of the Board's meeting attesting the structure is safe for occupancy **B.** Submit a revised Recertification Report prepared by a licensed Architect or Engineer within sixty (60) days of the Board's Order Recertifying the property. **C.** A \$250 daily fine be imposed, if any of these deadlines are not met.

PERMIT ACTIVITY: No current permits associated with the Building Recertification