From:

Goizueta, Virginia

Sent:

Thursday, October 29, 2015 1:31 PM

To: Cc: alp@alp-law.com Garcia, Belkys

Subject:

FW: American Legion Post 98, Case No. 15-4406

Alexander, please read below.

Virginia Goizueta

Building Service Coordinator City of Coral Gables Development Services Department 405 Biltmore Way, 3<sup>rd</sup> Floor Coral Gables, Florida 33134

Office: 305-460-5250



Celebrating 90 years of a dream realized.

From: Lopez, Manuel

**Sent:** Thursday, October 29, 2015 12:30 PM **To:** 'John M.Thomson, P.A.'; Goizueta, Virginia

Cc: 'dominic angelica'

Subject: RE: American Legion Post 98, Case No. 15-4406

Virginia please notify our attorney.

Manuel Z. Lopez P.E. Building Official City of Coral Gables Development Services Department 405 Biltmore Way, 3<sup>rd</sup> Floor Coral Gables Florida, 33134 305-460-5242



Celebrating 90 years of a dream realized.



From: John M.Thomson, P.A. [mailto:jmtlaw59@aol.com]

Sent: Thursday, October 29, 2015 11:39 AM

To: Lopez, Manuel Cc: 'dominic angelica'

Subject: American Legion Post 98, Case No. 15-4406

### Manny

As I indicated to you over the phone today, I am the Post Judge Advocate (SJA) and have been asked by the Post Commander to respond to the Order Declaring our building at 301 Alhambra Circle to be an unsafe structure.

Commander Angelica has taken the day off to search for the report that he was assured was filed last year. He wants you to know that he was not ignoring the several notices received from the city informing him that the report was past due. He didn't receive notice of the recent hearing and only learned of it from our registered agent, attorney Toby Muir. He is very upset that this could happen on his watch and wants you to know that the report will be in your hands ASAP.

If he does not find the report he was told had been filed, he will authorize me to employ Tom Cooper of Chael, Cooper & Associates P.A, who prepared the 40 year report in 2004, to prepare the report now required by the City.

Jack
John M. Thomson, Esq.
John M. Thomson, P.A.
Suite 310
100 Almeria Avenue
Coral Gables, Florida 33134
Telephone: 305-443-5444
Facsimile: 305-443-4446

The information contained in this E-Mail, including any attachments, is confidential, intended only for the named recipient(s), and may be legally privileged. if you are not the intended recipient, please delete the E-Mail and any attachments, destroy any printouts that you may have made and notify us immediately by return E-Mail. Thank you.

### ATTORNEYS AT LAW

DUNWODY WHITE & LANDON, P.A.

FRANK T. ADAMS JACKSON M. BRUCE, JR. DANIEL K. CAPES DENISE B. CAZOBON NEIL R. CHRYSTAL JORGE DE LA CRUZ-MUÑOZ JACK A. FALK, JR. RONALD L. FICK JOHN J. GRUNDHAUSER

DAVID M. HALPEN ROBERT D. W. LANDON, II IEREMY P. LEATHE THOMAS J. MATKOV WILLIAM T. MUIR ALFRED J. STASHIS, JR. ROBERT A. WHITE

ATWOOD DUNWODY (1912-1996)

Please reply to Miami office e-mail: wmuir@dwl-law.com

November 3, 2015

### VIA U.S. MAIL and

E-MAIL: mlopez@coralgables.com

Manuel Z. Lopez, P.E. **Building Official** City of Coral Gables PO Box 141549 Coral Gables, Florida 33114-1549

> Coral Gables Post no. 98, American Legion, Inc. ("Post 98") Re:

> > CASE NO. 15-4406

Dear Mr. Lopez:

Thank you for your letter dated October 27, 2015 enclosing a copy of the Order Declaring Structure Unsafe issued on October 28, 2015, by the Construction Regulation Board for Failure to Recertify and Notice of Hearing that was served on me yesterday, November 2, 2015, as Registered Agent for Post 98.

Upon receipt of your letter and the Order, in collaboration with co-counsel John M. Thomson, Esq., on behalf of Post 98, we have immediately commenced the Required Actions as follows:

- (a) Begun taking actions necessary to obtain and submit an inspecting report,
- completing the required repairs, and (b)
- (c) submitting a letter from the architect or engineer who prepared the Report stating that the Structure now meets the minimum requirements.

On behalf of Post 98, we respectfully request that, at this time while we are working to assist Post 98 with its compliance, no action be taken to cause Florida Power & Light Company to disconnect power to the Structure.

William 1. Musi

WTM/ama

cc (via e-mail):

Virginia Goizueta, vgoizueta@coralgables.com

John M. Thomson, Esq.

m personal wtm american legion ltr lopez 11-2015 re o-deci struc unsafe doc

MIAMI 550 Biltmore Way Suite 810 Coral Gables, Florida 33134 Telephone 305 / 529-1500 Fax 305 / 529-8855

NAPLES 4001 Tamiami Trail North Suite 200 Naples, Florida 34103 Telephone 239 / 263-5885 Fax 239 / 262-1442

Plaza Center, Suite 501 249 Royal Palm Way Palm Beach, Florida 33480 Telephone 561 / 655-2120 Fax 561 / 655-2168

PALM BEACH

www.dwl-law.com

From:

Goizueta, Virginia

Sent:

Tuesday, November 03, 2015 11:32 AM

To:

'Acosta, Adrya M.'; Lopez, Manuel

Cc: Subject: Muir, William T.; 'JMTLAW59@aol.com'; Garcia, Belkys RE: American Legion Post No. 98 - CASE NO. 15-4406

The following is the City Council's information.

Alexander L. Palenzuela Law Offices of Alexander L. Palenzuela, P.A. 1200 Brickell Avenue, Suite 1440 Miami, FL 33131-3205 main (305) 375-9510, ext. 303 direct +1 (305) 417-9007 fax (305) 375-9511 alp@alp-law.com www.alp-law.com

Oirginia Goizueta

Building Service Coordinator City of Coral Gables **Development Services Department** 405 Biltmore Way, 3rd Floor Coral Gables, Florida 33134

Office: 305-460-5250



Celebrating 90 years of a dream realized.

From: Acosta, Adrya M. [mailto:aacosta@dwl-law.com]

Sent: Tuesday, November 03, 2015 11:32 AM

To: Lopez, Manuel

Cc: Goizueta, Virginia; Muir, William T.; 'JMTLAW59@aol.com' Subject: American Legion Post No. 98 - CASE NO. 15-4406

Dear Mr. Lopez:

For your review, attached is Mr. William T. Muir's correspondence of today's date.

Should you have any questions or encounter any problems with the attachment, please let us know.

Sincerely,

Adrya Maria Acosta Assistant to William T. Muir, Esq. Dunwody White & Landon, P.A. 550 Biltmore Way, Suite 810 Coral Gables, FL 33134

E-mail: aacosta@dwl-law.com

Phone: 305-529-1500 Facsimile: 305-529-8855

Dunwody White & Landon, P.A. | Coral Gables (Miami): 305-529-1500 | Naples: 239-263-5885 | Palm Beach: 561-655-2120 | You may obtain further information on our firm, including the mailing addresses of our offices, by visiting our web site at: <a href="https://www.dwl-law.com">www.dwl-law.com</a> | The information contained in this transmission is attorney privileged and/or confidential information intended for the use of the individual or entity named above. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited.

From:

alp@alp-law.com

Sent:

Tuesday, November 03, 2015 6:17 PM

To:

Garcia, Belkys; Lopez, Manuel

Cc:

Goizueta, Virginia

Subject:

FW: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

**FYI** 

Very truly yours,

Alexander L. Palenzuela
Law Offices of Alexander L. Palenzuela, P.A.
1200 Brickell Avenue, Suite 1440
Miami, FL 33131-3205
main (305) 375-9510, ext. 303
direct +1 (305) 417-9007
fax (305) 375-9511
alp@alp-law.com
www.alp-law.com

### PLEASE CONSIDER THE ENVIRONMENT BEFORE PRINTING

This message, together with any attachments, is intended only for the addressee. It may contain information which is legally privileged, confidential and exempt from disclosure. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, use, or any action or reliance on this communication is strictly prohibited. If you have received this e-mail in error, please notify the sender immediately by telephone, at (305) 375-9510, ext. 303, or by return e-mail and delete this message, along with any reply and attachments.

Tax Advice Disclosure: To ensure compliance with requirements imposed by the IRS under Circular 230, we inform you that any U.S. federal tax advice contained in this communication (including any attachments), unless otherwise specifically stated, was not intended or written to be used, and cannot be used, for the purpose of (1) avoiding penalties under the Internal Revenue Code or (2) promoting, marketing or recommending to another party any matters addressed herein.

From: "John M.Thomson, P.A." < jmtlaw59@aol.com>

Date: Tuesday, November 3, 2015 at 4:26 PM

To: "thomastcooper@gmail.com" <thomastcooper@gmail.com>

Cc: "wmuir@dwl-law.com" <wmuir@dwl-law.com>, Alexander Palenzuela <alp@alp-law.com>, Manuel Lopez <mlopez@coralgables.com>, Virginia Goizueta <vgoizueta@coralgables.com>, "art2@ntrs.com" <art2@ntrs.com>, 'dominic angelica' <copdad2054@yahoo.com>, "americanlegion98@aol.com" <a href="mailto:americanlegion98@aol.com">americanlegion98@aol.com</a>

Subject: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

Dear Mr. Cooper

This will confirm that you have been retained by the American Legion Post 98 to perform the required building 10 year recertification for the above referenced property, folio # 03-4108-006-2430.

The current Post Commander is: Art Angelica. His mobile phone is: 786-306-5929. He is easily reached by text message. He can arrange for a member to meet you or your representative at the premises. He will also inform the Doctor next door, who is a tenant, and arrange for your access to his premises. If you have any difficulty call me at the below number or Toby Muir, co counsel at: 305-529-1500

The property information indicated on your prior report dated August 18, 2004 is correct. If you need it, I can scan and mail you a copy of that report.

As I indicated over the phone the report is past due and, in fact, an order has been entered dated October 28, 2015 that the property has been determined to be an unsafe structure for failure to timely file this report. We have asked for an extension of time to accomplish this task. It would be helpful if you could reply to all indicating when the inspection may be performed.

If you need any additional information please contact me or Toby Muir.

Jack
John M. Thomson, Esq.
John M. Thomson, P.A.
Suite 310
100 Almeria Avenue
Coral Gables, Florida 33134
Telephone: 305-443-5444
Facsimile: 305-443-4446

The information contained in this E-Mail, including any attachments, is confidential, intended only for the named recipient(s), and may be legally privileged. if you are not the intended recipient, please delete the E-Mail and any attachments, destroy any printouts that you may have made and notify us immediately by return E-Mail. Thank you.

From:

Lopez, Manuel Wednesday, November 04, 2015 9:07 AM Sent:

'alp@alp-law.com'; Goizueta, Virginia; Garcia, Belkys To:

Cc: Figueroa, Yaneris

RE: American Legion Post No. 98 - CASE NO. 15-4406 Subject:

I am fine with this. I do not want to disconnect power at this time. Now that Mr. Thomson is involved I am sure they will comply.

Manuel Z. Lopez P.E. **Building Official** City of Coral Gables **Development Services Department** 405 Biltmore Way, 3rd Floor Coral Gables Florida, 33134 305-460-5242



Celebrating 90 years of a dream realized.

From: alp@alp-law.com [mailto:alp@alp-law.com] Sent: Tuesday, November 03, 2015 6:57 PM

To: Lopez, Manuel; Goizueta, Virginia; Garcia, Belkys

Cc: Figueroa, Yaneris

Subject: FW: American Legion Post No. 98 - CASE NO. 15-4406

Please let me know what the City decides on the request not to disconnect power. If they do not meet with the deadlines in the order, then we will prepare a notice of non-compliance. Otherwise, the City can decide to hold off on disconnecting without any other formal actions than letting them know to meet the deadlines in the order to prevent disconnection.

Thanks!

Very truly yours,

Alexander L. Palenzuela Law Offices of Alexander L. Palenzuela, P.A. 1200 Brickell Avenue, Suite 1440 Miami, FL 33131-3205 main (305) 375-9510, ext. 303 direct +1 (305) 417-9007 fax (305) 375-9511 alp@alp-law.com www.alp-law.com

### PLEASE CONSIDER THE ENVIRONMENT BEFORE PRINTING

This message, together with any attachments, is intended only for the addressee. It may contain information which is legally privileged, confidential and exempt from disclosure. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, use, or any action or reliance on this communication is strictly prohibited. If you have received this e-mail in error, please notify the sender immediately by telephone, at (305) 375-9510, ext. 303, or by return e-mail and delete this message, along with any reply and attachments.

Tax Advice Disclosure: To ensure compliance with requirements imposed by the IRS under Circular 230, we inform you that any U.S. federal tax advice contained in this communication (including any attachments), unless otherwise specifically stated, was not intended or written to be used, and cannot be used, for the purpose of (1) avoiding penalties under the Internal Revenue Code or (2) promoting, marketing or recommending to another party any matters addressed herein.

From: "Acosta, Adrya M." <aacosta@dwl-law.com>
Date: Tuesday, November 3, 2015 at 1:56 PM
To: Alexander Palenzuela <alp@alp-law.com>

Cc: Virginia Goizueta <<u>vgoizueta@coralgables.com</u>>, Belkys Garcia <<u>bgarcia@coralgables.com</u>>, "Muir, William T." <<u>wmuir@dwl-law.com</u>>, Manuel Lopez <<u>mlopez@coralgables.com</u>>, "'JMTLAW59@aol.com'" <<u>JMTLAW59@aol.com</u>> Subject: American Legion Post No. 98 - CASE NO. 15-4406

Dear Mr. Palenzuela:

For your review, attached is a letter to the City of Coral Gables from Mr. Muir. Ms. Virginia Goizueta requested we forward it to you.

If you have any questions, concerns or encounter any problems with the attachment, please let us know. Sincerely,

Adrya Maria Acosta Assistant to William T. Muir, Esq. Dunwody White & Landon, P.A. 550 Biltmore Way, Suite 810 Coral Gables, FL 33134

E-mail: aacosta@dwl-law.com

Phone: 305-529-1500 Facsimile: 305-529-8855

Dunwody White & Landon, P.A. | Coral Gables (Miami): 305-529-1500 | Naples: 239-263-5885 | Palm Beach: 561-655-2120 | You may obtain further information on our firm, including the mailing addresses of our offices, by visiting our web site at: <a href="https://www.dwl-law.com">www.dwl-law.com</a> | The information contained in this transmission is attorney privileged and/or confidential information intended for the use of the individual or entity named above. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited.

From:

alp@alp-law.com

Sent:

Wednesday, November 04, 2015 3:02 PM

To:

Garcia, Belkys; Goizueta, Virginia

Subject:

FW: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

**FYI** 

Very truly yours,

Alexander L. Palenzuela
Law Offices of Alexander L. Palenzuela, P.A.
1200 Brickell Avenue, Suite 1440
Miami, FL 33131-3205
main (305) 375-9510, ext. 303
direct +1 (305) 417-9007
fax (305) 375-9511
alp@alp-law.com
www.alp-law.com

### PLEASE CONSIDER THE ENVIRONMENT BEFORE PRINTING

This message, together with any attachments, is intended only for the addressee. It may contain information which is legally privileged, confidential and exempt from disclosure. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, use, or any action or reliance on this communication is strictly prohibited. If you have received this e-mail in error, please notify the sender immediately by telephone, at (305) 375-9510, ext. 303, or by return e-mail and delete this message, along with any reply and attachments.

Tax Advice Disclosure: To ensure compliance with requirements imposed by the IRS under Circular 230, we inform you that any U.S. federal tax advice contained in this communication (including any attachments), unless otherwise specifically stated, was not intended or written to be used, and cannot be used, for the purpose of (1) avoiding penalties under the Internal Revenue Code or (2) promoting, marketing or recommending to another party any matters addressed herein.

From: Thomas T Cooper < <a href="mailto:thomastcooper@gmail.com">thomas T Cooper < <a href="mailto:thomastcooper@gmail.com">thomastcooper@gmail.com</a>>
<a href="mailto:balaution.com">Date: Wednesday, November 4, 2015 at 2:59 PM</a>

To: "John M.Thomson, P.A." < jmtlaw59@aol.com>

Cc: "wmuir@dwi-law.com" <wmuir@dwi-law.com>, Alexander Palenzuela <alp@alp-law.com>, Manuel Lopez <mlopez@coralgables.com>, Virginia Goizueta <vgoizueta@coralgables.com>, "art2@ntrs.com" <art2@ntrs.com>, 'dominic angelica' <copdad2054@yahoo.com>, "americanlegion98@aol.com" <americanlegion98@aol.com>

Subject: RE: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

Jack, thank you for this opportunity to work on this recertification for the American Legion Post 98. I have talked with the Electrical Engineer and we are trying to determine the best day for the inspection. I will call you on Thursday with the date. We have given this top priority and will do our best to expedite.

Tom Cooper, AIA

# THOMAS T. COOPER

STATE OF FLORIDA LICENSE NUMBER AR 0004486

#### THOMASTCOOPER@GMAIL.COM

THOMASTCOOPER COM 4498 NE SKYLINE DRIVE JENSEN BEACH, FL 34957 TEL 772.232.1767 CEL 305.667.2009 FAX 772.232.1767

From: John M.Thomson, P.A. [mailto:jmtlaw59@aol.com]

Sent: Tuesday, November 03, 2015 4:27 PM

To: <a href="mailto:thomastcooper@gmail.com">thomastcooper@gmail.com</a>

Cc: wmuir@dwl-law.com; alp@alp-law.com; mlopez@coralgables.com; vgoizueta@coralgables.com; art2@ntrs.com;

'dominic angelica'; americanlegion98@aol.com

Subject: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

Dear Mr. Cooper

This will confirm that you have been retained by the American Legion Post 98 to perform the required building 10 year recertification for the above referenced property, folio # 03-4108-006-2430.

The current Post Commander is: Art Angelica. His mobile phone is: 786-306-5929. He is easily reached by text message. He can arrange for a member to meet you or your representative at the premises. He will also inform the Doctor next door, who is a tenant, and arrange for your access to his premises. If you have any difficulty call me at the below number or Toby Muir, co counsel at: 305-529-1500

The property information indicated on your prior report dated August 18, 2004 is correct. If you need it, I can scan and mail you a copy of that report.

As I indicated over the phone the report is past due and, in fact, an order has been entered dated October 28, 2015 that the property has been determined to be an unsafe structure for failure to timely file this report. We have asked for an extension of time to accomplish this task. It would be helpful if you could reply to all indicating when the inspection may be performed.

If you need any additional information please contact me or Toby Muir.

Jack
John M. Thomson, Esq.
John M. Thomson, P.A.
Suite 310
100 Almeria Avenue
Coral Gables, Florida 33134
Telephone: 305-443-5444
Facsimile: 305-443-4446

The information contained in this E-Mail, including any attachments, is confidential, intended only for the named recipient(s), and may be legally privileged if you are not the intended recipient, please delete the E-Mail and any attachments, destroy any printouts that you may have made and notify us immediately by return E-Mail. Thank you.

From:

alp@alp-law.com

Sent:

Thursday, November 05, 2015 10:39 AM

To:

Goizueta, Virginia; Garcia, Belkys; Lopez, Manuel; Figueroa, Yaneris

Subject:

FW: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

FYI

Very truly yours,

Alexander L. Palenzuela
Law Offices of Alexander L. Palenzuela, P.A.
1200 Brickell Avenue, Suite 1440
Miami, FL 33131-3205
main (305) 375-9510, ext. 303
direct +1 (305) 417-9007
fax (305) 375-9511
alp@alp-law.com
www.alp-law.com

### PLEASE CONSIDER THE ENVIRONMENT BEFORE PRINTING

This message, together with any attachments, is intended only for the addressee. It may contain information which is legally privileged, confidential and exempt from disclosure. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, use, or any action or reliance on this communication is strictly prohibited. If you have received this e-mail in error, please notify the sender immediately by telephone, at (305) 375-9510, ext. 303, or by return e-mail and delete this message, along with any reply and attachments.

Tax Advice Disclosure: To ensure compliance with requirements imposed by the IRS under Circular 230, we inform you that any U.S. federal tax advice contained in this communication (including any attachments), unless otherwise specifically stated, was not intended or written to be used, and cannot be used, for the purpose of (1) avoiding penalties under the Internal Revenue Code or (2) promoting, marketing or recommending to another party any matters addressed herein.

From: Alexander Palenzuela <alp@alp-law.com> Date: Thursday, November 5, 2015 at 10:38 AM

To: Thomas T Cooper < thomastcooper@gmail.com >, "'John M.Thomson, P.A.'" < imtlaw59@aol.com >

Cc: "wmuir@dwl-law.com" <wmuir@dwl-law.com>, Manuel Lopez <mlopez@coralgables.com>, Virginia Goizueta <vgoizueta@coralgables.com>, "art2@ntrs.com" <art2@ntrs.com>, 'dominic angelica' <copdad2054@yahoo.com>,

"americanlegion98@aol.com" <americanlegion98@aol.com>

Subject: Re: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

Dear Sirs:

Please note that the structure is actually due for its 90-year recertification. Because the structure has a parking lot, the Miami-Dade County ordinance requires the light level survey and report.

Thank you.

Very truly yours,

Alexander L. Palenzuela
Law Offices of Alexander L. Palenzuela, P.A.
1200 Brickell Avenue, Suite 1440
Miami, FL 33131-3205
main (305) 375-9510, ext. 303
direct +1 (305) 417-9007
fax (305) 375-9511
alp@alp-law.com
www.alp-law.com

### PLEASE CONSIDER THE ENVIRONMENT BEFORE PRINTING

This message, together with any attachments, is intended only for the addressee. It may contain information which is legally privileged, confidential and exempt from disclosure. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, use, or any action or reliance on this communication is strictly prohibited. If you have received this e-mail in error, please notify the sender immediately by telephone, at (305) 375-9510, ext. 303, or by return e-mail and delete this message, along with any reply and attachments.

Tax Advice Disclosure: To ensure compliance with requirements imposed by the IRS under Circular 230, we inform you that any U.S. federal tax advice contained in this communication (including any attachments), unless otherwise specifically stated, was not intended or written to be used, and cannot be used, for the purpose of (1) avoiding penalties under the Internal Revenue Code or (2) promoting, marketing or recommending to another party any matters addressed herein.

From: Thomas T Cooper < thomastcooper@gmail.com >

Date: Thursday, November 5, 2015 at 10:14 AM

To: "John M.Thomson, P.A." < imtlaw59@aol.com>

Cc: "wmuir@dwl-law.com" <wmuir@dwl-law.com>, Alexander Palenzuela <alp@alp-law.com>, Manuel Lopez <mlopez@coralgables.com>, Virginia Goizueta <vgoizueta@coralgables.com>, "art2@ntrs.com" <art2@ntrs.com" <art2@ntrs.com</a>, 'dominic angelica' <copdad2054@yahoo.com>, "americanlegion98@aol.com" <a href="mailto:americanlegion98@aol.com">americanlegion98@aol.com</a>> Subject: RE: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

The electrical engineer and I will be at the site Friday November 6, at 10:00 am for the inspections. Please review and sign the attached agreements. If you could deliver a signed copy to us with the retainer checks it would be appreciated.

Tom Cooper, AIA



STATE OF FLORIDA LICENSE NUMBER AR 0004486

THOMASTCOOPER@GMAIL.COM

THOMASTCOOPER.COM 4498 NE SKYLINE DRIVE JENSEN BLACH, FL 34957 TEL .772.232.1767 CEL 305.667.2009 FAX 772.232.1767 From: John M.Thomson, P.A. [mailto:jmtlaw59@aol.com]

Sent: Thursday, November 05, 2015 10:03 AM

**To:** 'Thomas T Cooper'

Subject: RE: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

Thank you. Jack

John M. Thomson, Esq. John M. Thomson, P.A. Suite 310 100 Almeria Avenue

Coral Gables, Florida 33134 Telephone: 305-443-5444 Facsimile: 305-443-4446

From: Thomas T Cooper [mailto:thomastcooper@gmail.com]

Sent: Wednesday, November 04, 2015 2:59 PM

To: 'John M.Thomson, P.A.'

Cc: wmuir@dwl-law.com; alp@alp-law.com; mlopez@coralgables.com; vgoizueta@coralgables.com; art2@ntrs.com;

'dominic angelica'; americanlegion98@aol.com

Subject: RE: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

Jack, thank you for this opportunity to work on this recertification for the American Legion Post 98. I have talked with the Electrical Engineer and we are trying to determine the best day for the inspection. I will call you on Thursday with the date. We have given this top priority and will do our best to expedite.

Tom Cooper, AIA



STATE OF FLORIDA LICENSE NUMBER AR 0004486

### THOMASTCOOPER@GMAIL.COM

THOMASTCOOPER COM 4498 NE SKYLINE DRIVE JENSEN BEACH, FL 34957 TEL 772.232:1767 CEL 305.667.2009 FAX 772.232.1767

From: John M.Thomson, P.A. [mailto:jmtlaw59@aol.com]

Sent: Tuesday, November 03, 2015 4:27 PM

To: thomastcooper@gmail.com

Cc: wmuir@dwl-law.com; alp@alp-law.com; mlopez@coralgables.com; vgoizueta@coralgables.com; art2@ntrs.com;

'dominic angelica'; americanlegion98@aol.com

Subject: 301-303-305 Alhambra Circle, Coral GAbles, FL 33134

Dear Mr. Cooper

This will confirm that you have been retained by the American Legion Post 98 to perform the required building 10 year recertification for the above referenced property, folio # 03-4108-006-2430.

The current Post Commander is: Art Angelica. His mobile phone is: 786-306-5929. He is easily reached by text message. He can arrange for a member to meet you or your representative at the premises. He will also inform the

Doctor next door, who is a tenant, and arrange for your access to his premises. If you have any difficulty call me at the below number or Toby Muir, co counsel at: 305-529-1500

The property information indicated on your prior report dated August 18, 2004 is correct. If you need it, I can scan and mail you a copy of that report.

As I indicated over the phone the report is past due and, in fact, an order has been entered dated October 28, 2015 that the property has been determined to be an unsafe structure for failure to timely file this report. We have asked for an extension of time to accomplish this task. It would be helpful if you could reply to all indicating when the inspection may be performed.

If you need any additional information please contact me or Toby Muir.

Jack
John M. Thomson, Esq.
John M. Thomson, P.A.
Suite 310
100 Almeria Avenue
Coral Gables, Florida 33134
Telephone: 305-443-5444
Facsimile: 305-443-4446

The information contained in this E-Mail, including any attachments, is confidential, intended only for the named recipient(s), and may be legally privileged. if you are not the intended recipient, please delete the E-Mail and any attachments, destroy any printouts that you may have made and notify us immediately by return E-Mail. Thank you.

### CITY OF CORAL GABLES



### CODE ENFORCEMENT DIVISION

427 Biltmore Way, Suite 100

Case #: CE261560-110915

### **Notice of Violation**

AMERICAN LEGION POST NO 98 PO BOX 224 CORAL GABLES FL 331140224

Folio #: 0341080062430

Dear Property Owner and/or Occupant:

This letter constitutes a notice that a violation(s) exists on the premises at 301 ALHAMBRA CIR, Coral Gables, FL.

The violation(s) found was:

#### Violations:

Violation of Coral Gables City Code.

Code Enforcement Officer Comments: Violation of 8-11 of the Miami-Dade County Code, as applicable in the City, and of Section 105-186(j)(13) as adopted in City Ordinance 2015-18, by failing to complete the recertification process for the structure.

### The following steps should be taken to correct the violation:

Remedy: Apply for and obtain a recertification letter, including, but not limited to, by submitting a recertification report and applying for, obtaining, and passing final inspection on all permits required to correct any deficiencies noted the report, and submitting a compliance report.

The regulations enforced by the City have been adopted in order to protect the public and assure continuing high property values. Your immediate attention to correcting the violation(s) listed above is required.

The Code Enforcement Division will re-inspect the property on 12/9/2015 to determine if corrective measures have been completed. If the violation(s) has not been corrected at the time of inspection, your case will be presented to the Code Enforcement Board for review and possible action. At that time, you will have the opportunity to explain to the citizens serving on the Board the reasons why the violation(s) has not been corrected. The Board has the authority to assess a fine against you for as long as the violation continues.

The Division is available for consultation on this matter from 7:30 AM to 4:00 PM. Please do not hesitate to call the Code Enforcement Officer below for additional assistance.

Martha Delgado

Code Enforcement Officer

305 460-5325

mdelgado@coraigables.com

who & Kelush

## LAW OFFICES JOHN M. THOMSON, P.A.

ATTORNEY AT LAW 100 ALMERIA AVENUE SUITE 310 CORAL GABLES (MIAMI), FLORIDA 33I34-8711

Robert M. Thomson (1898-1976) COL. John M. (Jack) Thomson (Florida Bar 1959) TELEPHONE (305) 443-5444
TELEFAX (305) 443-4446
E-Mail: <u>JMTLAW59@aol.com</u>

January 6, 2016

Belkys Garcia
CITY OF CORAL GABLES
405 Biltmore Way
Coral Gables, Florida 33134

Re:

CORAL GABLES POST 98 AMERICAN LEGION, INC.

ads. CITY OF CORAL GABLES

Case No.: 15-4406

Dear Miss Garcia:

On behalf of Post 98, as its Staff Judge Advocate, I hereby request to be allowed to appear before the administrative judge to ask for an extension of time to comply with the requirements of the Unsafe Structures board for the reason that the installation of the illumination required by the 40 year or older recertification report filed with the City on November 11, 2015, Permit Number RC15-11-5548, is out for bid and cannot be accomplished until a licensed contractor can be employed to perform this task. The Post has sufficient funds to pay for this expense.

Sincerely,

JOHN M. THOMSON

JMT:bes

CC:

Antonio Silio

M. Lopez

From: alp@alp-law.com

Sent: Wednesday, January 06, 2016 3:10 PM

To: John M.Thomson, P.A.

Cc: 'Muir, William T.'; Goizueta, Virginia; Figueroa, Yaneris; Lopez, Manuel; Silio, Antonio;

Garcia, Belkys

**Subject:** Re: Coral Gables Post No. 98 American Legion, Inc ads City of Coral Gables, Case No.

15-4406 - 301 Alhambra Cir

Dear Mr. Thompson:

The City will set this matter for hearing on the notice of non-compliance on Monday, February, 8, 2016 at 2 p.m.

Thank you.

Very truly yours,

Alexander L. Palenzuela
Law Offices of Alexander L. Palenzuela, P.A.
1200 Brickell Avenue, Suite 1440
Miami, FL 33131-3205
main (305) 375-9510, ext. 303
direct +1 (305) 417-9007
fax (305) 375-9511
alp@alp-law.com
www.alp-law.com

### PLEASE CONSIDER THE ENVIRONMENT BEFORE PRINTING

This message, together with any attachments, is intended only for the addressee. It may contain information which is legally privileged, confidential and exempt from disclosure. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, use, or any action or reliance on this communication is strictly prohibited. If you have received this e-mail in error, please notify the sender immediately by telephone, at (305) 375-9510, ext. 303, or by return e-mail and delete this message, along with any reply and attachments.

Tax Advice Disclosure: To ensure compliance with requirements imposed by the IRS under Circular 230, we inform you that any U.S. federal tax advice contained in this communication (including any attachments), unless otherwise specifically stated, was not intended or written to be used, and cannot be used, for the purpose of (1) avoiding penalties under the Internal Revenue Code or (2) promoting, marketing or recommending to another party any matters addressed herein.

From: "John M.Thomson, P.A." < imtlaw59@aol.com>

Date: Wednesday, January 6, 2016 at 3:00 PM To: Belkys Garcia <br/>
bgarcia@coralgables.com

Cc: Alexander Palenzuela <alp@alp-law.com>, "'Muir, William T." <wmuir@dwl-law.com>, Virginia Goizueta

<vgoizueta@coralgables.com>, Yaneris Figueroa <yfigueroa@coralgables.com>, Manuel Lopez

<mlopez@coralgables.com>, Antonio Silió <asilio@coralgables.com>

Subject: Coral Gables Post No. 98 American Legion, Inc ads City of Coral Gables, CAse No. 15-4406

On behalf of Post 98, as its Staff Judge Advocate, I hereby request to be allowed to appear before the administrative judge to ask for an extension of time to comply with the requirements of the Unsafe Structures Board for the reason that the installation of the illumination required by the 40 year or older recertification report filed with the City on November 11, 2015, Permit Number RC15-11-5548, is out for bid and cannot be accomplished until a licensed contractor can be employed to perform this task. The Post has sufficient funds to pay for this expense.

John M. Thomson, Esq. John M. Thomson, P.A. Suite 310 100 Almeria Avenue Coral Gables, Florida 33134 Telephone: 305-443-5444 Facsimile: 305-443-4446

The information contained in this E-Mail, including any attachments, is confidential, intended only for the named recipient(s), and may be legally privileged. If you are not the intended recipient, please delete the E-Mail and any attachments, destroy any printouts that you may have made and notify us immediately by return E-

Mail. Thank you.

From:

Garcia, Belkys

Sent:

Thursday, January 07, 2016 8:01 AM

To:

Figueroa, Yaneris: Lopez, Manuel

Cc:

alp@alp-law.com; 'Muir, William T.'; Goizueta, Virginia; Silio, Antonio; 'John M.Thomson,

P.A.<sup>1</sup>

Subject:

Case No. 15-4406 - 301 Alhambra Circle

Attachments:

Sent from the City of Coral Gables Development Services Department

### Good morning,

The above Subject address and Case appeared before the Construction Regulation Board on October 19, 2015. The Recertification Report was rejected by the Electrical Official on November 20, 2015 due to insufficient parking lot lighting (#RC15115548). A plan was submitted to correct the lighting issue and is currently pending permit issuance (#EL15125735). Additionally, Administrative Construction Regulation Board and Board of Architects fees are pending as well on this Case. See Attached email which includes the pending Invoices and letter from the property owner's counsel.

This Case is not scheduled to appear before the Board's Monday, January 11th meeting. Please see Attached and read email below and advise on how to proceed.

Thank you,

Belkys Garcia

City of Coral Gables **Development Services Department** 405 Biltmore Way, 3rd Floor Coral Gables, Florida 33134 Office: (305) 460-5229

From: John M.Thomson, P.A. [mailto:jmtlaw59@aol.com]

Sent: Wednesday, January 06, 2016 3:01 PM

To: Garcia, Belkys

Cc: alp@alp-law.com; 'Muir, William T.'; Goizueta, Virginia; Figueroa, Yaneris; Lopez, Manuel; Silio, Antonio

Subject: Coral Gables Post No. 98 American Legion, Inc ads City of Coral Gables, CAse No. 15-4406

On behalf of Post 98, as its Staff Judge Advocate, I hereby request to be allowed to appear before the administrative judge to ask for an extension of time to comply with the requirements of the Unsafe Structures Board for the reason that the installation of the illumination required by the 40 year or older recertification report filed with the City on November 11, 2015, Permit Number RC15-11-5548, is out for bid and cannot be accomplished until a licensed contractor can be employed to perform this task. The Post has sufficient funds to pay for this expense.

John M. Thomson, Esq. John M. Thomson, P.A. Suite 310 100 Almeria Avenue

Coral Gables, Florida 33134 Telephone: 305-443-5444 Facsimile: 305-443-4446

The information contained in this E-Mail, including any attachments, is confidential, intended only for the named recipient(s), and may be legally privileged. if you are not the intended recipient, please delete the E-Mail and any attachments, destroy any printouts that you may have made and notify us immediately by return E-Mail. Thank you.

From: Garcia, Belkys

**Sent:** Friday, January 08, 2016 1:57 PM

To: 'americanlegion98@aol.com'; 'ceva@aol.com'

Cc: Goizueta, Virginia, Figueroa, Yaneris, alp@alp-law.com

Subject: 301 Alhambra Circle Invoices

Attachments: Sent from the City of Coral Gables Development Services Department.pdf

### Good afternoon.

Per our conversation please see Attached Invoices. Please note there will be additional fees at time of permit issuance of the submitted plans for the parking lot lighting (#EL15125735). Those fees will be available once the completed Permit Application is completed and submitted to Plans Processing Division.

### Thank you,

Belkys Garcia City of Coral Gables Development Services Department 405 Biltmore Way, 3rd Floor Coral Gables, Florida 33134 Office: (305) 460-5229

----Original Message----

From: ds-pln@coralgables.com [mailto:ds-pln@coralgables.com]

Sent: Friday, January 08, 2016 1:31 PM

To: Garcia, Belkys

Subject: Sent from the City of Coral Gables Development Services Department

Please open the attached document. It was scanned and sent to you using a Xerox Multifunction Printer.

Attachment File Type: pdf, Multi-Page

Multifunction Printer Location: Device Name: CTHDS3FL-7970A

From:

John M.Thomson, P.A. <jmtlaw59@aol.com>

Sent:

Wednesday, February 10, 2016 4:14 PM

To:

colhms@coralgables.com

Cc:

americanlegion98@aol.com; Mendez, Madelaine; Garcia, Belkys; Figueroa, Yaneris;

alp@alp-law.com; mayor85@aol.com

Subject:

Fire INspection

### Chief

The fire inspection items to correct per the inspection dated January 25, 2016 have been fixed. An inspection can be scheduled by calling our Post Secretary at 305-400-8043. Please let me know if you have any problems in arranging for the inspection. I understand that this work was completed prior to the hearing before the Construction Regulation Board and the Fire Department had been notified, however, the message apparently had not reached you. Sorry for that.

Jack
John M. Thomson, Esq.
John M. Thomson, P.A.
Suite 310
100 Almeria Avenue
Coral Gables, Florida 33134
Telephone: 305-443-5444
Facsimile: 305-443-4446

The information contained in this E-Mail, including any attachments, is confidential, intended only for the named recipient(s), and may be legally privileged. If you are not the intended recipient, please delete the E-Mail and any attachments, destroy any printouts that you may have made and notify us immediately by return E-Mail. Thank you.

From:

Garcia, Belkys

Sent:

Wednesday, February 24, 2016 8:27 AM

To:

John M.Thomson, P.A. (jmtlaw59@aol.com)

Cc:

Goizueta, Virginia; Figueroa, Yaneris; alp@alp-law.com

Subject:

301 Alhambra Circle Case #15-4406

Attachments:

Sent from the City of Coral Gables Development Services Department.pdf

### Good morning,

Please note I am in receipt of the Attached paperwork that was hand-delivered to me yesterday afternoon. Thank you for the updated Fire Department Inspection Report. In the Board's Order, 5c, states the Board wants an update from the owner. Therefore, this Case will be scheduled for the April 11, 2016 Board meeting. Additionally, 5b, in the Order states a deadline of 15 days to obtain all permits. Note, that deadline is March 2, 2016.

### Thank you,

Belkys Garcia City of Coral Gables Development Services Department 405 Biltmore Way, 3rd Floor Coral Gables, Florida 33134 Office: (305) 460-5229

----Original Message-----

From: ds-pln@coralgables.com [mailto:ds-pln@coralgables.com]

Sent: Wednesday, February 24, 2016 7:49 AM

To: Garcia, Belkys

Subject: Sent from the City of Coral Gables Development Services Department

Please open the attached document. It was scanned and sent to you using a Xerox Multifunction Printer.

Attachment File Type: pdf, Multi-Page

Multifunction Printer Location: Device Name: CTHDS3FL-7970A

## LAW OFFICES JOHN M. THOMSON, P.A.

ATTORNEY AT LAW 100 ALMERIA AVENUE SUITE 310 CORAL GABLES (MIAMI), FLORIDA 33I34-6711

Robert M. Thomson (1898-1976) COL. John M. (Jack) Thomson (Florida Bar 1959)

TELEPHONE (305) 443-5444
TELEFAX (305) 443-4446
E-Mail: <u>JMTLAW59@aol.com</u>

February 23, 2016

Belkys Garcia
Secretary to Construction Regulation Board
Development Services Department
CITY OF CORAL GABLES
405 Biltmore Way - 3<sup>rd</sup> Floor
Coral Gables, Florida 33134

Re: CONSTRUCTION REGULATION BOARD

Case Number: 15-4406

Coral Gables Post No. 98 American

Legion, Inc.

Dear Miss Garcia:

Enclosed is a copy of the Coral Gables Fire Rescue/Inspection results, showing all violations were cleared as of February 18, 2016.

Will you please note, for the record, that Post 98 has submitted this evidence as part of its compliance report required by the Order entered February 16, 2016. I assume that Paragraph 5 (c) will no longer be in effect.

I have paid the administrative fee of \$150.00 to the City today.

Sincerely,

JOHN M. THOMSON

JMT:bes Enclosure

cc: American Legion Post 98
Toby Muir, Resident Agent

### John M.Thomson, P.A.

From:

Americanlegion98@aol.com

Sent:

Thursday, February 18, 2016 2:58 PM

To:

Jack Thomson

Cc:

Paul Kruger; Ceva

Subject: **Attachments:**  Fwd: Coral Gables Fire Rescue - Inspection Results

EmailReport\_50085\_2182016.pdf

----- Forwarded message -----

From: Inspector-NoReply@mobile-eyes.org

Date: Feb 18, 2016 2:09 PM

Subject: Coral Gables Fire Rescue - Inspection Results

To: americanlegion98@aol.com, <artangelica@bellsouth.net>, <bgarcia@coralgables.com>

Cc:

This automatic email contains a copy of your inspection and was sent to you by the Coral Gables Fire Prevention Bureau. If you have any questions or concerns please contact the Fire Prevention Bureau at (305) 460-5563.



### City of Coral Gables Fire Department

**Fire Prevention Division** 2815 Salzedo Street, Coral Gables, FL 33134 Fax (305) 460-5598

The items noted below are in violation of the Florida Fire Prevention Code and/or the Florida Administrative Code. Nothing in this report supersedes any previously written, still existing violations for this occupancy/building. You are directed to comply with corrective measures as indicated.

Occupant Name:

American Legion Post 98

Inspection Date:

1/25/2016, 2/18/2016

Address:

303 Alhambra Circle

InspectionType:

Business (Annual Fire Inspection)

City:

Coral Gables

Inspected By:

Madelaine Mendez 305-460-5563 mmendez@coralgables.com

Suite:

Occ. Sq. Ft.:

### **FL NFPA 01 13**

### Floor 1

### Fire alarms systems

13.7.1.4.3 Failure to maintain the fire alarm system.

Provide copy of fire alarm inspection and testing report

ox Violation cleared on 2/18/2016

### **Chapter 12 Features of Fire Protection**

12.3.3.2 Excerpt: Where required, fire-rated gypsum wallboard walls or ceilings that...

Where required, fire-rated gypsum wallboard walls or ceilings that are damaged to the extent that through openings exist, the damaged gypsum wallboard shall be replaced or returned to the required level of fire resistance using a listed repair system or using materials and methods equivalent to the original construction.

Cover all openings in ceiling throughout occupancy Note: 2nd floor and axillary room (ceiling openings)

ок Violation cleared on 2/18/2016

### **FL NFPA 101 13**

Floor 1

### **Blocked Exits**

### 4.5.3.2 Unobstructed Egress.

In every occupied building or structure, means of egress from all parts of the building shall be maintained free and unobstructed. Means of egress shall be accessible to the extent necessary to ensure reasonable safety for occupants having impaired mobility.

Exit in Storage room obstructed by Storage

ox Violation cleared on 2/18/2016

### Exit signs

7.10.6.2.1 Excerpt: Directional indicators, unless otherwise provided in 7.10.6.2.2, shall comply...

Exit Sign - - - cover chevron pointing to the wrong egress direction

OK Violation cleared on 2/18/2016

### **Hood systems**

### 9.2.3 Commercial Cooking Equipment.

Commercial cooking equipment shall be in accordance with NFPA 96, Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations, unless such installations are approved existing installations, which shall be permitted to be continued in service.

Provide copy of inspection report

ок Violation cleared on 2/18/2016

Inspector Comments: NOTE \*\*\*\*\* BUILDING HAS BEEN POSTED WITH A NOTICE OF HEARING ON NON-COMPLIANCE WITH UNSAFE STRUCTURES ORDER.... CASE NO 15-4406 DATED JANUARY 22, 2016 \*\*\*\*

Failure to correct violations within 15 days of re-inspection is subject to penalties up to and including the issuance of Civil Citations in the amount of \$200 per violation / per day.

Failure to provide immediate corrective measures when required, may result in administrative action including but not limited to: mandatory fire watch, building evacuation, or stoppage of all work.

Per City Ordinanace 30-4, a Fire Inspection Fee will be billed for this inspection. All fees are subject to change without prior notice.

Thank you for your assistance. If you have any additional questions or to schedule an inspection, please contact the inspector listed at the top of this report.

Signature on file

Company

Representative: Melissa Angelica

2/18/2016

Signature on file

Inspector:

Madelaine Mendez

2/18/2016

Signature on file

Company

Representative: Melissa Angelica

1/25/2016

Signature on file

Inspector:

Madelaine Mendez

1/25/2016

From: Garcia, Belkys

**Sent:** Tuesday, March 01, 2016 8:23 AM

To: 'John M.Thomson, P.A.'

Cc: Lopez, Manuel; Goizueta, Virginia; Figueroa, Yaneris; Silio, Antonio; americanlegion98

@aol.com

Subject: RE: Construction Regulation Board Case #15-4406, 301 Alhambra Circle

Attachments: RECORDED ORDER - FEB.pdf

### Good morning,

Please note the Subject Case cannot be closed until the property is in compliance. I have Attached the Board's Order which states all requirements and deadlines. This structure will be considered compliant once all required inspections have been approved, the permit is finaled, and a new submitted Recertification Report has been approved by the Building and Electrical Officials. Once all those requirements are completed a Building Recertification Letter will be issued and the Case can be closed.

As of this date, all requirements have not been met; therefore, this Case will continue to be scheduled for the April 11th Construction Regulation Board meeting for a status report as Ordered by the Board. Note, if deadlines are not met, fines can be imposed by the Board.

### Thank you,

### Belkys Garcia

City of Coral Gables
Development Services Department
405 Biltmore Way, 3rd Floor
Coral Gables, Florida 33134
Office: (305) 460-5229

From: John M.Thomson, P.A. [mailto:jmtlaw59@aol.com]

Sent: Monday, February 29, 2016 6:14 PM

To: Garcia, Belkys; Figueroa, Yaneris; alp@alp-law.com

Cc: americanlegion98@aol.com; Silio, Antonio

Subject: Construction Regulation Board case #15-4406, CG Post 98 Am Legion

### Dear Ms Garcia

A Notice of Commencement of the illumination contract work on the parking lot of the American Legion has been filed today and the city has issued a building permit for this work earlier today. The referenced case has been dismissed and the 40/90 year recertification filed with the city has been formally accepted. Therefore there will be no necessity for further reports to the Board and the hearing scheduled for April 11,2015 should be cancelled. Please verify that this has been done and that there are no pending fines or the potential of any fines against Post 98 at this time.

John M. Thomson, Esq. John M. Thomson, P.A. Suite 310 100 Almeria Avenue Coral Gables, Florida 33134 Telephone: 305-443-5444 Facsimile: 305-443-4446

The information contained in this E-Mail, including any attachments, is confidential, intended only for the named recipient(s), and may be legally privileged. If you are not the intended recipient, please delete the E-Mail and any attachments, destroy any printouts that you may have made and notify us immediately by return E-Mail. Thank you.



THOMAS T. COOPER

November 11, 2015

Building Official
City of Coral Gables Building Department
40-Year Recertification Section

RE: Building Recertification

Folio # 03-4108-006-2430 American Legion Post No. 98.

301-303-305 Alhambra Circle, Coral Gables, FL 33114

Dear Building Official:

We have been retained by the American Legion Post No. 98 to perform the required building recertification for the above referenced property.

Enclosed is the completed report for the required structural inspection.

Please be advised that we have found the building to be in good condition and to be structurally safe for its present use.

As a routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure. To the best of my knowledge and belief, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible.

It is our recommendation that this building be granted recertification for continued use under its present occupancy. Please do not hesitate to contact this office should you have any questions.

Sincerely,

Thomas T. Cooper, AIA

Reg. No. 0004486

TTC (w/enclosures)

cc: Art Angelina, Post Commander

CITY'S EXHIBIT





### DEPARTMENT OF REGULATORY AND ECONOMIC RESOURCES

## MINIMUM INSPECTION PROCEDURAL GUIDELINES FOR BUILDING STRUCTURAL RECERTIFICATION

INSPECTION COMMENCED

DATE: 11/06/15

INSPECTION COMPLETED

DATE: 11/06/15

INSPECTION MADE BY:

SIGNATURE:

PRINT NAME: Thomas T. Cooper

TITLE: Architect

ADDRESS: Thomas T. Cooper, AIA

THOMAS T. COOPER, ARCHITECT

AR # 0004486 4498 NE Skyline Drive Jensen Beach, FL 34957 Tel. (305) 667-2009 thomastcooper@gmail.com

### DESCRIPTION OF STRUCTURE

- a. Name or Title: American Legion Post No. 98.
- b. Street address: 301-303-305 Alhambra Circle, Coral Gables, FL 33114-0224
- c. Legal description: Coral Gables Sec X PB 8, page 33, Lots 23 & 24 & E 6 feet of Lot 22 & Lots 25 to 28 inc. block 26.
- d. Owner's name: American Legion Post No. 98.
- e. Owner's mailing address: P. O. Box 224, Coral Gables, FL 33114-0224
- f. Building official folio number: 03-4108-006-2430
- g. Building code occupancy classification: 0042 Liberal Commercial.
- h. Present use: Private Veteran's Club or Hall and doctor's office.
- i. General description, type of construction, size, number of stories and special features. One and two story 7,683 square foot concrete block structure built in 1924 with wood joist and wood floor on second level and flat built-up roof and sloped terra cotta tile roof over poured concrete slab, lot size 15,600 square feet, built in 1924. (See photographs)
- j. Additions to original structure: Unknown

THOMAS T. COOPER, ARCHITECT-AR # 0004486-4498 NE Skyline Drive, Jensen Beach, FL 34957-Tel. (305) 667-2009 <a href="mailto:thomastcooper@gmail.com">thomastcooper@gmail.com</a>

Page 2 of 6 11/11/15

### 2. PRESENT CONDITION OF STRUCTURE

- a. General alignment (note good, fair, poor, explain if significant). General alignment is good.
- b. Portions showing distress (note beams, columns, structural walls, floors, roofs, other). None of the major structural systems showed distress that would be of concern.
- c. Surface conditions describe general conditions of finishes, noting cracking, spalling, peeling, signs of moisture penetration & stains. No major cracking or spalling was observered. Only signs of water penetration were old and had been repaired. (See photographs #1 and #2)
- d. Cracks note location in significant members. Identify crack size as HAIRLINE if barely discernable; FINE if less than 1 mm in width; MEDIUM if between 1 and 2 mm in width; WIDE if over 2 mm. The only cracks noticed were on one exterior wall and they would be classified as hairline to fine. From the layers of paint they were probably 20 years old plus and of no immediate concern.
- e. General extent of deterioration cracking or spalling of concrete or masonry; oxidation of metals; rot or borer attack in wood. The primary structural materials concrete block and wood joist and poured concrete decks appeared to be in very good condition. (See photographs)
- f. Previous patching in wood. No patching but termite evidence in wood members in rear parking area. No active termites were observed. Existing voids average 1/8" deep or less. No penetration from probe in all members tested. Many of the wood members appear to be South Florida Dade County Pine. (See photographs #4 and #5)
- Nature of present loading indicate residential, commercial, other estimate magnitude. Commercial-Assembly loading.
- h. Availability of original construction drawings location description. Not available.

### 3. INSPECTIONS

- a. Date of notice of required inspection. April 1, 2014
- b. Date (s) of actual inspection. November 6, 2015
- Name and qualification of individual submitting inspection report. Thomas T. Cooper, Architect.
- d. Description of any laboratory or other formal testing, if required, rather than manual or visual procedures: **None**
- e. Structural repair note appropriate line: None noted.
  - 1. One required.
  - 2. Require (describe and indicate acceptance).

Jehoma J. Com

THOMAS T. COOPER, ARCHITECT-AR # 0004486-4498 NE Skyline Drive, Jensen Beach, FL 34957-Tel. (305) 667-2009 <a href="mailto:thomastcooper@gmail.com">thomastcooper@gmail.com</a>

Page 3 of 6 11/11/15

### 4 SUPPORTING DATA

- Sheets written data, NA
- b. Photographs. See attached (See photographs #1 through #10).
- c. Drawings or sketches. NA

### 5. MASONRY BEARING WALLS — indicate good, fair, poor on appropriate lines:

- a. Concrete masonry units. Good (See photograph #6)
- b. Clay tile or terracotta units. Good
- Reinforced concrete tie columns. NA
- d. Reinforced concrete tie beams. NA
- e. Lintels, Good
- f. Other type bond beams. NA
- g. Masonry finishes exterior:
  - 1. Stucco. Good to fair
  - 2. Veneer. Applied stone good (See photograph #1)
  - 3. Paint only. Good (See photograph #2)
  - 4. Other (describe). NA
- h. Masonry finished interior:
  - 1. Vapor barrier. NA
  - Furring and plaster. Good
  - 3. Paneling. Good
  - 4. Paint only. Good to fair
  - 5. Other (describe). Tile good
- i. Cracks:

Thomas J. Com

THOMAS T. COOPER, ARCHITECT-AR # 0004486-4498 NE Skyline Drive, Jensen Beach, FL 34957-Tel. (305) 667-2009 thomastcooper@gmail.com

### Page 4 of 6 11/11/15

- 1. Location note beams, columns, other. None noted.
- 2. Description. NA
- j. Spalling:
  - 1. Location note beams, columns, other. None noted. (See photographs #6 and #7)
  - 2. Description, NA
- Rebar corrosion check appropriate line: None noted.
  - None visible, X
  - 2. Minor Patching will suffice.
  - 3. Significant but patching will suffice.
  - Significant structural repairs required (describe).
- Samples chipped out for examination in spall areas: None required.
  - 1. No. X
  - Yes describe color, texture, aggregate, general quality.

### 6. FLOOR AND ROOF SYSTEMS

- a. Roof. 2" x 10" Dade County Pine joists at 24" o.c. with t & g decking over second floor. Poured concrete roof slab in good condition over assembly spaces below on first floor. (See photographs) (See photographs #4, #5, #6, #7 and #8)
- b. Floor system (s): First floor is slab-on-grade with tile or terrazzo over. Second floor is wood joist with wood flooring.
- c. Inspection Note-exposed areas available for inspection and where it was necessary to open ceilings, etc. for inspection of typical members. Acoustical tiles were lifted on the first floor ceiling to view the concrete slab roof structural system. Two access hatches on the second floor attic space were open to view the wood roof structural system.

### STEEL FRAMING SYSTEMS

- Description, NA
- Exposed steel describe condition of paint and degree of corrosion: NA
- c. Concrete or other fireproofing note any cracking or spalling, and note where any covering was removed for inspection. NA
- d. Elevator sheave beams & connections, and machine floor beams note condition: N

THOMAS T. COOPER, ARCHITECT-AR # 0004486-4498 NE Skyline Drive, Jensen Beach, FL 34957-Tel. (305) 667-2009 thomastcooper@gmail.com

Page 5 of 6 11/11/15

### 8. CONCRETE FRAMING SYSTEMS

- a. Full description of structural system. Poured Concrete roof slab in good condition (See photographs #6 and #7)
- b. Cracking: None observed
  - 1. Not significant.
  - 2. Location and description of members effected and type cracking.
- General condition, Good
- Rebar corrosion check appropriate line.
  - 1. None visible X
  - 2. Minor Patching will suffice
  - 3. Significant but patching will suffice
  - Significant structural repair (describe).
- e. Samples chipped out in spall areas: NA
  - 1. No X
  - 2. Yes describe color, texture, aggregate, general quality:

### 9. WINDOWS

- a. Type (wood, steel, aluminum, jalousie, single hung, double hung, casement, awning, pivoted, fixed, other).

  Aluminum awning and steel fixed windows. (See photograph #1, #2, #9 and #10)
- b. Anchorage type and condition of fasteners and latches: Screw anchors in jamb, sill and head in good condition. (See photographs #9 and #10)
- Sealants type and condition of perimeter and sealants & at mullions: Rubber and silicone in fair condition.
- d. Interior seals type & condition at operable vents: NA
- e. General condition: Good to fair.

Thomas J. Coegn

## MINIMUM INSPECTION PROCEDURAL GUIDELINES FOR AMERICAN LEGION POST No. 98. BUILDING STRUCTURAL RECERTIFICATION-2015

THOMAS T. COOPER, ARCHITECT-AR # 0004486-4498 NE Skyline Drive, Jensen Beach, FL 34957-Tel. (305) 667-2009 <a href="mailto:thomastcooper@gmail.com">thomastcooper@gmail.com</a>

Page 6 of 6 11/11/15

#### WOOD FRAMING

- a. Type fully describe mill construction, light construction, major spans, and trusses: Floor and roof construction of Dade County pine joist and 6 inch tongue and groove decking in good condition. The previous termite damage of the wood joist and beams in parking courtyard appear to be sound. Approximately 30 plus probes of the wood members were made. All wood appeared to be strong and dense. (See photographs #4, #5 and #8)
- b. Note metal fittings i.e., angles, plates, bolts, split rings, pintles, other and note condition: All observered attachments were as per acceptable building practices of 1924. All wood structural members were toe nailed together for attachment and support.
- c. Joists note if well fitted and still closed: All observered joists were well fitted.
- d. Drainage note accumulations of moisture: No accumulation of moisture.
- e. Ventilation note any concealed spaces not ventilated: All spaces appeared ventilated.
- f. Note any concealed spaces opened for inspection: All spaces were accessible.

As a routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible.

Thomas T. Cooper #0004486

Date



### **American Legion Post No. 98 Photographs**



Photograph #1 of Dr.'s Office

entrance with stucco and applied stone over CBS.



Photograph #2 of south wall of

Legion Post #98 with stucco over CBS.

Thomas J. Cope # 4486 NOV. 11, 2015

### MINIMUM INSPECTION PROCEDURAL GUIDELINES FOR AMERICAN LEGION POST No. 98. BUILDING STRUCTURAL RECERTIFICATION-2015 Photographs

THOMAS T. COOPER, ARCHITECT-AR # 0004486-4498 NE Skyline Drive, Jensen Beach, FL 34957-Tel. (305) 667-2009 <a href="mailto:thomastcooper@gmail.com">thomastcooper@gmail.com</a>

Page 2 of 4 11/10/15



Photograph #3 of Parking

Courtyard at rear of building.



Photograph # 4 of wood joist,

decking and beam at Parking Courtyard roof.



Photograph #5 of previous termite damage at Parking Courtyard Shelter roof joist and deck.

## MINIMUM INSPECTION PROCEDURAL GUIDELINES FOR AMERICAN LEGION POST No. 98. BUILDING STRUCTURAL RECERTIFICATION-2015 Photographs

THOMAS T. COOPER, ARCHITECT-AR # 0004486-4498 NE Skyline Drive, Jensen Beach, FL 34957-Tel. (305) 667-2009 thomastcooper@gmail.com

Page 3 of 4 11/10/15



Photograph #6 of

underside of concrete slab over main meeting hall first floor roof south wall.



Photograph #7 underside

of concrete slab over main meeting hall first floor roof looking north.



Photograph #8 of wood structure at second floor roof.

Thomas J. Com

# MINIMUM INSPECTION PROCEDURAL GUIDELINES FOR AMERICAN LEGION POST No. 98. BUILDING STRUCTURAL RECERTIFICATION-2015 Photographs

THOMAS T. COOPER, ARCHITECT-AR # 0004486-4498 NE Skyline Drive, Jensen Beach, FL 34957-Tel. (305) 667-2009 thomastcooper@gmail.com

Page 4 of 4 11/10/15



Photograph #9 of aluminum awning

window in Legion Hall south wall.



Photograph #10 of

attachments in aluminum awning window in Legion Hall south wall.

Thomas J. Com

#### CITY OF CORAL GABLES



#### CODE ENFORCEMENT DIVISION

427 Biltmore Way, Suite 100

Case #: CE261560-110915

#### Notice of Violation

AMERICAN LEGION POST NO 98 PO BOX 224 CORAL GABLES FL 331140224

Folio #: 0341080062430

Dear Property Owner and/or Occupant:

This letter constitutes a notice that a violation(s) exists on the premises at 301 ALHAMBRA CIR, Coral Gables, FL.

The violation(s) found was:

#### Violations:

· Violation of Coral Gables City Code.

Code Enforcement Officer Comments: Violation of 8-11 of the Miami-Dade County Code, as applicable in the City, and of Section 105-186(j)(13) as adopted in City Ordinance 2015-18, by falling to complete the recertification process for the structure.

The following steps should be taken to correct the violation:

Velule

Remedy: Apply for and obtain a recertification letter, including, but not limited to, by submitting a recertification report and applying for, obtaining, and passing final inspection on all permits required to correct any deficiencies noted the report, and submitting a compliance report.

The regulations enforced by the City have been adopted in order to protect the public and assure continuing high property values. Your immediate attention to correcting the violation(s) listed above is required.

The Code Enforcement Division will re-inspect the property on 12/9/2015 to determine if corrective measures have been completed. If the violation(s) has not been corrected at the time of inspection, your case will be presented to the Code Enforcement Board for review and possible action. At that time, you will have the opportunity to explain to the citizens serving on the Board the reasons why the violation(s) has not been corrected. The Board has the authority to assess a fine against you for as long as the violation continues.

The Division is available for consultation on this matter from 7:30 AM to 4:00 PM. Please do not hesitate to call the Code Enforcement Officer below for additional assistance.

Martha Delgado

Code Enforcement Officer

305 460-5325

mdelgado@coralgables.com



# TCAPA CONSULTING ENGINEERS VA. DRA Florida Comparation

FL:CA-7055, GA, TN, VA DBA Florida Corporation tcarmstrong@tcapa.com

T:305-598-4030 F:/33 C: 305-205-2900

#### **40-YEAR ELECTRICAL RE-CERTIFICATION**

# **American Legion Post 98**

301-303 Alhambra Circle Coral Gables, Florida 33134-5003

FOLIO # 03-4108-006-2430



Tomas C. Armstrong, P.E. November 17, 2015







#### **CONSULTING ENGINEERS**

FL:CA-7055, GA, TN, VA tcarmstrong@tcapa.com

**DBA Florida Corporation** 

T:305-598-4030 F:/33

C 305-205-2900

November 17, 2015

TO:

Chief Electrical Inspector **Building Department** 40 year Building Recertification Section

Matter:

40-year Inspection Electrical Recertification letter.

Reference:

American Legion Post # 98

Address:

301-303 Alhambra Circle, Coral Gables, Florida 33134-5003

FOLIO#

03-4108-006-2430

#### **ELECTRICAL CERTIFICATION LETTER**

Dear Chief Electrical Inspector:

During the period ending on November 16, 2015 I conducted electrical inspections on the above referenced building for compliance with the 40-year certification requirements. See attached Report.

I have found the electrical system in the building to be in good condition and therefore I recommend that the building be re-certified and that the City take this action. As per the 40-year electrical inspection, this building is electrically safe for continued use and continued occupancy.

#### ILLUMINATION

On 11-16-2015 I conducted a night survey and photometric readings on the parking lot to the west of the building and found it very dark and not in compliance with M-D 8C-3.

#### **PARKING LOT#1**

PARKING LOT #1 is the parking lot on the north side and adjacent to the building with an overhang where the automobiles park under the overhang. The photometric night survey found that THIS AREA COMPLIES with Miami-Dade Code Section 8C-3. Refer to the Illumination Certification Form included.

#### PARKING LOT # 2

PARKING LOT # 2 is an independent parking lot, to the north of the building but separated from the building by an alley. There is no private luminaire covering this parking lot. The photometric night survey found that this area DOES NOT COMPLY with Miami-Dade Code Section 8C-3. Refer to the Illumination Certification Form included.

See attached Miami-Dade form on Parking Lot Illumination

Tomas C. Armstrong, F

President **TCAPA** 

PE# 17974

OM

7990 S.W. 117th Ave., Suite 140 • Miami, Florida 33183



TCAPA Consulting Engineers- CA # 7055 7990 S.W.117 Ave,S-140, Miami, FL 33183 Tel 305-598-4030 Fax /33 Cell: 305-205-2900 TOMAS C. ARMSTRONG P.E.# 17974 DATE 11-17-2015







#### **CONSULTING ENGINEERS**

tcarmstrong@jcapa.com

FL:CA-7055, GA. TN. VA DBA Florida Corporation

T:305-598-4030 F:/33 C. 305-205-2900



#### DEPARTMENT OF REGULATORY AND ECONOMIC RESOURCES

CERTIFICATION OF COMPLIANCE WITH PARKING LOT GUARDRAILS REQUIREMENTS IN CHAPTER 8C OF THE CODE OF MIAMI-DADE COUNTY

Date: 08-03 2015

RE:

Case No.:

Property Address: 301-303 Alhambra Circle, Coral Gables, Florida 33134-5003

Folio # 03-4108-006-2430

Building Description: Two story American Legion Hall & office + one story single

tenant

The undersigned states the following:

I am a Florida registered professional engineer or architect with an active license.

On November 16, 2015 I inspected the seven parking lots servicing the above referenced buildings for compliance with Section 8C-6 and determined the following (check only one):

The parking lot in the building property is not adjacent to or abutting a canal, lake or other body X of water.

The parking lot(s) is adjacent to or abutting a canal, lake or other body of water and parked vehicles are protected by a guardrail that complies with Section 8C-6 of the Miami-Dade County Code. (\*)

The parking lot(s) is adjacent to or abutting a canal, lake or other body of water and parked vehicles are not protected by a quardrail that complies with Section 8C-6 of the Miami-Dade County Code. I have advised the property owner that he/she must obtain a permit for the installation of the guardrail and obtain all required inspection approvals to avoid enforcement action.

Signature and Seal of Engineer

Tomas C. Armstrong, P. E. PE#17974 Print Name



Tomas C. Armstrong, P.E., LEED GA Plorida, «Georgia, «Tennesses, «Virginia

TCAPA Consulting Engineers CA-7055 7950 SW 117<sup>th</sup> Ave., 3-140, Milmil, Florids 3318; T: 305-588-4030 F:3 05-588-4033 C: 205-305-3900 tcarmstrong@tcapa.com

#### Note:

When Guardrails are present and as an electrical engineer I can only certify, by visual observations, that there is indeed a Guardrail installed protecting the parking vehicles and that the Guardrail appears to be, on visual observation, in fair condition with no section in disrepair. Structural observations and structural certification are not part of this report.







#### CONSULTING ENGINEERS

FL:CA-7055, GA, TN, VA DBA Florida Corporation tcarmstrong@tcapa.com

T:305-598-4030 F:/33 C. 305-205-2900



#### DEPARTMENT OF REGULATORY AND ECONOMIC RESOURCES

CERTIFICATION OF COMPLIANCE WITH PARKING LOT ILLUMINATION STANDARDS IN CHAPTER 8C OF THE CODE OF MIAMI-DADE COUNTY

Date: 11-17-2015

Case Number:

Property Address: 301-303 Alhambra Circle, Coral Gables, Florida 33134-5003

Folio Number 03-4108-006-2430

Building Description: Two story Hall & Office + one story single tenant

- 1.-I am a Florida registered professional engineer or architect with an active license.
- On 11-16-2015 I measured the level of illumination in the two independent parking lots serving the 2.above reference building.

PARKING LOT # 1 (UNDER THE PARTIAL CANOPY AND AJACENT TO THE BUILDING)

- Maximum 6.4 foot candle per SF, Minimum 1.2 foot candle per SF, Minimum to Maximum ratio 5.3 and 3.8 foot candle average per SF.
- 4A.-The level of illumination provided in the parking lot (s) meets / does not meet the minimum standards for the occupancy classification of the building as established in Section 8C-3 of the Code of Miami-Dade County.

Complies with M-D 8C-3 Does NOT Comply with M-D 8C-3

PARKING LOT # 2 (SEPARATED FROM THE BUILDING AND ACROSS THE ALLEY)

- Maximum 0.3 foot candle per SF, Minimum 0.0 foot candle per SF, Minimum to Maximum ratio N/A and N/A foot candle average per SF.
- The level of illumination provided in the parking lot (s) meets / does not meet the minimum standards 4Bfor the occupancy classification of the building as established in Section 8C-3 of the Code of Miami-Dade County.

Complies with M-D 8C-3

Does NOT Comply with M-D 8C-3

No 17974

STATE OF

ORIDA

Chapter 8C of the Miami-Dade County Code sec Signature and Seal or Engineer Tomas C. Armstrong, P. E.

**Print Name** 

Tomas C. Armstrong, P.E., LEED GA
• Florida, • Georgia, • Tennessee, • Virginia TCAPA Consulting Engineers CA-7055 7890 SW 117" Ave. 3-140, Blami, Florida 33183 T: 305-698-4030 F:3 06-688-4032 C: 306-206-2900

tcarmstrong@tcapa.com

Note: To comply with Chapter 8C of the Miami-Dade County Code section 8C-3 the Illumination data was obtained at night using a calibrated extech Light Meter model # 40/026 mounted on a mobile Light Rover specially built for this purpose. The Maximum, Minimum and Average illumination reading were obtained by switching the Extect Light Meter to RECORD mode, scan the parking for recording the illumination at grade level, and then switch the meter to RECALL to read the recorded illumination levels for Max, Min and Average. Also, when possible, with the meter in SINGLE mode I verify that the overspill of illumination levels onto adjacent properties does not exceed the 0.5 foot-candle horizontal illumination at grade level.



PE#17974





#### MINIMUM INSPECTION PROCEDURAL GUIDELINES FOR BUILDING'S ELECTRICAL RECERTIFICATION

INSPECTION COMMENCED

INSPECTION COMPLETED

Date:

Date:

11-07-2015

11-17-2015

PRINT NAME:

SIGNATURE:

TITLE:

Tomas C. Armstrong, P.E.

Professional Engineer

INSPECTION MADE BY: Tomas C. Armstrong, P.E.

ADDRESS:

TCAPA Consulting Engineers - CA # 7655 7990 N.W. 191 Ave., S-140, Miami, FL 33183 Tel 3055 568-4030 Fax /33 Cell: 305-205-2900 JOMAS C. ARMSTRONG, P.E.# 17974 &GA,TN,VA DATE 11-17-2015

#### **DESCRIPTION OF STRUCTURE**

Name of Title: American Legion Post # 98

Street Address: 301-303 Alhambra Circle, Coral Gables, Florida 33134-5003 b-.

Legal Description: CORAL GABLES SEC X PB 8-33 LOTS 23 & 24 & E6FT OF LOT 22 & C.-

LOTS 25 TO 28 INC BLK 26 LOT SIZE IRREGULAR

Owners Name: d.-American Legion Post # 98

Owners Mailing Address: PO BOX 224, CORAL GABLES, FL 33114-0224 e.-

03-4108-006-2430 f.-Folio Number or Property on which Building is Located:

**Building Area**; 7,683 Sq. Ft g-

Floors: 2 h.-

i.-Living Units: 0

j.-Building Code Occupancy 6600 COMMERCIAL - LIBERAL

Present Use: Residential 7742 BENEVOLENT - EXEMPT : CLUB OR HALL - PRIVATE k.-

General Description, Type of Construction, Size, Number of Stories, and Special Features



Tel (305) 598-4030 Fey 305-598-4033 TOMAS C. ARMSTRONG P.E.# 17974 DATE: 11-17-2015







#### **BULDING- AMERICAN LEGION POST #98**



#### **301 TENANT**





TCAPA Consulting Engineers- CA + 1055 7990 S.W.117 Ave., S-140, Miemi, FL 33183 Tel (305) 598-4030 Fax 305-598-4033 TOMAS C. ARMSTRONG P.E.# 17974 DATE: 11-17-2015





#### **ADDITIONAL COMMENTS**

#### BUILDING

#### American Legion # 98 area

The building is situated the northwest corner of the intersection of Alhambra Circle and Salzedo St... Coral Gables. Large part of the building is occupied by the American Legion # 98. There is a parking lot on the north side of the building with an overhang where the automobiles park under the overhang. The Main Entrance to the American Legion # 98 space is from the parking lot on the north side.

#### Fernando Hernandez MD tenant area.


Small tenant area is occupied by the medical office of Fernando Hernandez MD. The Main Entrance to the medical office of Fernando Hernandez MD space is from the south side of the building by Alhambra Circle.

#### **PARKING LOTS**

Parking Lot #1 is the parking lot on the north side and adjacent to the building with an overhang where the automobiles park under the overhang

Parking lot # 2 is an independent parking lot, to the north of the building but separated from the building by an alley.





Tel (305) 598-4830 Fey 305-598 TOMAS C. ARMSTRONG P.E.# 17974

DATE: 11-17-2015





# GUIDELINES AND INFORMATION FOR RECERTIFICATION OF ELECTRICAL SYSTEMS OF FORTY (40) YEAR STRUCTURES

3. Cc	ondition:	Good	(	X	)	Fair	(	<b>X</b> )	Needs Repair	(	)	
2. Ph	nase:	Three Phase	(	X	)	Single Phase	(	<b>X</b> )		(	)	
1. Si	ze	Amperage	22	25 + 20	200+ 0	Fuses	(	)	Breakers	( )	( )	
1. E	ELECTRIC	SERVICE										

#### 3. Comments:

#### **ELECTRIC SERVICE FOR AMERICAN LEGION #98**

#### **AERIAL SERVICE**

The FPL aerial service originates at the FPL Pole Transformer at the northwest corner of the building. The service is aerial to the west side wall. See photos 03 & 04. The FPL aerial service connects to the Service Conductors at the Weather Head. See photos 05 & 06. The vertical Mast Conduit is securely attached to the wall. See photo 06.

The FPL aerial service, the Service Entrance, the Weather Head and the vertical Mast conduit appeared in good condition.

The Meter appeared to be a double lug meter.

- 1.- The first lateral service is run from the Meter to the 120v/208v 3\psi-225a exterior mounted NEMA 3R Main Breaker 1 of 2 (installed next to the Meter). See photo 07,11 & 12
- 2.- The second lateral service is run from the Meter to the 120v/208v 1φ-200a interior Main Panel B installed on the north wall next to the entry door and labeled Main 2 of 2 because it contains a 120v/208v 200a 1φ Main Breaker 2/2. See photos 42 & 43

#### ELECTRIC SERVICE FOR FERNANDO HERNANDEZ MD MEDICAL OFFICE.

#### **AERIAL SERVICE**

This service is totally separated and independent from the American Legion aerial service

The FPL service also originates at the FPL Pole Transformer at the northwest comer of the building but the service is to the north side of the tenant wall. See photo 72. The FPL aerial service connects to the Service Conductors at the Weather Head. The vertical Mast Conduit protrudes above the roof and it is securely attached to the wall. See photo 72. The FPL aerial service, the Service Entrance, the Weather Head and the vertical Mast conduit appeared in good condition.

The service is 120/208 16 200 amp

The vertical Service Conduit terminates at the FPL meter and then into a Main Electrical Panel with 6 Main Breakers. This Main Electrical Panel is used to power A/C units and a Main Breaker that serves an exterior Sub-Panel which powers the medical office.

#### Conclusion

The electrical Service Entrance or the American Legion # 98 and for Fernando Hernandez MD medical office appeared in good condition.

I ne electrical Service Entrance or office appeared in good condition.

CENS

No 17974

STATE OF

ORIONALEMAN

TCAPA

Consulting Engineers- CA = 7055
7990 S.W.117 Ava., S. 140, Miami, FL 33183
Tol (305) 598-4030 Fax 305-598-4033
TOMAS C. ARMSTRONG P.E.N 17974
DATE: 11-17-2015






2. METER	AND E	LECTRIC	CRO	OOM									
1. Clearance	es:	Good	(	<b>X</b> )	Fair	r (	)	)	Requ	ires Correction	(	)	
2. Commen	ts:												
There are N	O meter	room or e	electr	ical r	rooms								
are run, one the other or 12. EL	Service to an expect to Pan  ECTRIC Service	Conduit t exterior 36- el B, insid METER A Conduit	ermine 2258 de the the the the the the the the the th	nates a Ma e ter	s at the e in Breake nant area	exterio er 1/1 which	r FP NEM 1 con	L mel IA 3R Itains	er. From Mein	CAN LEGION #98 om the Meter two nted on the outside Breaker 2/2/. See MD MEDICAL OF d into an exterior	servi e we: phot FICI	st wa o 07 E.	all and , 11 &
and has a N	lain Brea	ker that s	erve	s an	exterior (	Sub-P	anel,	also	moun	Panel is used to p ted on the north ex rs the medical offi	derio	r wa	II. The
3. GUTTE	RS		1099			0000							
Location:	A/C	Gutter on	the e	exter	ior wall		Good	l (	<b>X</b> )	Requires Repa	air	(	)
Taps and Fi	il: See	Photos 1	28.	18			Good	•	<b>X</b> )	Requires Repa		(	)
Comments		1 110103 1	_,~							requires repr			
		PANELS		e Mai	in Breake	er for /	Amer	ican l	egion.	was in good cond	dition		
Panel # A					Locatio	n: /	mer	ican	Legio	n ground floor Bac	k roc	om	
See Photos	28, 29,	30,31, 32	, 33			Good:		<b>X</b> )		Needs Repa		(	)
Panel # B The Panel is	s labeled	Main 2 o	f 2 b	ecau	se it cont		he 20			North Wall eaker 2/2 Needs Repa		(	\
										•			
Sub-Panel					- 1				egion	2 <sup>nd</sup> floor storage re			,
See Photos No.	CENS	*			_	5		7990 : Tel (3 TOM/	uiting Eng S.W.117 A 05) 598-41	Needs Repairment of the state o	LE	ED	)

Main Panel with 6 Main di										_
See Photos <b>73,74,7</b> 5			Good:	( )	K )			Needs Repair	(	
Sub-Panel # A Connected to Panel A/C a		n: Dr. Herr	nandez N	<b>AD</b> me	edica	offic	e out	tside back wall		
See Photos 73,74,75			Good:	( )	K )			Needs Repair	(	)
2. Panel Comments:										
The cover of the par circuits appeared in connected. Panels ap	good condition	n. Conduc	tors insi							
5. BRANCH CIRC	UITS:									Mary I
1. Identified:				Y	es	( X	)	Must be identified	(	)
2. Conductors:	Good	( X )	Deter	riorate	ed	(	1)	Must be replaced	(	)
3. Comments:										
The removal of the co	-	es and rec					nch c	ircuits in fair conditio	n.	2 ==
The removal of the co	overs of switch	es and rec		s sho	wed			ircuits in fair conditio		)
The removal of the co	overs of switch	es and rec	eptacles	s sho	wed	bran				)
The removal of the co	ERVICE FOR To been grounded by 08, 09, 10  ERVICE FOR Its been grounded by 08, 09, 10	THE AME ed at the F DR. HERN ed at the e	Goo RICAN PL Mete ANDEZ xterior N	od LEGI er. Gi	( ON:	bran  X )  #98 : ding	SER via 2	Repairs Required  VICE ENTRANCE  grounding electrode	( e and	to the

Condition:	Good	(	X	)	Repairs Required	(	)
Comments:				•			
The Main Service Switchgear conductors. The feeders to the photos 17 29 & 33							
B. SERVICE CONDUITS/F	RACEWAYS						
Condition:	Good	(	X	)	Repairs Required	(	)
Comments:			- 24				-
The vertical <b>Service Conduit</b> American Legion or from the \ Breakers for Dr. Hernandez ap	Neather Head to the Meter						
9. SERVICE CONDUCTOR	RS AND CABLES			M.			
	Good	(	X	)	Repairs Required	(	)
Comments:				-			
The Service Conductors from American Legion is a short of appeared in good condition  The Service Conductors from serving the American Legion a	istance because the Brea m the double lug Meter t	ker	is i	nstall	ed next the double lug	Me	ter. I
American Legion is a short of appeared in good condition  The Service Conductors from serving the American Legion a  The Service Conductors from	in the double lug Meter to the Breat to the weather Head to the	ker o th Me	is i e N	nstall	ed next the double lug	g Me	ter. I
American Legion is a short of appeared in good condition  The Service Conductors from serving the American Legion at the Service Conductors from Main Breakers for Dr. Hernand	in the double lug Meter to the ppeared in good condition the Weather Head to the lez appeared in good condition	ker o th Me	is i e N	nstall	ed next the double lug	g Me	ter. I
American Legion is a short of appeared in good condition  The Service Conductors from serving the American Legion at The Service Conductors from Main Breakers for Dr. Hernand 10. TYPE OF WIRING ME	in the double lug Meter to the ppeared in good condition the Weather Head to the lez appeared in good condition	ker o th Me	is i e N	nstall	ed next the double lug	g Me	ter. I
American Legion is a short of appeared in good condition  The Service Conductors from serving the American Legion at The Service Conductors from Main Breakers for Dr. Hernand 10. TYPE OF WIRING ME	m the double lug Meter to the ppeared in good condition on the Weather Head to the lez appeared in good condition.	ker o th Me	is i	nstall	ed next the double lug Breaker 2/2 inside Par the Main Electrical Pa	g Me	ter. I
American Legion is a short of appeared in good condition  The Service Conductors from serving the American Legion at the Service Conductors from Main Breakers for Dr. Hernand Main Breakers for Dr. Hernand Conduit Raceways:  Conduit PVC:	in the double lug Meter to ppeared in good condition in the Weather Head to the lez appeared in good condition.  THODS:	ker o th Me	is i	nstall	Breaker 2/2 inside Particular Par	g Me	ter. I
American Legion is a short of appeared in good condition  The Service Conductors from serving the American Legion at the Service Conductors from Main Breakers for Dr. Hernand Main Breakers for Dr. Hernand Conduit Raceways:  Conduit PVC:  NM Cable:	in the double lug Meter to the ppeared in good condition in the Weather Head to the lez appeared in good condition.  THODS:  Good Good	ker o th Me	is i	nstall	Breaker 2/2 inside Par the Main Electrical Par Repairs Required Repairs Required	g Me	ter. I
American Legion is a short of appeared in good condition  The Service Conductors from serving the American Legion at the Service Conductors from Main Breakers for Dr. Hernand	m the double lug Meter to ppeared in good condition on the Weather Head to the lez appeared in good condition.  THODS:  Good Good Good	ker o th Me	is i	nstall	Breaker 2/2 inside Par the Main Electrical Par Repairs Required Repairs Required Repairs Required	g Me	ter. I

	41.1	0		<i>-</i> 1		Dennim Denvired	,		
	dition:	Good	- (	<b>X</b> )		Repairs Required	(	_	,
Com	ments:							_	
This	Feeder Conductors from the Main D condition was observed when the conditions 29, 30 33	isconnects to the overs of Panels w	tena ere	ent I rem	Panel loved	s appeared in fair cond	ditio	n.	
12.	EMERGENCY LIGHTING						191		7.59
Con	dition:	Good	(	X	)	Repairs Required	(	X	)
Con	nments:	2							
13.	BUILDING EGRESS ILLUMINA	ATION					WICE VOICE		
Con	dition:	Good	(	)		Repairs Required	(	X	)
Соп	nments:	2000							
Both	n areas, the American Legion # 98 a	rea and Dr. Herna	ande	za	rea h	ave adequate egress il	llum	inat	tion
14.	FIRE ALARM SYSTEM								
	Charles that I share his term that finds all three M.	Good	1	Х	)	Repairs Required			)
Con	FIRE ALARM SYSTEM  adition:  mments:	Good	(	X	)	Repairs Required	9		)



TEAPA
Consulting Engineer. CA #1055
7990 S.W.117 Ave., S-140, Miaml, FL 33183
Tel (305) 598-4030 Fax 305-598-4033
TOMAS C. ARMSTRONG P.E.# 17974
DATE: 11-17-2015





Condition:					ULL STATIONS		
oondition.	Good	(	X	)	Repairs Required	(	)
Comments:							
Smoke Detectors, Strobes, Horn Strobes and Pu See Photos 38, 40,41, 53, 55, 58, 66, 70, 76 & 7		s W	еге 	found	and working.		
16. EXIT LIGHTS							W.
Condition:	Good	(	X	)	Repairs Required	(	)
Comments:							
Exit Lights appeared in good condition and prope See photos 39, 54,57,66,70,76,77	erly worki	ng.					
17. EMERGENCY GENERATOR							
Condition:	Good	(	x	)	Repairs Required	(	
Comments:					200000000000000000000000000000000000000		
18. WIRING IN OPEN OR UNDER COVER	R PARKI	NG	G	ARAG	GE AREAS		
18. WIRING IN OPEN OR UNDER COVER Condition:	R PARKI Good		G,		GE AREAS  Repairs Required	(	)
Condition: Comments:	Good	(	X	)	Repairs Required	(	)
Condition:	Good  UNDER or the over	(THE	X E O' ang 26	VERH to pro	Repairs Required  ANG  ovide illumination to the the parking lot driveway	e ve	hicle

19. OPEN OR UNDERCOVER SURFACE	AND SE	CUR	ITY LIC	HTING						
Condition: Go	ood (	)	Ille	ımination Required	(	)				
Comments: SEE MIAMI -DADE PARKING LO	T ILLUM	NATI	ON CE	RTIFICATION FORM						
A night survey was conducted to verify compliant (2) independent parking lot areas.	ce with Mi	ami-E	ade Co	de Section 8C-3 The	ere ar	e two				
PARKING LOT #1 is the parking lot on the north side and adjacent to the building with an overhang where the automobiles park under the overhang. The photometric night survey found that this area complies with Miami-Dade Code Section 8C-3. Refer to the Illumination Certification Form included.										
PARKING LOT # 2 is an independent parking lot, to the north of the building but separated from the building by an alley. There is no private luminaire covering this parking lot. The photometric night survey found that this area DOES NOT COMPLY with Miami-Dade Code Section 8C-3. Refer to the Illumination Certification Form included.  See attached Miami-Dade form on Parking Lot Illumination										
20. SWIMMING POOL WIRING										
Condition: N/A	Good	(	)	Repairs Required	(	)				
Comments: No swimming pool										
24 MARINO OF MECHANICAL FOLUDATE	NIT	700			2 - 11	i de la				
21. WIRING OF MECHANICAL EQUIPME Condition:	Good		<b>A</b>	Popoiro Poquirod	,	\ \ \				
Comments:	Good	( X	)	Repairs Required	. (	)				
The wiring of the mechanical units, the A/C comp	oressor ar	nd the	AHU a	ppeared in fair condition	חכ					
22. WIRING IN PUMP ROOM										
Condition: N/A	Good	(	)	Repairs Required	(	)				
Comments:	essen		-201							
No pump room										

No 17974

\*

STATE OF

WARD OF THE STATE OF

PCAPA
Consulting Engineers CA # 7055
7990 S MATT Ave., S-140, Miami, FL 33183
F-17095 598-4030 Fax 305-598-4033
TOMAS C. ARMSTRONG P.E.# 17974
DATE: 11-17-2015





#### 23.- GENERAL ADDITIONAL COMMENTS

Note: The building department with jurisdiction requires that any electrical changes, upgrades and repairs described in this report be performed with a certified electrician under an electrical permit.

#### THIS IS A LIST OF ITEMS THAT NEED TO BE INSTALLED, REPAIRED OR REPLACED

#### **ELECTRICAL**

The electrical system in this building is in good condition. Electrically this building passes the 40-year electrical inspection as per the MD County guidelines.

#### **ILLUMINATION**

On 01-09-2015 I conducted a night survey and photometric readings on the parking lot to the west of the building and found it very dark and not in compliance with M-D 8C-3.

#### **PARKING LOT #1**

PARKING LOT #1 is the parking lot on the north side and adjacent to the building with an overhang where the automobiles park under the overhang. The photometric night survey found that this area complies with Miami-Dade Code Section 8C-3. Refer to the Illumination Certification Form included.

#### **PARKING LOT #2**

PARKING LOT # 2 is an independent parking lot, to the north of the building but separated from the building by an alley. There is no private luminaire covering this parking lot. The photometric night survey found that this area DOES NOT COMPLY with Miami-Dade Code Section 8C-3. Refer to the Illumination Certification Form included.

See attached Miami-Dade form on Parking Lot Illumination

No 17974

B STATE OF

ORIO ACIDATION

ORIO ACI

CAPA
consulting Engineers- CA # 7055

Consulting Engineers- CA # 7055 7990 S.W.117 Ave., S-140, Miami, FL 33183 Tel (305) 598-4030 Fax 305-598-4033 TOMAS C. ARMSTRONG P.E.# 17974 DATE: 11-17-2015



1:8/5/2011: 40yrtrackingysstem



T: 305-598-4030 F:/33 C: 305-205-2900





40-year Electrical Re-Certification inspection - Photo 01



40-year Electrical Re-Certification Inspection - Photo 03



40-year Electrical Re-Certification Inspection - Photo 02



40-year Electrical Re-Certification Inspection - Photo 04







40-year Electrical Re-Certification Inspection - Photo 06



40-year Electrical Re-Certification Inspection - Photo 07



40-year Electrical Re-Certification Inspection - Photo 06



40-year Electrical Re-Certification Inspection - Photo 08




T: 305-598-4030 F:/33 C: 305-205-2900





40-year Electrical Re-Certification inspection - Photo 10A



40-year Electrical Re-Certification Inspection - Photo 10C



40-year Electrical Re-Certification inspection - Photo 10B



40-year Electrical Re-Certification Inspection - Photo 10D









T: 305-598-4030 F:/33 C: 305-205-2900



40-year Electrical Re-Certification Inspection - Photo 14

40-year Electrical Re-Certification inspection - Photo 13




40-year Electrical Re-Certification Inspection - Photo 16









40-year Electrical Re-Certification Inspection - Photo 19



40-year Electrical Re-Certification Inspection - Photo 18



40-year Electrical Re-Certification Inspection - Photo 20






T: 305-598-4030 F:/33 C: 305-205-2900



40-year Electrical Re-Certification Inspection - Photo 22



40-year Electrical Re-Certification Inspection - Photo 24











40-year Electrical Re-Certification Inspection - Photo 27




40-year Electrical Re-Certification Inspection - Photo 26



40-year Electrical Re-Certification Inspection - Photo 28






40-year Electrical Re-Certification Inspection - Photo 29



40-year Electrical Re-Certification Inspection - Photo 31



40-year Electrical Re-Certification Inspection - Photo 30









40-year Electrical Re-Certification Inspection - Photo 34



40-year Electrical Re-Certification Inspection - Photo 35



40-year Electrical Re-Certification Inspection - Photo 36





T: 305-598-4030 F:/33 C: 305-205-2900



40-year Electrical Re-Certification Inspection - Photo 37



40-year Electrical Re-Certification Inspection - Photo 39



40-year Electrical Re-Certification Inspection - Photo 38



40-year Electrical Re-Certification inspection - Photo 40





CONSULTING ENGINEERS

DBA Florida Corporation

T: 305-598-4030 F:/33 C: 305-205-2900



40-year Electrical Re-Certification Inspection - Photo 42

40-year Electrical Re-Certification Inspection - Photo 41




40-year Electrical Re-Certification Inspection - Photo 44






T: 305-598-4030 F:/33 C: 305-205-2900



40-year Electrical Re-Certification Inspection - Photo 46

40-year Electrical Re-Certification inspection - Photo 45



40-year Electrical Re-Certification inspection - Photo 48




T: 305-598-4030 F:/33 C: 305-205-2900



40-year Electrical Re-Certification Inspection - Photo 49



40-year Electrical Re-Certification Inspection - Photo 51



40-year Electrical Re-Certification Inspection - Photo 50



40-year Electrical Re-Certification Inspection - Photo 52










40-year Electrical Re-Certification Inspection - Photo 53



40-year Electrical Re-Certification Inspection - Photo 55



40-year Electrical Re-Certification inspection - Photo 54




40-year Electrical Re-Certification Inspection - Photo 56













40-year Electrical Re-Certification inspection - Photo 60







40-year Electrical Re-Certification inspection - Photo 61



40-year Electrical Re-Certification Inspection - Photo 63



40-year Electrical Re-Certification Inspection · Photo 62






TCAPA
CONSULTING ENGINEERS
DBA Florida Concention






40-year Electrical Re-Certification Inspection - Photo 65



40-year Electrical Re-Certification inspection - Photo 66



40-year Electrical Re-Certification Inspection - Photo 68




CONSULTING ENGINEERS DBA Floridg Corporation

T: 305-598-4030 F:/33 C: 305-205-2900





40-year Electrical Re-Certification Inspection - Photo 71



40-year Electrical Re-Certification Inspection - Photo 72



CONSULTING ENGINEERS
DBA Florida Corporation

T: 305-598-4030 F:/33 C: 305-205-2900



40-year Electrical Re-Certification Inspection - Photo 74



40-year Electrical Re-Certification Inspection - Photo 75



40-year Electrical Re-Certification Inspection - Photo 76




T: 305-598-4030 F:/33 C: 305-205-2900







40-year Electrical Re-Certification Inspection - Photo 77



40-year Electrical Re-Certification inspection - Photo 79



40-year Electrical Re-Certification Inspection - Photo 78



40-year Electrical Re-Certification Inspection - Photo 80





# City of Coral Gables Development Services

RC-15-11-5548 303 ALHAMBRA CIR #

ermit	03-4108-006-2430 Description: 40 YEAR BUILDING IFICATION OR OLDER BUILT (1924)
ΞL	
ME	
<b>-</b> L	8

# **OFFICE SET**

		Appro	ved						
	Section	By /	Date	,					
Ø	BUILDING	left	11/20/	ľ					
O	CONCURRENCY		•	-					
ø	ELECTRICAL			1					
0	FEMA								
0	FIRE								
0	HANDICAP								
ام	HISTORICAL								
o	MECHANICAL								
0	PLUMBING								
0	PUBLIC WORKS								
0	STRUCTURAL								
0	ZONING								
0									
O									
0									
0	OWNER BUILDER								
Subject to compliance with all Federal, State, County and City rules and regulations. City assumes no responsibility for accuracy of/or results from these plans.  THIS COPY OF PLANS MUST BE AVAILABLE ON BUILDING SITE OR AN INSPECTION WILL NOT BE									

APPROVAL OF THIS SET OF PLANS DOES NOT CONSTITUTE APPROVAL OF ANY STRUCTURE OR CONDITION NOT IN COMPLIANCE WITH ANY APPLICABLE CODES

400
_
01
TO.
en .

Permit Action Report Page: 1	CITY OF CORAL GABLES	
pmPermitActions	1/25/2016 7:41:15AM	

Address: 301 ALHAMBRA CIR CORAL GABLES, FL 33134-5003	Comments					REPAIRS REQUIRED AS PER REPORT		
	Completed By	cgonzalez	iwebuser	mlopez		areyes		
RTIFICATION RTIFICATION	Completion Completion Date Code	comp		apvd		reject		
UILDING RE CEI TRUCTURE CEF	Completion Date	11/12/2015	11/19/2015	11/20/2015		11/20/2015		
Permit type: rc010 - BUILDING RE CERTIFICATION Routing queue: rc012 - STRUCTURE CERTIFICATION	Action Description	CALCULATE FEES	COLLECT FEES	BUILDING PLAN REVIEW	ELECTRICAL PLAN REVIEW	ELECTRICAL PLAN REVIEW	COLLECT FEES	GENERATE LETTER
11-5548	Action Code	calc fees	collect	prbuild	prelec	prelec	collect	letter
Permit #: RC-15-11-5548 Master permit #:	Group # - Name	1 - BOARDS - GENERATE F calc fees	2 - CASHIER	3 - PLAN REVIEW	3 - PLAN REVIEW	3 - PLAN REVIEW	4 - RE CERTIFIED LETTER	4 - RE CERTIFIED LETTER

CITY'S

EXHIBIT\_