Page 1 of 5 Actions



Citizen Services

Permits and Inspections: Actions

BL-14-11-4165

Applied

11/14/2014

Approved 08/07/2017

Issued 08/07/2017

Permit Description

ON HOLD*** NEW PLANS MUST BE

Type RESIDENTIAL ADDITION

Permit Address 1252 OBISPO AVE CORAL GABLES FL 33134-3510

Applicant RAMESH C AIRAN &W ARUNA R Owner N

Owner RAMESH C AIRAN &W ARUNA R

ON HOLD*** NEW PLANS MUST BE SUBMITTED **** CONSULTANT - JEM *** HISTORICAL*** INCLUSIVE *** (2) LEVEL RESIDENCE *** SIMPLIFIED *** COV TERR, BALCONY, TRELLIS, PAVER DRIVEWAY \$500,000** Viewing Actions <-- Select the information you would like to view.</p> Comp'd Group Action Comment Approve Date Date Code pradmin - ADMINISTRATIVE BOARD OF ARCHITECTS PLAN REVIEW BOA PLAN 01/09/2015 APPROVED cmindreau BOA PLAN REVIEW pradmin - ADMINISTRATIVE BOARD OF ARCHITECTS PLAN REVIEW 11/16/2016 APPROVED pradmin - ADMINISTRATIVE BOARD cmindreau OF ARCHITECTS PLAN REVIEW BOA PLAN 02/08/2017 APPROVED REVIEW prboa - BOARD OF ARCHITECTS PLAN REVIEW 11/13/2014 APPROVED jray REVIEW prboa - BOARD OF ARCHITECTS PLAN REVIEW BOA PLAN 12/11/2014 APPROVED dgarcia REVIEW BOA PLAN prboa - BOARD OF ARCHITECTS PLAN REVIEW 02/05/2015 APPROVED irav REVIEW BUILDING PLAN prbuild - BUILDING PLAN REVIEW mlopez 01/14/2015 01/14/2015 REJECTED CLARIFY DRAINAGE ON FLAT ROOF REVIEW BUILDING PLAN prbuild - BUILDING PLAN REVIEW mlopez 02/23/2015 02/23/2015 REJECTED SEE PREVIOUS COMMENT. REVIEW BUILDING PLAN prbuild - BUILDING PLAN REVIEW mlopez 09/11/2015 09/11/2015 REJECTED CLARIFY ROOF DRAINAGE. SEE ME 7:30 TO 9:30 AM MWF. BUILDING PLAN prbuild - BUILDING PLAN REVIEW mlopez 09/18/2015 09/18/2015 REJECTED SEE PREVIOUS COMMENT. BUILDING PLAN prbuild - BUILDING PLAN REVIEW 04/26/2017 REJECTED ARCHITECT TO SEE ME 7:30 TO 9:30 AM MWF mlopez REVIEW BUILDING PLAN prbuild - BUILDING PLAN REVIEW mlopez 05/04/2017 05/05/2017 REJECTED ARCHITECT TO SEE ME 7:30 TO 9:30 AM MWF REGARDING DRAINAGE OF ROOF AND OV REVIEW BUILDING PLAN prbuild - BUILDING PLAN REVIEW 05/08/2017 mlopez REVIEW ELECTRICAL prelec - ELECTRICAL PLAN REVIEW 11/18/2014 11/19/2014 APPROVED areyes PLAN REVIEW ELECTRICAL prelec - ELECTRICAL PLAN REVIEW 03/16/2017 APPROVED areyes 03/16/2017 PLAN REVIEW HISTORICAL PLAN REVIEW COA (SP) 2014-018 prhist - HISTORICAL PLAN REVIEW kkautz 10/06/2015 10/21/2015 APPROVED HISTORICAL prhist - HISTORICAL PLAN REVIEW eauin 06/01/2017 06/05/2017 APPROVED COA (SP) 2014-018 PLAN REVIEW MECHANICAL ormech - MECHANICAL PLAN 12/17/2014 12/18/2014 APPROVED gruggiano PLAN REVIEW REVIEW prmech - MECHANICAL PLAN REVIEW 03/16/2017 APPROVED MECHANICAL gruggiano 03/16/2017 PLAN REVIEW prplbg - PLUMBING PLAN REVIEW gurgelles PLUMBING PLAN 12/18/2014 12/22/2014 REJECTED 1.NEED DEPARTMENT OF HEALTH APPROVAL 2.NEED WASA WATER ALLOCATION LETTER prplbg - PLUMBING PLAN REVIEW PLUMBING PLAN 01/23/2015 01/26/2015 REJECTED SAME COMMENTS AS DATED 12/22/14 gurgelles PLUMBING PLAN REVIEW prplbg - PLUMBING PLAN REVIEW 02/10/2015 02/10/2015 SAME COMMENTS AS DATED 12/22/14 gurgelles REJECTED PLUMBING PLAN prplbg - PLUMBING PLAN REVIEW 09/11/2015 09/17/2015 APPROVED REVIEW PLUMBING PLAN prplbg - PLUMBING PLAN REVIEW rperez2 03/16/2017 03/17/2017 APPROVED REVIEW PUBLIC WORKS 1- INDICATE ON PLANS "EXISTING ASPHALT APPROACHES TO REMAIN". 2- ALL RAINWA prpworks - PUBLIC WORKS PLAN 11/17/2014 REJECTED Ihickman 11/14/2014 PLAN REVIEW REVIEW PRIVATE PROPERTY. 3- PROVDE A CONCRETE PERIMETER 8" BY 8" AND ONE #5 CONTIN PAVERS' AREAS prpworks - PUBLIC WORKS PLAN REVIEW 1- INDICATE ON PLANS "EXISTING ASPHALT APPROACHES TO REMAIN". 2- ALL RAINWA PUBLIC WORKS emunoz 12/22/2014 12/23/2014 REJECTED PRIVATE PROPERTY. 3- PROVDE A CONCRETE PERIMETER 8" BY 8" AND ONE #5 CONTIN PAVERS' AREAS PLAN REVIEW 1- INDICATE ON PLANS "EXISTING ASPHALT APPROACHES TO REMAIN". 2- ALL RAINWAPRIVATE PROPERTY. 3- PROVDE A CONCRETE PERIMETER 8" BY 8" AND ONE #5 CONTIN PAVERS' AREAS PUBLIC WORKS PLAN REVIEW PUBLIC WORKS PLAN 01/12/2015 01/13/2015 REJECTED PUBLIC WORKS - PUBLIC WORKS PLAN 02/06/2015 02/09/2015 REJECTED DRIVEWAY AND APPROACH MUST BE SYMETRICAL emunoz PLAN REVIEW REVIEW LOOSE GRAVEL NOT ALLOWED UNLESS LOCATED MORE THAT FIVE FEET FROM PROPERT PUBLIC WORKS prpworks - PUBLIC WORKS PLAN Ihickman 09/18/2015 09/18/2015 REJECTED PLAN REVIEW REVIEW PRIVATE PROPERTY prpworks - PUBLIC WORKS PLAN REVIEW PUBLIC WORKS 12/07/2015 APPROVED emunoz 12/03/2015 PLAN REVIEW prstr - STRUCTURAL PLAN REVIEW STRUCTURAL baarcia 01/26/2015 01/26/2015 CANCELLED PLAN REVIEW STRUCTURAL prstr - STRUCTURAL PLAN REVIEW dreczek 02/18/2015 02/23/2015 REJECTED PLAN REVIEW STRUCTURAL prstr - STRUCTURAL PLAN REVIFW 09/21/2015 10/06/2015 REJECTED The Project appears to fall under Level 3 Alteration (Substantial structural alteration) dreczek PLAN REVIEW Please provide complete information, within the drawings, on all new and gravity/uplify and lateral force resisting elements. 2. Review terminated. STRUCTURAL Outside Consultant Review: General Comments 1. Structural review was not considered t incomplete structural calculations and lack of existing condition consideration in the plan additional comments will/can arise when these are adequately addressed. The structural prstr - STRUCTURAL PLAN REVIEW dreczek 12/09/2015 01/15/2016 REJECTED PLAN REVIEW

Page 2 of 5 Actions

12/16/2016 01/09/2017 REJECTED

existing slab on grade, but the existing building has an elevated framed floor (pier and be not address the effect of the new framing OR the new 2nd floor on the existing foundation provide no calculations for any existing elements. We will perform a full review when the adequately address the actual conditions of the building. 2. Drawings shall clearly indicate per FBC Existing. Please provide all necessary calculations to comply with the requireme Provide copy of the drawings for the existing building. 4. Clearly show in the demolition p all structural items, including any existing foundations that may be affected by the new si calculations of new concrete footings and stem walls. 6. Provide calculations for the existing including checks for new loads. 7. Drawings indicate an existing slab on grade, however a crawl space, and age of building indicates floor is most likely a wood framed elevated str. drawings and clearly show how the floor framing is affected by the medifications. 8. Provide calculations for the check of the exiting MWFRS of the build the connections of the transfer of MWRS roof diaphragm loads to CMU walls 11. Provide c Provide calculations for concrete columns 13. Provide calculations for sconfloor and ro S-2A, S2-B, and S-3 including long-term deflection checks 14. Provide calculations for stem assonry wall connection 15. Provide calculations for the metal deck roof 16. Provide that building pressures for roof 17. Architectural set is missing sheet A402 which is refere Structural Drawings Review: 18. Sheet S-1: Architectural set is missing sheet A402 which is refere Structural Drawings Review: 18. Sheet S-1: Architectural set is missing sheet A402 which is refere Structural Drawings Review: 18. Sheet S-1: Architectural set is finding and new alls and their respective reinforcing c. Foundation Note 10: Provide a rabuilding and new walls are connected and show the existing framing of the first floor will Include foundation notes b. Indicate size and length of reinforcement at corners of new s Include roundation notes B. Indicate size and length of reinforcement at corners or new si-calculations and reinforcement detail of masonry column MCI 21. Sheet S-2. Indicate that match lines that refer to partial plans on S-2A and S-2B 22. Sheet S-2A & S-2B: a. Show indicate how floor elements are framed b. Provide calculations and details of supports of: north-south direction c. Provide design of roof beams RB-6 to RB-22 d. Indicate on plan t columns type 5 parallel to south side of stairs e. Provide loading diagram of the special or and direction of load, or show load reaction on section 1/S-6 f. On roof plan at elevation and direction of load, or show load reaction on section 1/S-6.f. On roof plan at elevation beam does not match what is shown on section 1/S-6, where concrete beams are shown, elevation +15'-10", provide dimensions of locations of steel columns h. Roof note 9: Prov loads for wood truss engineer. Also clarify the strut load requirement? 23. Sheet S-3 a. Ir loads b. Clarify detail that shows connection between wood trellis beams and concrete be 4x10 and 4x12 wood beams supporting trellis 24. Sheet S-4 a. Show shear reinforcement Provide typical detail for steel column supported by concrete footing c. Beam schedule: B don't meet minimum steel reinforcement as per ACI 318-08 Section 10.5. Please clarify d shall be a size #3 bar as a minimum as per ACI 318-08 Section 7.10. Currently shows #2. Footings shall have minimum longitudinal and transverse reinforcement as per ACI 318-0 Footings shall have minimum longitudinal and transverse reinforcement as per ACI 318-0 f. Footings F-4.5A, F-4.5B, F-5.5 and F-6A shall have minimum longitudinal and transvers 08 Section 7.12.2.1. Please clarify 25. Sheet S-5: Structural Design Criteria, note 2: a. Pl dead load not live load as noted. b. Include truss bottom chord load of 10 psf as per table point load per FBC 1615.6.1 26. Sheet S-6: Provide calculations of connection between restel column on section 1/S-6 27. Sheet S-7: a. Section 1: How is stair supported (please Section 2: As per plan, slab at elevation +12'-0" is a concrete slab. No steel joists are sht clarify c. Section 2: Provide calculations of connection of wood trusses to existing Chruse regineer. e. Section 3: Plyworde calculations of connection of wood trusses to existing Chruse regineer. e. Section 3: Plywood soffit? "thick - provide calculations for plywood f. Scalculations of connections 28. Sheet S-8: a. Section 8: Indicate if stair steps are steel or calculations and details for stair if applicable End of comments, 1st Structural Review To process, please be sure to: 1) Cloud and date all revisions. 2) Address all comments com drawings. 3) Organize your responses in the same numerical order as this critique. 4) Recomments are not fully understood. If you disagree, explain why. 5) Provide a complete rand sealed on company letterhead. This is your opportunity to clearly communicate your misunderstandings. 6) Failure to comply with these requirements will result in additional Review by Consultant NOTE: Per Structural response sheet and review of arch/structural and sealed on company letterhead. This is your opportunity to clearly communicate your misunderstandings. 6) Failure to comply with these requirements will result in additional Review by Consultant NOTE: Per Structural response sheet and review of arch/structural new review due to the redesign and change of scope. 1. Please void all superseded sheet included in structural set. Please provide copy of the drawings for the existing indicate that this is a Level 3 alteration per FBC- Existing. Please provide all necessary carequirements of the FBC-Existing. 5. Per Florida Administrative Code (FAC), Please provide calculation book in lieu of signing and sealing each page. 6. Existing conditions must be cention of existing footings, connections between new and existing, existing footing calculated existing stating footings and existing being stating footings that are footings that are to remain or are being altered, footings that are footings that are to remain, etc. Callout BW-1 is being used for both existing and new wa provided for existing footings and existing block walls. Please show the direction of the wshow the support locations for these. Include calculations for the wood joists and their cosections and details to clearly show how the new elements and the existing elements are not found on architectural drawings - please provide elevation and riser information in str architectural information. (A-601 does not appear to be up to date) 8. Provide calculation roof connections, steel columns. 9. S-1A/1B: Coordinate slab and floor elevations with an Demolition drawings all out for wall to be demolished to the top of footing (for example or drawings show a new footing - please coordinate demolition drawings and structural draw appear to be openings that are being made larger that are not noted at all in demolition cortions of block walls that are not indicated in the demolition drawings and structural draw appear to be openings that are being made larger that are not noted at all in demolition cortions of block w

STRUCTURAL PLAN REVIEW prstr - STRUCTURAL PLAN REVIEW carguinzon 02/28/2017 03/11/2017 REJECTED

prstr - STRUCTURAL PLAN REVIEW dreczek

STRUCTURAL

CONSULTANT REVIEW - JEM - D. PERAZZO P.E. NOTE: This numbering system will conting plans. 1. 2nd Review: Satisfied. 2. 2nd Review: Satisfied. 3. 2nd Review: Satisfied. 4. 2n Review: Satisfied. 6. Existing conditions must be clearly indicated - there is no mention o Neview: Satisfied. 6. Existing conditions must be clearly indicated: There is no mention o between new and existing, existing footing calculations, etc. Drawings shall clearly show: remain or are being altered, footings that are to be removed and replaced, footings that is being used for both existing and new walls. Calculations are to be provided for existing Please show the direction of the wood joists, size, spacing etc. and show the support loca calculations for the wood joists and their connections. Provide sufficient sections and deta elements and the existing elements are connected, etc. 2nd Review: EBW-2 SHOWS #5@ elements and the existing elements are connected, etc. 2nd Review: EBW-2 SHOWS #5@ CALCULATED REINFORCEMENT FOR EXTERIOR WALL - ALSO SEE COMMENT #13B REGAR THE ATTACHMENT OF THE CANTILEVERED TRUSSES. PLEASE PROVIDE CALCULATIONS F NORTH WALL WHICH ARE SUBJECT TO NEW LOADS. 7. 2nd Review: Satisfied. 8. 2nd Revisitisfied. 10. 2nd Review: Satisfied. 11. S-2A/2B - how is the NW corner of the roof supp PROVIDE CALCULATIONS FOR THE CONNECTION ON A & B ON S-11 AND FOLLOW THE P. EXISTING ELEMENTS. ALSO SEE COMMENT #13 REGARDING THE CANTILEVERED TRUSS WALL. 12. S-2A/2B - Provide calculations for existing beams at the roof level. . 2nd Revie OVER THE GARAGE DOOR - THIS BEAM SUPPORTS NEW CANTILEVERED TRUSSES AND NEEDS TO BE ABLE TO SPAN HORIZONTALLY FOR THE TRIBUTARY LATERAL LOAD PLUS | 13. S-2A/2B - Unclear what type of steel trusses specified, but please note light gauge m
Gables Zoning Code - please clarify if it is rolled steel or something different. Please show
manufacturer. Please provide all relevant truss design information for truss delegated eng

threaded rods and the plate is not typical. Welding of threaded rods is not specifically add recommended. The type of rod has to be specified to be weldable (look in AISC Design G connection shall include any eccentricity of the connection. 17. S-7 - Review size of new onto appear to be deep enough for all necessary connections. 18. Calculations: the height calculations does not appear to be correct, the height shall be from the top of the footing slab does not provide bracing. 19. Review steel joist selection - per the Vulcraft tables the (exceeding allowed deflections per FBC) **THERE ARE STILL MANY INCONSISTENCIES BI STRUCTURAL DRAWINGS, SEVERAL ITEMS RELATED TO THE TWO PREVIOUS REVIEWS T ADDRESSED, MISSING CALCULATIONS, MISSING DETAILS, ETC. WE RECOMMEND THIS REVIEW BY AN ENGINEER THAT HAS TO BE APPROVED BY THIS DEPARTMENT PRIOR TO REVIEW. A MEETING WITH THE OWNER AND PROPOSED PEER REVIEWER WILL BE REQUE DRR/City of Coral Gables: Please provide a Peer Review of the drawings and calculations.

Review Engineer to contact the Building Department for clarification of scope of services p

Actions Page 3 of 5

05/08/2017 05/09/2017 APPROVED

STRUCTURAL

prstr - STRUCTURAL PLAN REVIEW carquinzon

the trusses to the structure are the responsibility of the EOR. 2nd Review: THERE ARE SE CONNECTION OF THE CANTILEVERED STEEL TRUSSES: -1) THE WALLS ARE NOT BEING MOMENT FROM THE CANTILEVER (BOTH EXISTING NORTH WALL AND NEW EAST GARAG CONTINUITY OF THE REINFORCEMENT BETWEEN THE EXISTING WALL AND THE ADDED I AND 1/S-10) AT THE TOP TO BE ABLE TO RESIST THE MOMENT AND III) P.9 OF THE CAL USING THE ANCHOR CAPACITY FOR EMBEDMENT INTO CONCRETE INSTEAD OF GROUTE SEPARATE TABLES, SPACING AND EDGE DISTANCE REQUIREMENTS FOR CMU). 14. 2nd clarify the intent of the "roof garden" and clarify finishes/loads. (Will there be planters?) / roof - please provide detailed SDL break-down. 2nd Review: PLEASE REVIEW/REVISES HACKHITECTURAL ENTIRE SOUTH AREA OF THE ROOF IS A TERRACE. 16. 2nd Review: Satisfied. 19. 2nd Review: Satisfied. 2nd Review Comments: 2.0. PLEASE SHOWN ON THE ROOF PLAN AND THE SECTION, SOME AREAS ARE CALLED TO BE 14'-3" SECTIONS SHOW TOP OF SLAB ELEVATIONS TO BE FLUSH (FOR EXAMPLE 2/S-8, 2/S-72) PARAPET AND TRELLIS OVER THE COVERED WALKWAY SOUTH OF THE PANTEY, PLEASE THE ROOF FRAMING 22. S-2A/2B - PLEASE ADD THE CONCRETE OVER METAL DECK INFO NOTES 23. SA - PLEASE REVIEW ANGLE "A" REQUIREMENTS - THE SECTIONS THAT SHO A -203, AND A-403 THROUGH THE CITTY BEFORE FINAL APPROVAL End of J.E.M. comment ensure an efficient review process, please be sure to: 1) Cloud and date all revisions. 2) / before resubmitting drawings. 3) Organize your responses in the same numerical order a clarification if any comments are not fully understood. If you disagree, explain why. 5) Promments, signed and sealed on company letterhead. This is your opportunity to clearly avoid possible misunderstandings. 6) Failure to comply with these requirements will resul disapprovals.

STRUCTURAL PLAN REVIEW	prstr - STRUCTURAL PLAN REVIEW	carguinzon	05/08/2017	05/09/2017	APPROVED	APPROVED - CONSULTANT - JEM - DESIREE PERAZZO P.E.
ZONING PLAN REVIEW	legalsuff - LEGALLY SUFFICIENT	srodriguez		03/06/2015	COMPLETED	1. UNITY OF TITLE COVENANT APPLICATION COMPLETED.
ZONING PLAN REVIEW	przoning - ZONING PLAN REVIEW	srodriguez	11/19/2014	11/24/2014	DEFERRED	ZONING COMMENT #1 1. PAGE A101, PROVIDE A BIRDS EYE VIEW OF THE COMPLETE R BUILDING ON THE PROPOSED SITE PLAN AND PROVIDE THE INTERIOR LAYOUTS FOR TH PROVIDE THE PERMIT NUMBER FOR THE CONVERSION OF THE DETACH GARAGE TO A DI A101, THE EXISTING CARPORT SHALL HAVE A DRIVEWAY FOR INGRESS AND EGRESS PLOWING THAT THE FRONT WALKWAY DOES NOT EXCEED 5 FEET IN WIDTH. 5. PAGE A1 SETBACK FROM THE WEST PROPERTY LINE TO THE CLOSEST EDGE OF THE DRIVEWAY. 6. REQUIRED SETBACKS. 7. PROVIDE A RECORDED COPY OF THE UNITY OF TITLE COVENNA YOU NEED TO APPLY, THE APPLICATION CAN BE FOUND AT: HTTP://WWW.CORALGABLE: 8. PAGE A301, PROVIDE THAT THE TOTAL BUILDING HEIGHT OF 28 FEET IS TAKEN FRON LABEL ACCORDINGLY. 9. PAGE A203, PROVIDE THE DETACH GUEST ROOM AND COVERE 10. PAGE A101, PROVIDE LANDSCAPE OPEN SPACE CALCULATION OF NOT LESS THAN FO LANDSCAPE OPEN SPACE SHALL BE LOCATED IN THE FRONT YARD AREA. 11. ON ALL AF "PROPOSED JACUZZI" TO "PROPOSED SPA". 12. PAGE A101, PROVIDE THE SQUARE FOOTAGE FOR THE SPA. 14. PAGE A101, THE GROUND THE SPA LA, PAGE A101, PROVIDE THE SQUARE FOOTAGE FOR THE SPA. 14. PAGE ATION IS OVER, REDUCTION REQUIRED. RE-EXAM DOUBLE VALUE SECTION AND ZOND GARDEN). 15. PAGE A101, THE GROUND AREA COVERAGE 35% IS OVER, REDUCTION REQUIRED. RE-EXAM DOUBLE VALUE SECTION AND ZOND GARDEN). 15. PAGE A101, THE GROUND AREA COVERAGE 35% IS OVER, REDUCTION RETURN TERRACES WITH VERTICAL SUPPORTS. 16. PAGE A101, PROVIDE THE GROUND AREA COVERAGE 35% IS OVER, REDUCTION RETURN TERRACES WITH VERTICAL SUPPORTS. 16. PAGE A101, PROVIDE THE GROUND AREA COVERAGE 35% IS OVER, REDUCTION RETURN TERRACES WITH VERTICAL SUPPORTS. 16. PAGE A101, PROVIDE THE GROUND AREA COVERAGE 35% IS OVER, REDUCTION RETURN TERRACES WITH VERTICAL SUPPORTS. 16. PAGE A101, PROVIDE THE GROUND AREA COVERAGE 35% IS OVER, REDUCTION RETURN TERRACES WITH VERTICAL SUPPORTS. 16. PAGE A101, PROVIDE THE GROUND AREA COVERAGE 35% IS OVER, REDUCTION RETURN TERRACES WITH VERTICAL SUPPORTS. 16. PAGE A101, PROVIDE THE GROUND AREA COVERAGE 35% IS OVER, REDUCTION RETURN TERRACES WITH V
ZONING PLAN REVIEW	przoning - ZONING PLAN REVIEW	srodriguez		12/17/2014	DEFERRED	ZONING COMMENT #2 1. PAGE A101 PRIOR COMMENT NOT FULLY ADDRESS, PROVIDE 1 DOES NOT EXCEED 5 FEET IN WIDTH 2. RE-LABEL THE "PROPOSED PORCH" TO "PROPC A101.1 PRIOR COMMENT NOT FULLY ADDRESS, THE FLOOR AREA RATIO CALCULATION I DOES NOT ACCOUNT FOR THE GARAGE BATHROOM AND THE PROPOSED PORCH COURT REQUIRED (NOTE, THE NEW 2ND FLOOR OPEN GARDEN AND THE INTERIOR STAIR DOUF FROM THE F.A.R. COUNT). 4. PAGE A101.1 PRIOR COMMENT NOT FULLY ADDRESS, THE IS OVER, G.A.C. COUNT SHOWN DOES NOT ACCOUNT FOR ALL COVERED AREAS WITH V COURT YARD, CARPORT, AND GARAGE BATHROOM. A REDUCTION IS REQUIRED. 5. FUR REVIEW BY: STEVEN RODRIGUEZ ZONING TECH. EMAIL: srodriguez@coralgables.com CI wwwcoralgables.com
ZONING PLAN REVIEW	przoning - ZONING PLAN REVIEW	srodriguez	01/20/2015	01/22/2015	DEFERRED	ZONING COMMENT #3 1. PAGE A203, PROVIDE COMPLETE EXTERIOR DIMENSIONS. 2. T REDUCTION REQUIRED. 3. PAGE A101.1, THE GARAGE COUNTS AT A 100%. 4. THE GRO OVER, REDUCTION REQUIRED. 5. PAGE A101.1, THE GROUND AREA CALCULATION GIVI ZONING CODE ARTICLE 4, SECTION 4-101). WEB LINK: http://www.coralgables.com/ind THE OFFICE SET, PAGE A101.1, FOR CALCULATION BREAK DOWN.
						ZONING COMMENT #3 (REVISED PER MEETING) 01/29/2015 1. PAGE A203, PROVIDE CC 2. THE FLOOR AREA RATIO IS OVER, REDUCTION REQUIRED. 3. PAGE A101.1, THE GARZ SEE THE OFFICE SET, PAGE A101.1, FOR CALCULATION BREAK DOWN. 4. FURTHER REVI STEVEN RODRIGUEZ ZONING TECH. EMAIL: srodriguez@coralgables.com CITY WEB SITE FURTHER REVIEW REQUIRED. REVIEW BY: STEVEN RODRIGUEZ ZONING TECH. EMAIL: \$\text{WEB SITE}\$ WWW.coralgables.com
ZONING PLAN REVIEW	przoning - ZONING PLAN REVIEW	srodriguez		02/23/2015		ZONING COMMENT #4 1. PAGE A203 PRIOR COMMENT NOT FULLY ADDRESS, PROVIDE (DIMENSIONS. REMOVE THE SIDE DRIVEWAY BRICK HATCHING, BRICK RIBBON HATCHIN HATCHING, AND THE FRONT DRIVEWAY HATCHING TO PROVIDE LEGIBLE DIMENSIONS. DIMENSIONS FOR THE BUILDING ENVELOP SEPARATE FROM THE TRELLIS WALKWAYS AI PROVIDE THAT ALL FOOTPRINT CHANGES MADE ON THE ARCHITECTURAL PAGES ARE AL PAGES, TOO. 4. FURTHER REVIEW REQUIRED. NOTE: THE FLOOR AREA RATIO AND THE COULD NOT BE VERTIFED DUE TO THE MISSING DIMENSIONS. REVIEW BY: STEVEN ROC STORTING CORRESPONDED.
ZONING PLAN REVIEW	przoning - ZONING PLAN REVIEW	srodriguez	02/27/2015	03/06/2015	CANCELLED	1. NEW SHEETS ADDED.
ZONING PLAN REVIEW	przoning - ZONING PLAN REVIEW	srodriguez		12/09/2016	DEFERRED	ZONING COMMENT #5 1. PROVIDE ONE PROPOSED SITE PLAN SEE PAGES A101 AND A1 SHEET. 2. PAGE A101, PROVIDE COMPLETE DRIVEWAY RIBBONS TO THE CARPORT 3. P. TRIANGLE OF VISIBILITY FOR THE DRIVEWAY. 4. PAGE A101, PROVIDE A NOTE ON THE STATING THAT, "THE TRIANGLE OF VISIBILITY SHALL BE KEPT CLEAR OF VISUAL OBSTR TWO AND A HALF (2 1/2) FEET AND EIGHT (8) FEET ABOVE THE ESTABLISHED GRADE". PAGE FROM, "LOW ROOF PLAN MAIN HOUSE" TO "2ND FLOOR AND LOW ROOF PLAN". 6. COVERAGE IS OVER, REDUCTION REQUIRED. 7. PAGE A101.1, RE-EXAM THE IST & ZND MATCH WITH THE FLOOR PLANS. 8. PAGE A101.1, PROVIDE A LEGIBLE ZONING TABLE. CONCRETE WALL BETWEEN THE POWDER ROOM AND THE GARAGE. 10. PAGE A203, PRO BETWEEN CLOSEST #3 AND THE GARAGE. 11. PAGE A101.1, RE-EXAM OPEN LANDSCAPI REVIEW REQUIRED. REVIEW BY: STEVEN RODRIGUEZ ZONING TECH. EMAIL: srodriguez SITE: WWW.coralgables.com
ZONING PLAN REVIEW	przoning - ZONING PLAN REVIEW	srodriguez	02/10/2017			ZONING COMMENT #6 1. THE 35% GROUND AREA COVERAGE IS OVER, REDUCTION REI OF REDUCTION ON PAGES A101.1 AND A203. 2. PAGE A101.1, PROVIDE A DETAIL BREA FOR THE 35% GROUND AREA COVERAGE CALCULATION. 3. PAGE A101, PROVIDE THE D. PROPERTY LINE TO THE CLOSEST EDGE OF THE RESIDENCE. 4. PAGE A101, ON THE PRE CONCRETE PAVERS AND JUST SHOW THE TURF PAVERS. 5. FURTHER REVIEW REQUIREE RODRIGUEZ ZONING TECH. EMAIL: srodriguez@coralgables.com CITY WEB SITE: www.c
ZONING PLAN REVIEW	przoning - ZONING PLAN REVIEW	srodriguez	04/27/2017	02/23/2017	APPROVED	
PLAN PROCESSING	ppappl - APPLICATION/LICENSE/OWNERSHIP VERIFICATION	carguinzon		06/12/2017	INCOMPLETE	MISSING THE PERMIT APPLICATION W/ THE CONTRACT COST OF THE JOB
PLAN PROCESSING	ppappl - APPLICATION/LICENSE/OWNERSHIP VERIFICATION	carguinzon				CONTRACTOR TO UPDATE LIC & INS & LOCAL BUS. TAX, CONTRACTOR HAS EXPIRED PE
PLAN PROCESSING	ppappl - APPLICATION/LICENSE/OWNERSHIP VERIFICATION	ebermudez1			COMPLETED	
PLAN PROCESSING	calc fees - CALCULATE FEES	carguinzon				NEED THE CONTRACT COST OF THE JOB.
PLAN PROCESSING	calc fees - CALCULATE FEES	carguinzon		07/28/2017	COMPLETED	

Actions Page 4 of 5

ppimpfees - MIAMI-DADE COUNTY IMPACT FEES carguinzon 09/11/2015 COMPLETED PLAN PROCESSING PLAN PROCESSING pphrs - PLUMBING-HRS APPROVAL - SEPTIC TANK carguinzon 09/02/2015 APPROVED ppwater - PLUMBING-WATER VERIFICATION FORM PLAN carguinzon 06/12/2017 INCOMPLETE NEED AND UPDATED WATER VER. LETTER. PROCESSING PLAN PROCESSING ppwater - PLUMBING-WATER VERIFICATION FORM carguinzon 08/02/2017 APPROVED CASHIER collect - COLLECT FEES 08/07/2017 NOTICE OF COMMENCEMENT ppnoc - NOTICE OF COMMENCEMENT 08/01/2017 COMPLETED BUILDING INSPECTIONS bl002 - ARCH/ENG REVIEW SOIL CONDITION LETTER BUILDING INSPECTIONS bl084 - FINAL BUILDING BUILDING INSPECTIONS bl112 - FOUNDATION ADDITIONS/NEW - SOIL LETTER REOUIRED bl114 - FRAMING 01 FLOOR BUILDING INSPECTIONS BUILDING bl115 - FRAMING 02 FLOOR INSPECTIONS BUILDING INSPECTIONS bl171 - INSULATION 01 FLOOR BUILDING INSPECTIONS bl172 - INSULATION 02 FLOOR BUILDING INSPECTIONS bl214 - POURED CELLS 01 FLOOR BUILDING INSPECTIONS bl215 - POURED CELLS 02 FLOOR BUILDING INSPECTIONS bl237 - ROOF INSULATION BUILDING INSPECTIONS bl239 - ROOF SHEATHING BUILDING bl242 - ROOF SLAB INSPECTIONS BUILDING bl243 - ROOF TIE BEAM INSPECTIONS bl244 - ROOF TRUSSES - SHOP BUILDING INSPECTIONS DRAWING REQUIRED BUILDING INSPECTIONS bl245 - SCREW FOR GYPSUM BOARD 01 FLOOR BUILDING INSPECTIONS bl246 - SCREW FOR GYPSUM BOARD 02 FLOOR BUILDING INSPECTIONS bl281 - SHOP DRAWING - BALCONY RAILINGS BUILDING INSPECTIONS bl273 - SHOP DRAWING -EXTERIOR DOORS BUILDING INSPECTIONS bl285 - SHOP DRAWING -GARAGE/OVERHEAD DOOR BUILDING INSPECTIONS bl282 - SHOP DRAWING - STAIR RAILINGS BUILDING INSPECTIONS bl289 - SHOP DRAWING - TRUSSES BUILDING bl290 - SHOP DRAWING -INSPECTIONS WINDOWS BUILDING bl292 - SLAB 01 FLOOR INSPECTIONS BUILDING bl293 - SLAB 02 FLOOR INSPECTIONS bl981 - STORMWATER, EROSION AND SEDIMENTATION CONTROL BUILDING INSPECTIONS BUILDING INSPECTIONS bl315 - TERMITE TREATMENT bl334 - TIE COLUMNS 01 FLOOR BUILDING INSPECTIONS BUILDING INSPECTIONS bl335 - TIE COLUMNS 02 FLOOR bi358 - WINDOW/DOOR ANCHORS 01 FLOOR - BUCK INSPECTION REQUIRED BUILDING INSPECTIONS bl359 - WINDOW/DOOR ANCHORS 02 FLOOR - BUCK INSPECTION BUILDING INSPECTIONS REQUIRED bl375 - WINDOW/DOOR BUCK 01 BUILDING INSPECTIONS FLOOR - SHOP DRAWING REQUIRED BUILDING INSPECTIONS bl376 - WINDOW/DOOR BUCK 02 FLOOR- SHOP DRAWING REQUIRED HISTORICAL INSPECTIONS hi773 - FINAL HISTORICAL (BLDG PERMIT) PUBLIC WORKS INSPECTIONS pw820 - BASE pw821 - CONCRETE PERIMETER/STEEL PUBLIC WORKS INSPECTIONS PUBLIC WORKS pw837 - FINAL PUBLIC WORKS INSPECTIONS (BLDG PERMIT) pw807 - SUBGRADE PUBLIC WORKS INSPECTIONS PUBLIC WORKS ns101 - TREE PROTECTION PLAN INSPECTIONS zn002 - DRIVEWAY SETBACK **ZONING** INSPECTIONS ZONING INSPECTIONS zn010 - FINAL SURVEY-NEW SF ZONING INSPECTIONS zn004 - FINAL ZONING ZONING INSPECTIONS zn264 - SETBACK INSP-FOUNDATION SURVEY REQ

certificat - CERT OF COMPLETION OR OCCUPANCY ISSUANCE

PLAN PROCESSING Actions Page 5 of 5

PLAN ppelevcert - ELEVATION CERTIFICATE

The City's online services are protected with an SSL encryption certificate. For technical assistance, please call 305-569-2448 (8am-5pm, M-F).