9/3/2021 Actions



Citizen Services Business Services

Back to Coral Gables.com

Permits and Inspections: Actions

Logon

Help Contact

02/20/2022

BL-20-10-6838

Applied Approved 10/21/2020 08/19/2021 08/24/2021

Issued

Final Expires

DOOR/GARAGE Type DOOR/SHUTTER/WINDOW

Status issued

Permit Description

Permit Address 6809 NERVIA ST CORAL GABLES FL 33146-3601

Applicant JUVAL CORPORATION Owner N **RESIDENTIAL* REPLACEMENT OF** WINDOWS(13) \$10,000

Owner JAIME E CERVERA TRS JAIME E CERVERA REVOCABLE TRUST

Viewing	Actions 🗸	< Select the	information y	ou would like	to view.	
Group	Action	Approver	Start Date	Comp'd Date	Comp'd Code	Comment
PLAN REVIEW	pradmin - ADMINISTRATIVE BOARD OF ARCHITECTS PLAN REVIEW	jpino	10/22/2020	10/27/2020	DEFERRED	REVIEWED & DEFERRED BY J. RIESCO ON 10/27/2020 SEE PLANS FOR NOTES
PLAN REVIEW	pradmin - ADMINISTRATIVE BOARD OF ARCHITECTS PLAN REVIEW	schin	11/13/2020	11/16/2020	DEFERRED	REVIEWED & DEFERRED BY A. ALVAREZ PREVIOUS COMMENTS STILL APPLY
PLAN REVIEW	pradmin - ADMINISTRATIVE BOARD OF ARCHITECTS PLAN REVIEW	canderson	02/03/2021	02/09/2021	DEFERRED	DEFERRED FOR THE CITY ARCHITECT PREVIOUS COMMENTS REMAIN, PROVIDE A FLOOR PLAN AND GLASS COLOR HORIZONTAL ROLLER WINDOWS NOT APPROPRIATE ON STREET FACING ELEVATION FOR THIS ARCHITECTURAL STYLE. CASEMENT WINDOWS ARE RECOMMENDED FOR STREET FACING ELEVATIONS.
PLAN REVIEW	pradmin - ADMINISTRATIVE BOARD OF ARCHITECTS PLAN REVIEW	arestrepo	03/25/2021	04/19/2021	DEFERRED	DEFERRED FOR THE CITY ARCHITECT PREVIOUS COMMENT REMAIN: HORIZONTAL ROLLER WINDOWS NOT APPROPRIATE ON STREET FACING ELEVATION FOR THIS ARCHITECTURAL STYLE. CASEMENT WINDOWS ARE RECOMMENDED FOR

9/3/2021 Actions

13/2021			Actions			
PLAN	pradmin - ADMINISTRATIVE BOARD	canderson	08/06/2021	08/16/2021	APPROVED	STREET FACING ELEVATIONS. APPROVED FOR THE
REVIEW	OF ARCHITECTS PLAN REVIEW				D = 1 = 0 = D	CITY ARCHITECT
PLAN REVIEW	prbuild - BUILDING PLAN REVIEW	mlopez	10/21/2020	10/21/2020	REJECTED	NOA DRAWINGS MUST BE 11X17" 2 INDICATE WINDOW SIZES TYPE OF GLASS MULLION SIZES ANCHOR TYPE ON NOA DRAWINGS.
PLAN REVIEW	prbuild - BUILDING PLAN REVIEW	mlopez	11/18/2020	11/19/2020	REJECTED	INDICATE ESCAPE WINDOWS. SEE PREVIOUS COMMENTS.
PLAN REVIEW	prbuild - BUILDING PLAN REVIEW	mlopez		02/09/2021	REJECTED	INDICATE ESCAPE WINDOWS.
PLAN REVIEW	prbuild - BUILDING PLAN REVIEW	mlopez	03/04/2021	03/04/2021	APPROVED	
PLAN REVIEW	prstr - STRUCTURAL PLAN REVIEW	dreczek	10/27/2020	10/29/2020	REJECTED	1. Provide photos of North and East elevations. 2. Provide structural information on modifications to existing exterior walls required to accomodate new window 5.
PLAN REVIEW	prstr - STRUCTURAL PLAN REVIEW	dreczek	11/20/2020	11/30/2020	REJECTED	Submittal cannot be followed. Please organize all drawings/calculations into two identical, bound sets (no more than 2). Void sheets and calculations being superseded (retain within the submittal). Please coordinate with administrative staff - all new sheets/information being inserted into the Permit package to be perforated.
PLAN REVIEW	prstr - STRUCTURAL PLAN REVIEW	dreczek	02/10/2021	02/10/2021	REJECTED	THIRD REVIEW COMMENTS: 1. Provide photos of North and East elevations. PROVIDED PHOTOGRAPH DO NOT SHOW EXISTING WINDOWS BUT VEGETATION. PLEASE PEOVIDE ADDITIONAL PHOTOGRAPHS OF RESIDENCE WALLS TAKEN BEHIND VEGETATION ALLOWING FOR THE REVIEWER TO DETERMINE IF ADDITIONAL MODIFICATIONS TO THE EXISTING OPENINGS ARE BEING PROPOSED - SUCH AS ONE IN COMMENT BELOW. 2.

9/3/2021 Actions

Provide structural information on modifications to existing exterior walls required to accomodate new window 5. COMMENT REMAINS (NEW DRAWINGS REVISED WINDOW NUMBER FROM 5 TO 7 [KITCHEN]). SIZE OF **EXISTING WINDOW** WITHIN WEST FACE **DIFFERS FROM** WHAT IS SHOWN ON **SUBMITTED** PHOTOGRAPHS -PLEASE COMPARE THE TWO. PLEASE ADDRESS THIS WITHIN THE DRAWINGS AS IT WILL BE AN ALTERATION TO EXTERIOR WALL.

As per previous

PLAN REVIEW

PLAN

prstr - STRUCTURAL PLAN REVIEW dreczek

03/01/2021 03/02/2021 REJECTED

review comments: Width of exterior wall opening at window '7', shown in two included photographs, appears to exceed its height by roughly 30%. Width of exterior wall opening at window '7', shown and dimensioned on sheet 2 of 3 of submitted drawings, is roughly 90% of its height. How is this possible without alterations to the exterior wall? Please comply with all following as mandatory for a rereview: (a) engineer to provide a written response to all review comments (plans will not be reviewed otherwise). Avoid generic responses such as "see plans" or "see calculations". For drawings, reference specific sheet and plan/section/detail number. For calculations, reference page number. (b) no ink marks, white outs, or stick-ons permitted on drawings. Please make changes to originals and resubmit mechanically

prstr - STRUCTURAL PLAN REVIEW dreczek

03/24/2021 03/25/2021 WAIVED

reproduced copies.
NO STRUCTURAL

9/3/2021 Actions

REQUIRED

REVIEW SCOPE OF WORK. NO MODIFICATIONS TO EXTERIOR WALLS. PLAN prstr - STRUCTURAL PLAN REVIEW 08/19/2021 RE REVIEW **REVIEW FEE** 10/21/2020 INCOMPLETE OLD VERSION OF PLAN ppappl jray PROCESSING APPLICATION/LICENSE/OWNERSHIP **PERMIT VERIFICATION** APPLICATION NO LONGER ACCEPTED, **NEED NEW PERMIT** APPLICATION, AVAILABLE ONLINE. SIGNED BY CONTRACTOR AND **OWNER** 08/19/2021 INCOMPLETE - NEED NEW **PLAN** ppappl jray PROCESSING APPLICATION/LICENSE/OWNERSHIP VERSION OF PERMIT **VERIFICATION** APPLICATION, AVAILABLE ONLINE, SIGNED BY **CONTRACTOR AND** OWNER W/ UPDATED ESTIMATED COST OF WORK BEFORE INVOICING CAN BE **FINALIZED** ppappl -08/24/2021 COMPLETED PI AN jray APPLICATION/LICENSE/OWNERSHIP **PROCESSING VERIFICATION** calc fees - CALCULATE FEES 08/19/2021 INCOMPLETE - NEED NEW PI AN jray **PROCESSING** VERSION OF PERMIT APPLICATION, AVAILABLE ONLINE, SIGNED BY CONTRACTOR AND OWNER W/ UPDATED ESTIMATED COST OF WORK BEFORE INVOICING CAN BE **FINALIZED** 08/24/2021 COMPLETED **PLAN** calc fees - CALCULATE FEES jray **PROCESSING CASHIER** collect - COLLECT FEES iwebuser 08/24/2021 INSPECTION bl084 - FINAL BUILDING zn004 - FINAL ZONING INSPECTION bl358 - WINDOW/DOOR ANCHORS INSPECTION 01 FLOOR - BUCK INSPECTION **REQUIRED** bl375 - WINDOW/DOOR BUCK 01 INSPECTION FLOOR - SHOP DRAWING

The City's online services are protected with an **SSL encryption certificate**. For technical assistance, please call 305-569-2448 (8am-5pm, M-F).