



Legislation Details (With Text)

File #:	CE305050-081821	Version:	1	Name:	
Type:	Code Enforcement Board Violation	Status:		Public Hearings	
File created:	11/2/2021	In control:		Code Enforcement Board	
On agenda:	1/19/2022	Final action:			
Enactment date:		Enactment #:			
Title:	6915 Red Road				
	Violation Description - Expired Permits: -BL19024467 - ATM installation , block up portion of storefront surrounding ATM & night depository (Ocean Bank) -BL19013068 -Commercial interior renovation (Ocean Bank)				
	Remedy - Must reactivate permits and call for inspections to finalized				
	Owner - Red Sunset Building LLP				
	Code Enforcement Officer Roman				
Sponsors:					
Indexes:					
Code sections:					
Attachments:	1. EXP CODE, 2. OWNERSHIP, 3. CE NOV PHOTOS SEPT 22 2021, 4. CE VIO PHOTOS 8.18.2021, 5. CE305050 CE NOV 6915 RED ROAD (EXP) AGENT CM9171082133393265257702, 6. CE305050 CE NOV 6915 RED ROAD (EXP) CM9171082133393265257696, 7. CE305050 CE VIO 6915 AGENT RED ROAD TENANT 6939 RED RD OCEAN BANK CM9171082133393273532723, 8. CE305050 CE VIO 6915 RED ROAD TENANT 6939 RED RD OCEN BANK CM9171082133393273532730, 9. EMAIL TO CITE AUGUST 18 2021 BL19024467 EL19034764, 10. PERMIT BL19013068 EXPIRED 9.14.21, 11. PERMIT BL19024467 ACTIONS NEED OCCUPANCY, 12. PERMIT BL19024467 EXPIRED 1.30.21, 13. PERMIT BL190113068 ACTIONS NEED OCCUPANCY, 14. PERMIT ME19045249 NEVER ISSUED NEED PAYMENT INSPECTION AUGUST 18 2021, 15. PERMIT BL21107603 EXPIRED APRIL 18 2022, 16. SUMMONS CEB 11.17.21 6915 RED RD CE305050 (EXP) CM9171082133393265261150, 17. SUMMONS CEB 11.17.21 POSTED NOV 4 2021, 18. SUNBIZ AGENT RED SUNSET BUILDING LLLP, 19. AFFIDAVITZ VIO CE305050 6915 RED RD, 20. AFFIDAVITZ NOV CE305050 6915 RED RD				

Date	Ver.	Action By	Action	Result
11/17/2021	1	Code Enforcement Board	Continued prior to hearing	

6915 Red Road

Violation Description - Expired Permits:
-BL19024467 - ATM installation , block up portion of storefront surrounding ATM & night depository (Ocean Bank)
-BL19013068 -Commercial interior renovation (Ocean Bank)

Remedy - Must reactivate permits and call for inspections to finalized

Owner - Red Sunset Building LLP

Code Enforcement Officer Roman