



Legislation Text

File #: CE278415, **Version:** 1

CASE CONTINUED - 2850 Douglas Road

Violation Description - Perimeter walls and tile entry way are dirty. Update: Painted floor tiles in entry way, and wall on south side still in need of patching/painting.

Remedy - Must clean all dirty walls and tile entryway. Update: Must obtain permit for patch/paint wall at south side, and for replacing damaged floor tiles and entry way as well as painting floor tiles at entryway.

Owner - LLNI LLC

Code Enforcement Officer Correa