

# *Alhambra Circle Sidewalk Update*

---

December 12, 2023

**CORAL  
GABLES**<sup>®</sup>  
THE CITY BEAUTIFUL




# ARBORIST REPORT



#1



#3



❖ **Tree #1 – Black Olive 24” DBH**

- Poor Condition (35%)
- Could Remain


❖ **Tree # 3 – Black Olive 26” DBH**

- Poor Condition (35%)
- Could Remain

# ARBORIST REPORT



#7




- ❖ Tree #7 – Black Olive 18" DBH
- Poor Condition (35%)
- Could Remain

# ARBORIST REPORT



#10




- ❖ Tree #10 – Black Olive 28" DBH
- Poor Condition (30%)
- Remove

# ARBORIST REPORT



#16




- ❖ Tree #16 – Black Olive 20" DBH
- Poor Condition (30%)
- Remove

# SUMMARY



- ❖ Sixteen (16) Trees included in report
  - Two (2) to be removed
- ❖ Sidewalk to be constructed with concrete curb from South of Salvatierra Drive to Trevino Ave
- ❖ Sidewalk to shift behind two (2) trees for residence on NWC of Trevino Ave

 Calvin, Giordano & Associates, Inc. EXCEPTIONAL SOLUTIONS™		<b>Inspectors Observation Report</b>	
<input checked="" type="checkbox"/> Fort Lauderdale Office - 1800 Eller Drive - Suite 600 - Fort Lauderdale, FL 33316 - 954.921.7781(p) - 954.921.8807(f) <input type="checkbox"/> West Palm Beach Office - 560 Village Boulevard - Suite 340 - West Palm Beach, FL 33409 - 561.684.6161(p) - 561.684.6360(f)			
Date: 10/5/2023	Time: 04:00	<input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	Weather: <input type="checkbox"/> Sunny & Clear <input checked="" type="checkbox"/> Partly Cloudy <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Cool <input type="checkbox"/> Hot <input type="checkbox"/> Windy <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Humid
Watering Method: <input type="checkbox"/> Working Irrigation <input type="checkbox"/> Hand Watered <input checked="" type="checkbox"/> None (unknown)		Days since last rain event: Unknown	
Project Number: 23-7817	Project Name: City of Coral Gables - Arborist Services - Alhambra Circle		
Contractor:	Type of Work: Tree Inspections and Assessments		
Inspected by: Mike Conner	Reviewed by: Gianni Feoli		
MATERIAL INSPECTED:	INSPECTION EQUIPMENT:		
16 Large Black Olives and Live Oak trees on Alhambra Circle.	Camera/Calliper tape		
CONTRACTOR WORK FORCE (Including Subcontractor personnel):	EQUIPMENT IN USE:		
SUMMARY OF CONSTRUCTION ACTIVITIES:			
Field observations, tree assessment data collections, & photographs.			
SUMMARY OF OBSERVATION:			
The City of Coral Gables's Transportation Division Manager, Melissa DeZayas, requested to have an Arborist look at sixteen (16) large Black Olive and Live Oak trees located on the west side of Alhambra Circle where a proposed sidewalk is to be constructed in order to determine if the trees can remain (with some type of root pruning or special sort of sidewalk construction), or if they should be removed. I went to the site to visually inspect all 16 trees. Please see my observations and assessment of these trees attached.			
DISTRIBUTION:			
Melissa DeZayas, Coral Gables Gianni Feoli, CGA			
Reviewed by: Mike Conner			Date: 10/9/2023
Alhambra Circle - Trees Assessment Reports - 10-9-2023		1 of 25	

*Thank you!*

---

Public Works Department: *Keeping the City Beautiful Yesterday, Today & Tomorrow*

[PWDepartment@coralgables.com](mailto:PWDepartment@coralgables.com)

**CORAL  
GABLES**  
THE CITY BEAUTIFUL