ADDITIONAL WORK UNDERTAKEN DURING RESTORATION REPLACED OUTDATED ELECTRICAL





ADDITIONAL WORK UNDERTAKEN DURING RESTORATION INSTALLED COPPER GUTTERS




ADDITIONAL WORK UNDERTAKEN DURING RESTORATION INSTALLED COPPER GUTTERS (CONTINUED)



ADDITIONAL WORK UNDERTAKEN DURING RESTORATION

REMOVED NON-ORIGINAL DROPPED CEILING TO ESTABLISH ORIGINAL CEILING HEIGHTS



ADDITIONAL WORK UNDERTAKEN DURING RESTORATION

REMOVED NON-ORIGINAL DROPPED CEILING TO ESTABLISH ORIGINAL CEILING HEIGHTS (CONTINUED)



