

PERMIT BL18042837

NEED FINALS: BUILDING-NEED ACCESS FOR DOOR ALARM

PW-REPLACE ALL DAMAGED SIDEWALKS, SEPARATE PUBLIC WORKS PERMIT IS REQUIRED.  
LEVEL AND RESOD ALL DAMAGED AREAS.

ZONING-POOL ENCLOSURE NOT COMPLETE.

POOL ENCLOSURE NOT AS PER APPROVED SET OF PLANS.  
LEVEL AND RESOD DAMAGED AREAS.

POOL EQUIPMENT SCREENING NOT COMPLETE

Permits

File Edit Record Navigate Form Reports Format Tab Help

Jump 1



Main Custom Fjelds Plan Routing Actions Routing History Fees Fee Summary Parcels Contractors Sub Permits

Permit # BL-18-04-2837 Address 6621 SANTONA ST  
CORAL GABLES FL 33146-3111  
Permit type POOL / SPA / FOUNTAIN / POND

Tab Groups

Toolbox

Group	Action Code	Action Description	Completion Date	Complete Code
1	PLAN REVIEW	Routed		
2	PLAN PROCESSING	Routed		
3	CASHIER	Routed		
4	NOTICE OF COMMENCEMENT	Routed		
5	LANDSCAPE PLAN REVIEW	Routed		
6	INSPECTION	Hold		
6	pcompdate	REQUIRED PERMIT COMPLETION DATE	07/15/2020 08:43:00 AM	<input checked="" type="checkbox"/> comp
6	bi084	FINAL BUILDING		<input type="checkbox"/>
6	bi084	FINAL BUILDING	10/19/2018 03:32:48 PM	<input checked="" type="checkbox"/> reject
6	pw837	FINAL PUBLIC WORKS (BLDG PERMIT)		<input type="checkbox"/>
6	pw837	FINAL PUBLIC WORKS (BLDG PERMIT)	10/19/2018 01:14:40 PM	<input checked="" type="checkbox"/> reject
6	zn004	FINAL ZONING		<input type="checkbox"/>
+ 🔍	6 zn004	FINAL ZONING	10/19/2018 12:00:00 AM	<input checked="" type="checkbox"/> reject
6	zn004	FINAL ZONING	04/17/2019 02:33:48 PM	<input checked="" type="checkbox"/> cancel
6	bi213	POOL STEEL & MAIN DRAIN	08/06/2018 02:35:14 PM	<input checked="" type="checkbox"/> apvd
6	zn264	SETBACK INSP- FOUNDATION SURVEY RE	07/18/2018 03:13:33 PM	<input checked="" type="checkbox"/> reject
6	zn264	SETBACK INSP- FOUNDATION SURVEY RE	08/03/2018 03:24:12 PM	<input checked="" type="checkbox"/> apvd
6	bi981	STORMWATER, EROSION AND SEDIMENTA	10/19/2018 03:32:48 PM	<input checked="" type="checkbox"/> apvd

Group Title INSPECTION Group Status Hold