



# City of Coral Gables INSPECTOR'S REPORT

Building, Code Enforcement and Public Works

INSPECTION NO.: \_\_\_\_\_

3 | 11 | 2022

Date  
8:30AM  
Time

Permit No: \_\_\_\_\_ Project Name: 115 Frow Ave Address: Coral Gables, FL.

**Department:**

- Building
- Code Enforcement
- Public Works

**Purpose of visit:**

- Random or periodic check
- Scheduled inspection
- Investigate reported problem
- MOT
- Meeting at Department
- Other: \_\_\_\_\_

**Action taken:**

- No action
- Warning
- Red tag
- STOP WORK
- Other: \_\_\_\_\_

Individuals present: Noel Polo (P.W.) Photos taken:  Yes  No  
P.W. SANITARY DIVISION

**Summary of findings:  
(REQUIRED)**

- ① PUBLIC WORKS SEWER DIVISION CONDUCTED A MAIN SEWER LINE LOCATION FOR THE LATERAL BRANCH TO 115 FROW AVE.
- ② LATERAL DOES EXISTING BUT, NO SEWAGE FLOWS TO SEWER DUE TO BROKEN SANITARY DRAINAGE PIPING UNDER RESIDENCE.

**Action required:  
(REQUIRED)**

- ① Required PLANS & Permit For Plumbing Repairs.
- ② ADVISE CODE ENFORCEMENT TO SITE PROPERTY & DEVELOPMENT SERVICES

**ACKNOWLEDGEMENT OF WARNING**

\_\_\_\_\_  
Qualifier / Agent signature

\_\_\_\_\_  
Print name and title

R. PEREZ # 9462  
Inspector name

[Signature]  
Signature