

BEFORE PHOTOS

EXTERIOR ARCHITECTURAL FEATURES

FEATURE 1: ORIGINAL WINDOWS WITH STAINED GLASS



PHOTO #1



PHOTO #2

FEATURE 2: ORIGINAL WROUGHT IRON WORK



PHOTO #3 ↗

PHOTO #4 ↘



FEATURE #3: RE-ESTABLISHING ORIGINAL GARAGE



PHOTO #5



PHOTO # 33

FEATURE #3: RE-ESTABLISHING ORIGINAL GARAGE (CONTINUED)



PHOTO #34



PHOTO
#35



FEATURE # 4: RE-ESTABLISHING REMOVED WINDOWS



PHOTO #6

FEATURE #5: EXTERIOR (REAR OF HOME)



PHOTO #19



PHOTO #20

FEATURE #5: EXTERIOR (REAR OF HOME) CONTINUED



PHOTO # 21




PHOTO # 22

FEATURE #5: EXTERIOR (REAR OF HOME) CONTINUED



PHOTO # 23 ↗

PHOTO # 24
↳



FEATURE #5: EXTERIOR (REAR OF HOME) CONTINUED



PHOTO #25




PHOTO #26

FEATURE #5: EXTERIOR (REAR OF HOME) CONTINUED



PHOTO #27

FEATURE #6: ACCESSORY BUILDING




PHOTO # 28



PHOTO # 29

FEATURE #6: ACCESSORY BUILDING (CONTINUED)



PHOTO #30



PHOTO #31

FEATURE # 6: ACCESSORY BUILDING (CONTINUED)



PHOTO # 32