



Figure 1

Coral Gables Merrick House (CGMH), south / front façade, pre-1920s

All images courtesy of the City of Coral Gables Historical Resources Department unless otherwise noted.



Figure 2
CGMH, south / front façade (before) 2014



Figure 3
CGMH, south / front façade (after), 2019



Figure 4
CGMH, northwest corner (before), 2014



Figure 5
CGMH, northwest corner (after), 2019



Figure 6
CGMH, north / rear façade (before), 2014



Figure 6a
CGMH, north / rear façade (during), 2017



Figure 7
CGMH, north / rear façade (after), 2018



Figure 8
CGMH, east façade at sunroom (before), 2014



Figure 9
CGMH, east façade at sunroom (after), 2019



Figure 10
CGMH, auxiliary structure – east / front façade (before), 2014



Figure 11
CGMH, auxiliary structure – east / front façade (after), 2019



Figure 12
CGMH, auxiliary structure – second floor, looking west (before), 2014



Figure 13
CGMH, auxiliary structure – second floor, looking west (after), 2019



Figure 14
CGMH, hallway, looking north (before), 2014



Figure 15

CGMH, hallway, looking north (after), 2017 *Photo by Dan Forer Photography, 2017
Courtesy of MC Harry & Associates, Inc.



Figure 16
CGMH, living room, looking north (before), 2014



Figure 17

CGMH, living room, looking north (after), 2017 *Photo by Dan Forer Photography, 2017
Courtesy of MC Harry & Associates, Inc.



Figure 18
CGMH, second floor bathroom, looking east (before), 2014



Figure 19
CGMH, second floor bathroom, looking east (after), 2019



Figure 20
CGMH, second floor west bedroom, looking north (before), 2017



Figure 21
CGMH, second floor west bedroom, looking north (after), 2018