## MIAMI-DADE COUNTY HISTORIC PRESERVATION AD-VALOREM TAX EXEMPTION

2015 MAY 15 AM 11: 35



## **PART 1 – PRECONSTRUCTION APPLICATION**

## **INSTRUCTIONS:**

Type or print clearly in black ink. You may attach additional sheets if more space is needed.

I.	PROPERTY IDENTIFICATION AND LOCATION		
	Historic/Site Name:		
	Property Address:	239 Sarto Ave., Coral Gables, FL 33134	
	Folio Number:	03-417-007-0710	
	Legal Description:	Coconut Grove Sec 1-Coral Gables	
	Lots 41 \$ 42 and West 1/2 of 10+40.		
Please check all that apply:			
	[ ] Designated as	s a local historic landmark or site s a contributing structure within a local district sted in the National Register of Historic Places ing structure in a National Register District	
	Name of Dist	rict	
	Please attach the des designated.	ignation report and resolution as proof the property is	
11.	OWNER INFORMATION		
	Name(s) of Owner(s):	Venancio I. Torre & Wayra Palengue Torre	
	Mailing Address:	441 VOLETCIA AVE PH	
		COPAL COAPLES FL 33134	
	Phone: (305) 442 - 9	2 <sup>nd</sup> Phone: 305 · 332 - 5700	
		torrecompanies. Com ple owners, please attach a list of all owners and their mailing	

## III. CURRENT PHYSICAL DESCRIPTION OF PROPERTY:

A.	General Information			
	Date of Construction: 1941 Architect (if known): H. George Fink			
	Alterations: Please provide the date and description of any physical alterations to the property. [Example: Original casement windows were replaced with jalousie windows around 1974.]  Performance NEST 2005.			
	Additions: Please provide date and description of any additions which may have been made. [Example: A rear bedroom and bath were added to the house in 1981.]			
В.	Exterior Description			
	Roof Type: Roof Material: FLAT_ TILE (WHITE)  Example: hip, gable, flat, etc			
	Number of Stories: Detached Garage? (Y/N)_++0			
	Basic Floor Plan: Example: square, "L" shaped, "U" shaped, rectangular, irregular, etc			
	Main Window Type(s):			
	Example: casement, fixed, single hung sash, jalousie, awning, etc  Siding Material(s):			
	Example: stucco, wood frame, brick			
	Briefly describe any distinguishing Exterior Architectural Features:  [Example: the placement of the windows, chimneys, porches, columns, etc]			
	FRATT DORGH W DECOPATIVE APT DECO WRONGHIROH CO			

\* SLUMP BRICK DETAILING @ FRONT OF HOUSE

\* COPATICE TREATMENT

HP Ad Valorem Application Updated 1/2014

## C. Interior

Please list any distinguishing Interior Architectural Features found in the home that are original to the house, by room: [Example: The dining room retains the original decorative crown molding and tile floor. The living room retains the original limestone fireplace.]

ORIGINAL DECOPATIVE ART DECO FIREPLACE (HEAPINT ORIGHAL OBE FLOORS OPIGIHAL SINGLE PAHEL DOORS WI FLUTED CASE MOLDINGS SCREEN POPUL TILE FLOOR IROH SCROLLS DECOPATION @ SCREEN POPUL (ART DECO).

## **D.** Auxiliary Structures

Please describe the present appearance of any auxiliary structures on the property, such as garages, cabanas, outbuildings, perimeter walls, etc.

#### IV. **DESCRIPTION OF PROPOSED IMPROVEMENTS**

All improvements to historic properties will be evaluated for their consistency with the Secretary of Interior Standards for Rehabilitation. The application must include labeled photographs of both the interior and exterior of the property which clearly show the property and its characteristics.

What was the original use of the building? SIHOUE FAMILY PES.
What will the building be used for after improvements?
What is the estimated start date of construction?
What is the estimated completion date?
What is the estimated cost of restoration/rehabilitation?
Briefly describe your project, including any proposed additions, upgrades and

restorations.

### A. EXTERIOR ARCHITECHTURAL FEATURES

The following represents an itemization of work to be accomplished. List each principal architectural feature affected and describe the impact that restoration/rehabilitation will have on it. Label which elevation(s) contains that feature, and include a corresponding photograph for each. Please attach additional sheets if necessary.

**FEATURE 1:** Elevation: SOUTH Photo Number: 12, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12 Plan Number: **Describe Work and Impact on Existing Feature:** REPLACE WINDOW SHUTTERS WITH AUTHENTIC PEPLACEMENT REMOVE SOLAR PAHEIS OH POOF, REPAIR POOF, CHANGE WINDOWS TO ALUM. CASEMENT TO MATCH EXISTING RESTORE SCREEN PORCH PESTORE SCREEN DOOR, REFINISH WROUGHT 1201 DECORATIVE PAHELS @ PORCH, PAINT HOUSE, RESTORE CORNICE MOLDINGS Elevation: WEST (LEFT SIDE)

PESTOPE/PEPAINT POPULA WINDOW

Photo Number:

13 14 15 16, 17

PEMOVE AND PEPVACE DRIVEWAY **Plan Number:** STRIPS (COHCRETE) Describe Work and Impact on Existing Feature: --RESTORE/PERCONSTRUCT SIDE POPULIT ROOF OVERHAND AT DOOP to KITCHEH, PESTORE CRIN BLOCK OPENING @ GARAGE PANT WALLS AND STEDS.

Elevation: REAR ELEVADOH (NORTH SIDE)

Photo Number: 18

**Plan Number:** 

Describe Work and Impact on Existing Feature: REMOVE HURPICAME SHUTTERS OF WITH DOWS REPLACE WITHDOWS WI NEW ALLMINUM CASEMENT WITHDOWS TO MATCH EXISTING. CUT WITHDOW OPENING OF DITHING TO MAKE DOOD OPENING TO FEAT PATO. ADDITION FEATURE 4:

Elevation: EAST ELEVATION (RIGHT SIDE)

Photo Number: 19, 20

**Describe Work and Impact on Existing Feature:** 

REMOVE HYPRICAME SHUTTERS, REPLACE WITHOUS WINEW ALLMINUM CASEMENT WITHDOWS TO MATCH EXISTING PAGE 8 of 16

## B. INTERIOR ARCHITECHTURAL FEATURES

FEATURE 1:
ROOM: LIVING ROOM & DIHING ROOM
Photo Number: 21, 22, 23, 24, 25
Plan Number:
Describe Work and Impact on Existing Feature:
PEFINISH ALL DOOPS, MOLDINES AND TRIM THROUGHOUT
PEFINISH FIREPLACE MANTLE PEFINISH OAK FLOOPS PESTOPE DOOR HAPDWAPE, NEW MASSER WING AND CLOSET FEATURE 2:  ROOM: BATHLOOMS
PESTOPE DOOR HAPDWAPE, NEW MASTER WING AND GLOSET
FEATURE 2:
Photo Number: 24, 27
Plan Number:
Describe Work and Impact on Existing Feature:
TOTE THE FLOOR WALLS AT HALL BISTH, PEFIHISH BAPHTUP
RESTORE THE (FLOOR WALLS) AT HALL BATH PEFIHISH BATHTUP RESTORE WALLS, HEN LIGHTING AND MEDICINE CARRINET
AND INSTALL HOW PLUMING FIXTURES AND TOILET
AND INSTALL HEN PLIMING FIXTURES AND TOILET DEMO OLD MASTER BATH AND REPLACE WI NEW HISTORICALLY FEATURE 3:
ROOM: KITCHEH  COPPEUT AT HEW WITH  COPPEUT AT HEW WITH
Photo Number: 28, 29
Plan Number:
Describe Work and Impact on Existing Feature:
PEPUACE FITCHEST CABINHETPY WITH HISTOPICALLY CORPECT HEW CAPSIHETS TO MATCH EXISTING, NEW CHECKERED THE
HEW CAPSIHETS TO MATCH EXISTING HEW CHECKEDED THE
FLOOP REFIHISH WALLS AND CEILING. HEW LIGHTS.
FEATURE 4:
Room:
Photo Number:

**Describe Work and Impact on Existing Feature:** 

**Plan Number:** 

#### C. **LANDSCAPE FEATURES**

Please list any restorative work to be done to original landscape features, including pathways, walls, fountains, etc. Include a site plan or sketch if necessary.

**FEATURE 1:** 

Photo Number: 30, 3 | Describe Work and Impact on Existing Feature:

MSTALL HEW HEDCOES ASH'S ACCEPT PLOSTING

PESOD AS NECESSAPY.

**FEATURE 2:** 

**Photo Number:** 

**Describe Work and Impact on Existing Feature:** 

**FEATURE 3:** 

**Photo Number:** 

**Describe Work and Impact on Existing Feature:** 

**OWNER ATTESTATION:** I hereby attest that the information provided in this application is, to the best of my knowledge, correct, and that I own the property described above or that I am legally the authority in charge of the property. Further, by submission of this Application, I agree to allow access to the property by representatives of the appropriate official in which the property is located, for the purpose of verification of information provided in this Application. I also understand that, if the requested exemption is granted, I will be required to enter into a Covenant with the municipality and Miami-Dade County in which I must agree to maintain the character of the property and the qualifying improvements for the term of the exemption.

Print Name\*


Signature

Date

[Please attach the photographic documentation on subsequent pages. Submit a copy of all photographs to County staff on a CD as well, if possible.]

# PRE-CONSTRUCTION APPLICATION REVIEW TO BE FILLED OUT BY THE LOCAL HISTORIC PRESERVATION OFFICER

Street Address of property 239 SARTO AVE, COPAL CARPILES 3313  Folio number 03-4117-007-0710
Folio number 03-4117-007-0710
The local Historic Preservation Officer has reviewed Part 1 (Preconstruction Application) of the Historic Preservation Property Tax Exemption Application for the above named property and hereby:
[ ] Certifies that the above referenced property <u>qualifies as a historic property</u> consistent with the provisions of s. 196.1997 (11), F.S.
[ ] Certifies that the above referenced property <u>does not qualify</u> as a historic property consistent with the provisions of s. 196.1997 (11), F.S.
[ ] Determines that improvements to the above referenced property <u>are consistent</u> with the Secretary of Interior Standard's for Rehabilitation and Guidelines for Rehabilitating Historic Buildings and the criteria set forth in Chapter 1A-38, F.A.C.
[ ] Determines that improvements to the above referenced property <u>are not consistent</u> with the Secretary of Interior Standard's for Rehabilitation and Guidelines for Rehabilitating Historic Buildings and the criteria set forth in Chapter 1A-38, F.A.C.
Please list any Review Comments here:
Additional Review Comments attached? Yes [ ] No [ ]
Signature:
Typed or printed name:
Title:
Date of Review:






Photo: 2



Photo: 3






Photo: 5





Photo: 6




























Photo: 16




Photo: 17



