# Property Search Application - Miami-Dade County OFFICE OF THE PROPERTY APPRAISER

## **Summary Report**

Generated On: 10/27/2015

Property Information				
Follo:	03-4117-005-2580			
Property Address:	241 ALMERIA AVE			
Owner	BROCKWAY LTD			
Mailing Address	297 ALMERIA AVE CORAL GABLES , FL 33134-5903			
Primary Zone	6600 COMMERCIAL - LIBERAL			
Primary Land Use	2719 AUTOMOTIVE OR MARINE : AUTOMOTIVE OR MARINE			
Beds / Baths / Half	0/0/0			
Floors	1			
Living Units	0			
Actual Area	Sq.Ft			
Living Area	Sq.Ft			
Adjusted Area	2,350 Sq.Ft			
Lot Size	5,006 Sq.Ft			
Year Built	1955			

Assessment Informat	lon	×	
Year	2015	2014	2013
Land Value	\$690,828	\$690,828	\$600,720
Building Value	\$470,000	\$213,334	\$100,000
XF Value	\$0	\$0	\$0
Market Value	\$1,160,828	\$904,162	\$700,720
Assessed Value	\$847,871	\$770,792	\$700,720

Benefits Information					
Benefit	Туре	2015	2014	2013	
Non-Homestead Cap	Assessment Reduction	\$312,957	\$133,370		
Note: Not all hapafite are applicable to all Tayable Values (Le. County					

School Board, City, Regional).

Short Legal Description	
CORAL GABLES CRAFTS SEC	
PB 10-40	
LOTS 33 & 34 BLK 10	
LOT SIZE 50.060 X 100	
OR 12575-1399 1284 4	



Taxable Value Informa	ation		
	2015	2014	2013
County	<u> </u>	-	
Exemption Value	\$0	\$0	\$0
Taxable Value	\$847,871	\$770,792	\$700,720
School Board			
Exemption Value	\$0	\$0	\$0
Taxable Value	\$1,160,828	\$904,162	\$700,720
City			
Exemption Value	\$0	\$0	\$0
Taxable Value	\$847,871	\$770,792	\$700,720
Regional			
Exemption Value	\$0	\$0	\$0
Taxable Value	\$847,871	\$770,792	\$700,720

Sales Inform	nation		
Previous Sale	Price	OR Book- Page	Qualification Description
09/01/1972	\$55,000	00000- 00000	2008 and prior year sales; Qual by exam of deed

The Office of the Property Appraiser is continually editing and updating the tax roll. This website may not reflect the most current information on record. The Property Appraiser and Miami-Dade County assumes no liability, see full disclaimer and User Agreement at http://www.miamidade.gov/info/disclaimer.asp

Version:





Development Services Department CITY HALL 405 BILTMORE WAY CORAL GABLES, FLORIDA 33134

4/20/2015

VIA CERTIFIED MAIL

BROCKWAY LTD 297 ALMERIA AVE CORAL GABLES, FL 33134-5903

RE: 241 ALMERIA AVE, Coral Gables, Florida Folio # 03-4117-005-2580 Recertification of Building 40 Years or older

#### Gentlemen:

This Department has been advised the above referenced property address is forty (40) years old, or older, having been built in 1955.

In accordance with the Miami-Dade County Code, Chapter 8, Section 8-11(f), a Florida Registered Architect or Professional Engineer must inspect said building and a report must be furnished to this Department within ninety (90) days from the date of this letter indicating the building meets the requirements of building recertification under the Code. In the event the repairs or modifications are found to be necessary resulting from the recertification inspection, the owner shall have a total of one hundred fifty (150) days from the date of this letter in which to complete the indicted repairs or modifications.

The architect or engineer chosen to perform the inspection may obtain the required Form, "Minimum Inspection Procedural Guidelines for Building Recertification," from the link below: <a href="http://www.miamidade.gov/building/form-checklist.asp">http://www.miamidade.gov/building/form-checklist.asp</a>. In addition to the Form a cover letter must state the property meets the requirement for building recertification; no additional documents or photographs are necessary.

The certification report, along with the filing fee in the amount of \$380.63; plus, \$2.45 per page Document Preservation Fee must be paid with a check or credit card payable to the "City of Coral Gables," and sent/delivered to:

#### **BUILDING RECERTIFICATION SECTION**

Development Services Department 405 Biltmore Way, 3<sup>rd</sup> Floor Coral Gables, Florida 33134

Any questions may be directed to (305) 460-5250. Thank you for your prompt consideration.

Sincerely,

Manuel Z. Lopez, P.E. Building Official

Manuel Z. Lopez

CITY'S
EXHIBIT 2



#### The City of Coral Gables

#### **Development Services Department**

CITY HALL 405 BILTMORE WAY CORAL GABLES, FLORIDA 33134

August 17, 2015

**VIA CERTIFIED MAIL** 

91 7108 2133 3932 5928 3212

Brockway LTD 297 Almeria Avenue Coral Gables, Fl 33134-5903

Re: 241 Almeria Avenue

Folio # 03-4117-005-2580

Dear Property Owner/Manager:

This Department has received your request dated August 12, 2015 for an extension to provide us with the Recertification Report for the above referenced property.

By these means, I am granting you sixty (60) days from the date of this letter to provide the Recertification Report. If you have further questions please contact me at (305) 460-5242.

Sincerely,

Manuel Z. Lopez, P.E.

Manuel Z. Lope;

Building Official



ORIGINAL

# CBUILDERS + GROUP

7301 Southwest 83 Court, Miami, Florida 33143

Telephone 305.275.6310 Facsimile 305.275.6309

Lic. AAC001931

RE: 03-4117-005-2580

**DATE: October 16, 2015** 

OWNER NAME:

Brockway LTD.

**Property Address:** 

241 Almeria Avenue, Coral Gables, Florida

**City of Coral Gables Building Department:** 

Dear Mr. Manuel Lopez, P.E., Building Official:

Based on my evaluation as attached hereto of the aforementioned property, this building is electrically safe however requires building/structural correction for a safe continued use and occupancy as provided for Re-Certification.

Therefore, on behalf of my client, I am respectfully requesting that this building(s) be \*granted Re-certification per Section 8-11(f) of the Code of Miami-Dade County upon the proper completion, verification of same by our office of the item(s) as contained herein and our subsequent written notification to your office.

As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure(s). To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building(s) based upon the careful evaluation of the observed conditions, to the extent reasonably possible.

Thank you for your attention to this matter.

Very trul

DCT16.0015 Rick Hernandez Capote, A.I.A.

President, AR13379

Dade County Building and Roofing Inspector BN2418

Special Inspector State of Florida No.0976

#### Additional

Comments: \*This report is prepared and is to be submitted to the Building Official as may be required for Re-Certification as referenced above, this report is not intended to be a Due Diligence (buyer/seller) inspection report nor is it to be used for any other purpose than that specifically stated herein. No permit or property history was either made available, examined or verified for purposes of this report. Any required corrections/repairs/alterations must be in compliance with FBC, NEC and all applicable codes and ordinances. Should any violations or open permits exist all must be corrected prior to granting of Re-Certification.



#### The City of Coral Gables

Development Services Department City Hall 405 Biltmore Way Coral Gables, Florida 33134

BROCKWAY LTD 297 ALMERIA AVE CORAL GABLES, FL 33134 4/20/2015 \_ 5/ \_ 6/20 \_ - 7/20

VIA CERTIFIED MAIL

91 7108 2133 3932 6147 1430

RE: 241 ALMERIA AVE, Coral Gables, Florida Folio # 03-4117-005-2580 Recertification of Building 40 Years or older

Gentlemen:

This Department has been advised the above referenced property address is forty (40) years old, or older, having been built in 1955.

In accordance with the Miami-Dade County Code, Chapter 8, Section 8-11(f), a Florida Registered Architect or Professional Engineer must inspect said building and a report must be furnished to this Department within ninety (90) days from the date of this letter indicating the building meets the requirements of building recertification under the Code. In the event the repairs or modifications are found to be necessary resulting from the recertification inspection, the owner shall have a total of one hundred fifty (150) days from the date of this letter in which to complete the indicted repairs or modifications.

The architect or engineer chosen to perform the inspection may obtain the required Form, "Minimum Inspection Procedural Guidelines for Building Recertification," from the link below: <a href="http://www.miamidade.gov/building/form-checklist.asp">http://www.miamidade.gov/building/form-checklist.asp</a>. In addition to the Form a cover letter must state the property meets the requirement for building recertification; no additional documents or photographs are necessary.

The certification report, along with the filing fee in the amount of \$380.63; plus, \$2.45 per page Document Preservation Fee must be paid with a check or credit card payable to the "City of Coral Gables," and sent/delivered to:

BUILDING RECERTIFICATION SECTION
Development Services Department
405 Biltmore Way, 3<sup>rd</sup> Floor
Coral Gables, Florida 33134

Ugoizueta@66.com

Any questions may be directed to (305) 460-5250. Thank you for your prompt consideration.

Sincerely,

Manuel G. Lopez

Manuel Z. Lopez, P.E. Building Official

MINIMUM INSPECTION PROCEDURAL GUIDELINES FOR BUILDING RECE

INSPECTION COMMENCE DATE: August 24, 2015

INSPECTION COMPLETED DATE: August 24, 2015

MUST BE SIGNED AND SEALED BY ARCHITECT OR ENGINEER

INSPECTION SIGNATURE:

PRINT NAME | Rick Hernandez-Capote, R.A. TITLE: AR 13379, AAC001931

The minimum

ADDRESS: 7301 SW 83 Court

Miami-Dade, FL 33143

(305) 275-6310 PHONE:

FAX:

(305) 275-6309

- 1. Description of Structure:
  - a. Name or Title: BROCKWAY LTD.
  - b. Property address: 241 ALMERIA AVENUE, CORAL GABLES FL.
  - Legal description: CORAL GABLES CRAFTS SEC PB 10-40
  - Owner's name: Same as title đ.
  - Owner's mail address: 297 ALMERIA AVENUE, CORAL GABLES FL. 33134
  - Building Official Folio Number: 03-4117-005-2580
  - Building Code Occupancy Classification: COMMERCIAL
  - Present use: REPAIR SHOP
  - General description, type of construction, size, number of stories, and special features. CBS, one story, per Dade County Property Appraiser was built 1955, and has 2,350 ASF.
  - j. Additions to original structure: NONE OBSERVED at time of inspection. No property permit history was either made available or reviewed for purposes of this report. Areas inspected were those made available by property owner/representative on day of inspection. All gas lines, meters and appliances and equipment are specifically excluded for purposes of this report, however we urge property owner to take any and all necessary precautions to assure that these items are properly maintained to protect property and above all life safety.
- Present Condition of Structure: 2.
  - General alignment (note, good, fair, poor, explain if significant)
    - 1. Bulging- FAIR, for age of structure
    - 2. Settlement- FAIR, for age of structure
    - 3. Deflections - FAIR, for age of structure
    - Expansion- FAIR, for age of structure
    - 5. Contraction- FAIR, for age of structure

This report is not a Buyers Report, Due Diligence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official solely in accordance and with the purpose of compliance with Section 8-11 (f) of the Code of Miami-Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all content. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, it is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and flability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

b. Portions showing distress (note beams, columns, structural walls, floors, roofs, other)

ROOF FRAMING AND STRUCTURE ARE CONCEALED, UNABLE TO DETERMINE TYPE OF STRUCTURE. NO DRAWINGS HAVE BEEN MADE AVAILABLE. FLAT MODIFIED BITUMEN ROOF SEEMINGLY IN POOR CONDITION, OWNER IS REQUIRED TO HAVE AN UPLIFT TEST AND MOISTURE TEST COMPLETED, IN ORDER TO HAVE PROVIDE A PROPER ASSESSMENT. TOTAL RE -ROOF AND REPAIRS MAY BE REQUIRED. Any required corrections/repairs/alterations must be in compliance with FBC, NEC and all applicable codes and ordinances. This report is not for bidding or for permitting purposes. Additionally, property owner is responsible and liable to continuously maintain property safe for continued use and occupancy.

Surface conditions - describe general conditions of finishes, noting cracking, spalling, peeling, signs of moisture penetration and stains.

Surface conditions have normal appearance 50 years +. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

d. Cracks - note location in significant members. Identify crack size as HAIRLINE if barely discernable; FINE if less than 1mm in width; MEDIUM if between 1 and 2 mm in width; WIDE if over 2mm.

Normal condition for age and use of structure. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

 General extent of deterioration - cracking or spalling of concrete or masonry; oxidation of metals; rot or borer attack in wood.

Normal condition for age and use of structure. Provide continued observations and inspections for termites and other possible agents that may cause deterioration, due to age of building. Also proactive preventive maintenance should be practiced. No testing for termites, other pest, deteriorating agent, contaminant or other is part of this examination or report. Fumigation to be provided on a regular basis by owner as needed.

f. Previous patching or repairs

Continue preventative maintenance and repairs as may be necessary. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

g. Nature of present loading - indicate residential, commercial, other estimate magnitude.

Structural COMMERCIAL loading TO remain stable UPON COMPLETION OF ITEMS LISTED IN 2B, built 1955.

h. Availability of original construction drawings - location description

Not at premise, during visual observations.

#### 3. Inspections:

- a. Date of notice of required inspection: 4/20/2015
- b. Date(s) of actual inspection: AUGUST 24, 2015
- c. Name and qualification of individual submitting inspection report: RICARDO HERNANDEZ-CAP
  - Rick Hernandez-Capote, R.A. AR13379, AAC001931
- d. Description of any laboratory or other formal testing, if required, rather than manual or visual procedures:

This report is <u>not</u> a Buyers Report, Due Diligence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official <u>solely</u> in accordance and with the purpose of compliance with Section 8-11 (i) of the Code of Miami-Dade County, any other use is strictly prohibited and volds all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and volds all content. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, <u>nothing</u> in this report should be construed directly or indirectly as a guarantee for <u>any</u> portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, It is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and liability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

Visual observations conducted at present. This report is a "snapshot" of observed conditions of accessible and applicable components on the day of inspection. No testing is part of this report. Additionally, we rely on the validity of documentation as may be provided by owner for repairs performed to their property and for which they are solely responsible and liable for assuring they meet proper compliance with all applicable codes and life safety. Owner is to conduct proactive preventive maintenance to include any possible testing that may be necessary. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

- e. Structural repair note appropriate line:
  - 1. None required- ( )
  - 2. Required- ( XX )- PLEASE REFER TO 2B.
- 4. Supporting data:
  - a. See this report, sheets written data and hold harmless executed by owner.
  - b. N/A photographs.
  - c. N/A drawings or sketches.
- 5. Masonry Bearing Walls indicate good, fair, poor on appropriate lines:
  - a. Concrete masonry units- FAIR, for age of structure.
  - b. Clay tile or terra cotta units- N/A
  - Reinforced concrete tie columns- FAIR, for age of structure.
  - d. Reinforced concrete tie beams- FAIR, for age of structure.
  - e. Lintels- FAIR, for age of structure.
  - f. Other type bond beams- FAIR, for age of structure.
  - g. Masonry finishes exterior:
    - Stucco- FAIR, for age of structure.
    - Veneer- FAIR, for age of structure.
    - Paint only- FAIR, for age of structure.
    - 4. Other (describe) N/A
  - h. Masonry finished interior:
    - Vapor barrier- Seemingly watertight at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to sature building is safe for continued use and occupancy.
    - 2. Furring and plaster- FAIR appearance
    - Panelling- FAIR appearance
    - Paint only- FAIR appearance
    - 5. Other (describe) N/A

This report is <u>not</u> a Buyers Report, Due Diligence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official <u>solely</u> in accordance and with the purpose of compliance with Section 8-11 (f) of the Code of Miami-Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all content. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, <u>nothing</u> in this report should be construed directly or indirectly as a guarantee to any portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, it is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and liability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

- i. Cracks:
  - 1. Location note beams, columns, other- Exterior bearing walls
  - Description- Normal age stress cracks hairline.
- j. Spalling:
  - 1. Location note beams, columns, other- None observed
  - 2. Description- N/A
- k. Rebar corrosion check appropriate line:
  - None visible- (√)
  - 2. Minor Patching will suffice- N/A
  - 3. Significant but patching will suffice- N/A
  - 4. Significant structural repairs required (describe) N/A
- 1. Samples chipped out for examination in spall areas:
  - No- (√)
  - Yes describe color texture, aggregate, general quality- N/A
- 6. Floor and Roof Systems:
  - a. Roof:
    - 1. Describe (flat, sloped, type roofing, type roof deck, condition)

Flat, built up plies roof seemingly in POOR condition for age of building as visibly observed at units/areas made accessible at time of inspection. PLEASE REFER TO 2B. No testing is part of this report. Owner is to assure that roof is properly maintained to include proper drainage, preventive measures and upgrades as may be necessary. Age of roof, life expectancy or guarantee of condition is not part of this inspection report. Owner must keep in mind that the average life expectancy of a roof in South Florida can vary by design, age, maintenance and material. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

Note water tanks, cooling towers, air conditioning equipment, signs, other heavy equipment and condition of supports:

CENTRAL AC equipment, seemingly secure.

3. Note types of drains and scuppers and condition:

POSITIVE FLOW/SLOPED TO DRAIN: POOR condition for age of structure. PLEASE REFER TO 2B.

- b. Floor system(s):
  - 1. Describe (type of system framing, material, spans, condition)

Concrete slabs on fill, ground floor: FAIR condition for age of structure.

c. Inspection - note exposed areas available for inspection and where it was found necessary to opeceilings, etc. for inspection of typical framing members.

Visual observations conducted of open accessible framing.

This report is not a Buyers Report, Due Diligence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official solely in accordance and with the purpose of compliance with Section 8-11 (i) of the Code of Miami-Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all content. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, it is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and liability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

- Steel Framing Systems:
  - a. Description: None observed
  - b. Exposed Steel describe condition of paint and degree of corrosion: N/A
  - c. Concrete or other fireproofing note any cracking or spalling, and note where any covering was remove for inspection.

Visual observations done of open accessible areas on day of inspection

d. Elevator sheave beams and connections, and machine floor beams - note condition:

None

- 8. Concrete Framing Systems:
  - a. Full description of structural system

Concrete masonry units (C.M.U.), Concrete tie beams, grade beams, tie columns.

- b. Cracking:
  - Not significant- Normal age stress cracks.
  - 2. Location and description of members affected and type cracking Exterior bearing walls
- c. General condition:

Seemingly stable concrete framing UPON COMPLETION OF ITEMS LISTED IN 2B, built 1955. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

- d. Rebar corrosion check appropriate line:
  - None visible- (√)
  - Minor Patching will suffice- N/A
  - 3. Significant but patching will suffice- N/A
  - Significant structural repaired (describe) N/A
- e. Samples chipped out in spall areas:
  - 1. No- (√)
  - Yes describe color, texture, aggregate, general quality: N/A
- 9. Windows:

a. Type (wood, steel, aluminum, jalousie, single hung, double hung, casement, awning, pivoted, fixed, other)

AWNING

b. Anchorage - type and condition of fasteners and latches:

Machine screws and bolts

c. Sealants - type and condition of perimeter and sealants & at mullions:

FAIR for age of structure. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

This report is not a Buyers Report, Due Dillgence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official solely in accordance and with the purpose of compliance with Section 8-11 (f) of the Code of Miami-Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all content. Both Bullding (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, it is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and liability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

d. Interior seals - type & condition at operable vents:

FAIR for age of structure. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

e. General condition:

FAIR for age of structure, preventative maintenance should continue. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

#### 10. Wood Framing:

a. Type - fully describe if mill construction, light construction, major spans, trusses:

UNABLE TO VERIFY. PLEASE REFER TO 2B.

- b. Note metal fittings i.e., angles, plates, bolts, split rings, pintles, other and note condition: UNABLE TO VERIFY. PLEASE REFER TO 2B.
- Joints note if well fitted and still closed:

UNABLE TO VERIFY. PLEASE REFER TO 2B. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

d. Drainage - note accumulations of moisture:

Seemingly watertight at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

Ventilation - note any concealed spaces not ventilated:

N/A

f. Note any concealed spaces opened for inspection:

Visual observations conducted of open and visibly accessible spaces.

The second secon

This report is not a Buyers Report, Due Diligence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official solely in accordance and with the purpose of compliance with Section 8-11 (f) of the Code of Miami-Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all content. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, it is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and liability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

MINIMUM INSPECTION PROCEDURAL GUIDELINES FOR BUILDING ELECTRICATION

INSPECTION COMMENCE DATE: August 24, 2015 INSPECTION MADE SIGNATURE:

INSPECTION COMPLETED DATE: August 24, 2015

PRINT NAME: fick Hernandez-Capote, R.A. TITLE: AR 1779, AAC001931

MUST BE SIGNED AND SEALED BY **ARCHITECT** OR ENGINEER ADDRESS: 7301 SW 83 Court

Miami-Dade, FL 33143

PHONE: (305) 275-6310 FAX: (305) 275-6309

- 1. Description of Structure:
  - k. Name or Title: BROCKWAY LTD.
  - Property address: 241 ALMERIA AVENUE, CORAL GABLES FL.
  - m. Legal description: CORAL GABLES CRAFTS SEC PB 10-40
  - n. Owner's name: Same as title
  - o. Owner's mail address: 297 ALMERIA AVENUE, CORAL GABLES FL. 33134
  - p. Building Official Folio Number: 03-4117-005-2580
  - q. Building Code Occupancy Classification: COMMERCIAL
  - r. Present use: REPAIR SHOP
  - s. General description, type of construction, size, number of stories, and special features.

CBS, one story, per Dade County Property Appraiser was built 1955, and has 2,350 ASF.

- either made available or reviewed for purposes of this report. Areas inspected were those made available by property owner/representative on day of inspection. All gas lines, meters and appliances and equipment are specifically excluded for purposes of this report, however we urge property owner to take any and all necessary precautions to assure that these items are properly maintained to protect property and above all life safety.
- ELECTRICAL SERVICE: Overhead service to from FPL, ONE FEEDER FOUR WIRES, and EACH WIRE APPROXIMATELY 4/0
  TN SIZE.
  - a. SIZE: AMPERAGE ( 200 ); FUSES ( ); BREAKER ( XX )
  - b. PHASE:  $3\phi$  ( XX );  $1\phi$  ( );
  - c. CONDITION: GOOD ( ); FAIR ( XX ); NEED REPAIR ( )
  - d. COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.
- 2. METER AND ELECTRICAL ROOM:
  - a. CLEARANCES: GOOD ( ); FAIR ( XX ); CORRECTION REQ. ( )
     COMMENTS: Exterior type meters.

This report is not a Buyers Report, Due Diligence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official solety in accordance and with the purpose of compliance with Section 8-11 (f) of the Code of Miami-Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all contents. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee or new portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, it is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and liability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

#### GUTTERS:

- a. LOCATION: N/A
  GOOD ( ); REQUIRES REPAIR ( )
- b. LOCATION:

GOOD ( ); REQUIRES REPAIR ( )

- c. COMMENTS: N/A
- c. TAPS AND FILL: N/A
  GOOD ( ); REQUIRES REPAIR ( )

#### 4. ELECTRICAL PANELS:

a. PANEL # (1): GOOD (XX); REQUIRES REPAIR ()
Location: As observed at each inspected area, breaker panels. Any required corrections/repairs/alterations must be in compliance with FBC, NEC and all applicable codes and ordinances. This report is not for bidding purposes. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

#### 5. BRANCH CIRCUITS:

- a. IDENTIFIED: YES (√); MUST BE IDENTIFIED ( )
- b. CONDUCTORS: GOOD ( √ ); DETERIORATED ( ); REPLACE ( )
- COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.
- 6. GROUNDING OF SERVICE: GOOD ( XX ); REQUIRES REPAIR ( )

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

7. GROUNDING OF EQUIPMENT: GOOD ( XX ); REQUIRES REPAIR ( )

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

8. SERVICE CONDUITS RACEWAYS; CONDITION: GOOD ( XX ); REQUIRES REPAIR (

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

9. SERVICE CONDUCTOR & CABLES; CONDITION: GOOD ( XX ); REQUIRES REPAIR ( )

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously very correct, repair and maintain all components of this building, whether included in the limiter inspection report or not, to assure building is safe for continued use and occupancy.

This report is not a Buyers Report, Due Diligence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official solely in accordance and with the purpose of compliance with Section 8-11 (i) of the Code of Miami-Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all content. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, it is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and liability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

10. TYPES OF WIRING METHODS:

CONDUIT RACEWAYS; RIGID: GOOD ( XX ); REQUIRES REPAIR ( )
CONDUIT; PVC: GOOD ( ); REQUIRES REPAIR ( )
NM CABLE: GOOD ( ); REQUIRES REPAIR ( )
BX CABLE: GOOD ( ); REQUIRES REPAIR ( )

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

11. FEEDER CONDUCTORS; CONDITION: GOOD ( XX ); REQUIRES REPAIR ( )

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

12. EMERGENCY LIGHTING: GOOD ( XX ); REQUIRES REPAIR ( )

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

13. BLDG. EGRESS ILLUMINATION: GOOD ( XX ); REQUIRES REPAIR ( )

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

14. FIRE ALARM SYSTEM: N/A (XX) GOOD ( ); REQUIRES REPAIR ( )

COMMENTS: None observed. Authority Having Jurisdiction may determine additional requirements. In the case that the Authority Having Jurisdiction makes this a requirement, it is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

15. SMOKE DETECTORS: N/A (XX) GOOD ( ); REQUIRES REPAIR ( )

COMMENTS: Property owner is responsible and liable to provide continued testing, maintenance and upgrades as may be necessary to assure all smoke detectors are continuously operable. Special care should be taken to assure units and their wiring are neither tampered with nor malfunctioning. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy. In addition, property owner is responsible to assure compliance with any requirement, code or ordinance that may require a hardwired carbon monoxide detector.

16. EXIT LIGHTS: GOOD ( XX ); REQUIRES REPAIR ( )

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify correct, repair and maintain all components of this building, whether included in this limite inspection report or not, to assure building is safe for continued use and occupancy.

17. EMERGENCY GENERATOR: GOOD ( ); REQUIRES REPAIR ( )

COMMENTS: None observed.

This report is not a Buyers Report, Due Dillgence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official solely in accordance and with the purpose of compliance with Section 8-11 (f) of the Code of Miami-Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all contents. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, it is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and liability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

18. WIRING IN OPEN OR UNDER COVER PARKING,

GARAGE AREAS: N/

AND SECURITY LIGHTING:

N/A ( ) GOOD ( XX );

N/A ( )

ADDITIONAL
ILLUMINAION
REQUIRED (

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

19. OPEN OR UNDER COVER PARKING SURFACE

ADDITIONAL ILLUMINATION GOOD ( XX ); REQUIRED (

COMMENTS: As observed/measured at time of inspection. Property owner is to assure that continued proper security lighting is provided at all times through preventive maintenance, upgrades or whatever means as may be necessary for compliance with section 8c-3 of the Code of Miami-Dade County. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

20. SWIMMING POOL WIRING:

GOOD ( ); REQUIRES REPAIR ( )

COMMENTS: N/A.

21. WIRING OF/TO

MECHANICAL EQUIPMENT:

GOOD ( √ ); REQUIRES REPAIR ( )

COMMENTS: As observed at time of inspection. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy. Any machinery or equipment which is for tenant use is excluded for the purposes of this report.

22. GENERAL ADDITIONAL COMMENTS: THIS REPORT IS NOT FOR BIDDING PURPOSES. Continue with proactive maintenance and provide repairs as may be necessary to maintain property safe for continued use and occupancy. Please note that this report does not include testing of any component, it is based on visual observations of applicable and accessible areas on day of inspection. Additionally, we rely on the validity of documentation as may be provided by owner for repairs performed to their property and for which they are solely responsible and liable for assuring they meet proper compliance with all applicable codes and life safety. It is the owner's responsibility to continuously verify, correct, repair and maintain all components of this building, whether included in this limited inspection report or not, to assure building is safe for continued use and occupancy.

This report is <u>not</u> a Buyers Report, Due Diligence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official <u>solely</u> in accordance and with the purpose of compliance with Section 8-11 (f) of the Code of Miami-Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all content. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, <u>nothing</u> in this report should be construed directly or indirectly as a guarantee for <u>any</u> portion of the structure(s). We rely on the validity of documentation provided by owner for repairs/alterations/corrections. No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection, only visual observations were conducted of areas and components as made accessible by property owner. Any repairs/alterations/modifications must be in compliance with FBC, NEC and all applicable codes and ordinances, if any violations or open permits exist all must be corrected prior to granting of Re-Certification. Further, it is understood by all parties that regardless of the content of this report, by submitting this report to the Building Department, property owner is not exempt, released or indemnified from any responsibility and liability to continuously verify, correct, repair and maintain all components of this building safe for continued use and occupancy whether included in this limited inspection report or not.

# CERTIFICATION OF COMPLIANCE WITH PARKING LOT ILLUMINATION STANDARDS IN CHAPTER 8C OF THE CODE OF MIAMI-DADE COUNTY

DATE	: October 16, 2015	
	Folio No. Property Address: Building Description:	03-4117-005-2580 241 Almeria Avenue, Coral Gables Fl. Bldg. No.: 1 One STORY Commercial
The u	ndersigned states the fo	llowing:
1.	I am a Florida register	red professional engineer or architect with an active license.
2.	On <u>August 16, 2015</u> , referenced building.	I measured the level of illumination in the parking lot(s) serving the above
3.	Maximum1.5 Maximum ratio1_	foot candle per SF, Minimum1 foot candle per SF, Minimum to :1.5, foot candle1 average per SF.
4.	The level of illumination occupancy classification Dade County.	on provided in the parking lot(s) meets the minimum standards for the on of the building as established in Section 8C-8 of the Code of Miami-  Signature and Seal of Architect or Engineer  Red Mouseure Capete
		(Print Name)

# REQUEST AND AGREEMENT FOR RE-CERTIFICATION AS PER SECTION 8-11(f) OF THE CODE OF MIAMI DADE COUNTY

OWNER NAME: BROCKWAY LTD.
Property Address(es): 241 Almeria Avenue, Coral Gables Fl.
Property Folio: 03-4117-005-2580
Date of Inspection for Purposes of this Report: August 24, 2015

as property owner and/or authorized representative of the above referenced property(s) am requesting that Arcbuilders and Group, inc. (the "company") prepare and submit the required \*Minimum Inspection Procedural Guidelines as required for Recentification as stipulated in Section 8-11 (f) of The Code of Miami Dade County (referred to as "this report") subject to the unconditional release and limitation of liability. I have submitted to Arcbuilders and Group, Inc. documentation in reference to repairs/alterations/corrections which I have performed on the subject property(s) and by doing so take full responsibility for the proper completion of any repairs/corrections/alterations and/or maintenance of the building components. I am responsible to disclose in writing any known defects or violations at the time of inspection or at the time the report is to be prepared and accordingly I am attaching as may be applicable a document in that regard. I understand that Arcbuilders and Group, Inc. relies on the validity of this documentation and is not responsible to verify the validity, quality, means and methods or compliance with applicable laws of the repairs/alterations/corrections performed at the subject building.

I understand that this limited \*report being requested from Archuilders and Group Inc. is not a guaranty or warranty for any part of this property. Further I hold harmless and indemnify Arcbuilders and Group Inc. its principals, owners and employees from any and all liability arising from the preparation and submission of this report. I acknowledge that this report is prepared and is to be submitted to the Building Official as may be required for Re-Certification as referenced above. This report is not a Buyers Report, Due Diligence, Insurance Inspection, Mitigation Document or for any other purpose other than to be prepared and submitted to the Building Official solely in accordance and with the purpose of compliance with Section 8-11(f) of The Code of Miami Dade County, any other use is strictly prohibited and voids all content. This report must bear the original signature and embossed seal on each page or it is void of all contents. This report is not transferable to any party. Copying, faxing and/or any alteration of this report is strictly prohibited and voids all content. Both Building (Structural) and Electrical Reports must be attached and accompanied by a cover letter to the building official. As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure(s). No property/permit history was either made available or reviewed for purposes of this report. No testing is part of this inspection or this report, only visual observations were conducted of areas and components as made accessible by property owner/representative on the day of inspection. Any repairs/corrections/alterations must be in compliance with FBC, NEC and all applicable codes and ordinances. If any violations or open permits exist all must be corrected prior to granting of Re-Certification. In the event that Archuilders and Group Inc, its principals, owners or employees are found liable due to breach of contract, breach of warranty, negligence, negligent misrepresentation, or any other theory of liability, the combined liability of the company and its principals, owners and employees shall be limited to a sum equal to the amount of the fee paid by the client for the original inspection and report. Property owner agrees to have no cause of action against the company and its principals, owners or employees beyond thirty days after the date of this agreement. In the event the property owner fails to prove adverse claims against company or its principals, owners or employees in a court of law, the property owner will pay all legal costs, expenses and fees in defending claim. By submitting this report to the Building Department, property owner accepts full responsibility and liability to continuously verify, correct, repair and maintain all components of this building whether included in this limited inspection report or not. Acceptance and understanding of this agreement are hereby acknowledged.

Signature

ODALYS GUTIERREZ
Notary Public - State of Florida
My Comm. Expires Sep 10, 2016
Commission # EE 830606
Bonded Through National Notary Assn.


My Commission expires:

ODALYS GUTIERREZ
Notary Public - State of Florida
My Commission # EE 830606
My Commission expires:

My Commission expires:

My Commission expires:

My Commission expires:



RC-15-10-5755 241 ALMERIA AVE #

Folio #: 03-4117-005-2580
Permit Description: 40 YEAR BUILDING
RECERTIFICATION OR OLDER BUILT (1955)

EL		
ME		_
	·	
PL		_

# **OFFICE SET**

	1	A	рргочед	
	Section	Ву	Dat	le
o	BUILDING			
	CONCURRENCY		1	
	ELECTRICAL	M	18/24	10
	FEMA	wer		
	FIRE			
0	HANDICAP			
0	HISTORICAL			
0	MECHANICAL	<u> </u>		
	PLUMBING	<u> </u>		
	PUBLIC WORKS			
	STRUCTURAL	<u> </u>		
	ZONING			
		<u> </u>		
	<u> </u>			
C				
	OWNER BUILDEF			
1	Dubject to compliance we City rules and regulation for accuracy of or results THIS COPY OF PLAN BUILDING SITE OR A MADE.	s. City assi from these p	imes no tesp p <b>lans.</b> BE AVAILA	BLE ON

APPROVAL OF THIS SET OF PLANS DOES NOT CONSTITUTE APPROVAL OF ANY STRUCTURE OR CONDITION NOT IN COMPLIANCE WITH ANY APPLICABLE CODES

pmPermitActions 1/25/2016 7:47:30AM		CIT	Permit Action Report CITY OF CORAL GABLES	port ABLES			Page: 1
Permit #: RC-15-10-5755 Master permit #:	10-5755	Permit type: rc010 - BUILDING RE CERTIFICATION Routing queue: rc012 - STRUCTURE CERTIFICATION	JILDING RE CER	RTIFICATION TIFICATION	Address: 241 COF	Address: 241 ALMERIA AVE CORAL GABLES, FL 33134-5903	
	Action		Completion	Completion Completion Completed	Completed		
Group # - Name	Code	Action Description	Date	Code	Ву	Comments	
1 - BOARDS - GENERATE F calc fees	calc fees	CALCULATE FEES	10/27/2015	comp	cgonzalez		
2 - CASHIER	collect	COLLECT FEES	10/28/2015		iwebuser		
3 - PLAN REVIEW	prbuild	BUILDING PLAN REVIEW					
3 - PLAN REVIEW	prbuild	BUILDING PLAN REVIEW	10/28/2015	reject	mlopez	SEE REPORT.	
3 - PLAN REVIEW	prelec	ELECTRICAL PLAN REVIEW	10/29/2015	apvd	areyes		
4 - RF CFRTIFIED   FTTFR letter	letter	GENERATE LETTER					



# BEFORE THE CONSTRUCTION REGULATION BOARD OF THE CITY OF CORAL GABLES

CITY OF CORAL GABLES,

Case # 16-4688

Petitioner.

VS.

BROCKWAY LTD.. LLLP a Florida limited liability limited partnership.

Respondent.

# NOTICE OF UNSAFE STRUCTURE VIOLATION FOR FAILURE TO RECERTIFY AND NOTICE OF HEARING

Date: January <u>22</u>, 2016

To:

Owner

Brockway Ltd., LLLP

297 Almeria Avenue

Coral Gables, FL 33134-5903

Brockway Ltd., LLLP

c/o Ronit Canet

Registered Agent

300 Almeria Avenue

Coral Gables, FL 33134-5812

Return receipt number:

Return receipt number:

91 7108 2133 3932 6905 4116

91 7108 2133 3932 6905 4123

MortgageeMortgageeThe Northern Trust CompanySun Trust Bank50 South Lasalle Street777 Brickell AvenueChicago, IL 60603-1008Miami, FL 33131-2809Return receipt number:Return receipt number:

91 7108 2133 3932 6905 4130

91 7108 2133 3932 6905 4147

CITY'S EXHIBIT 5

Mortgagee

Sun Trust Bank 303 Peachtree Street, NE Atlanta, GA 30308-3201

Return receipt number:

91 7108 2133 3932 6905 4154

Re: The one-story commercial building ("Structure"), built in 1955 (60-year recertification required), and located at **241 Almeria Avenue**, Coral Gables, FL 33146-5903, legally described as Lots 33 and 34, Block 10, of CORAL GABLES CRAFTS SECTION, according to the Plat thereof, as recorded in Plat Book 10, Page 40, of the Public Records of Miami-Dade County, Florida, and having folio number 03-4117-005-2580 ("Property").

The City of Coral Gables ("City") Building Official has inspected the records relating to the Structure in accordance with Article III, Chapter 105 of the City Code, pertaining to unsafe structures, and Section 8-11 of the Miami-Dade County Code, as applicable in the City, pertaining to existing buildings. The Structure is hereby declared unsafe by the Building Official and is presumed unsafe pursuant to Section 105-186(j)(13) of the City Code for failure to timely comply with the maintenance and recertification requirements of the Florida Building Code or Section 8-11 of the Miami-Dade County Code as follows:

On April 20, 2015, the City sent the Property Owner a 90-day Notice of Required Inspection requesting an inspection report conforming to the minimum inspection procedural guidelines as issued by the Miami-Dade County Board of Rules and Appeals, pursuant to Section 8-11(f) of the Miami-Dade County Code ("Report").

The Report, submitted to the City on October 16, 2015, stated that the Structure did not meet the minimum requirements to be recertified as structurally and electrically safe. The Report noted that the following items required repair or modification: **Structural:** 1) roof framing and structure are concealed, roof seemingly in poor condition, owner is required to have an uplift and moisture test completed, built up plies seemingly in poor condition for age of building, please refer to 2B; 2) wood framing and joints, unable to verify, please refer to 2B.

To date, the Owner has not a) completed the required repairs and b) submitted a letter from the architect or engineer who prepared the Report stating that the Structure now meets the minimum requirements ("Compliance Report")(collectively referred to as "Required Action").

Therefore, this matter is set for hearing before the City's Construction Regulation Board ("Board") in the Commission Chambers, City Hall, 405 Biltmore Way, Coral Gables, Florida 33134, on February 8, 2016, at 2:00 p.m.

You may appeal the decision of the Building Official to the Board by appearing at the hearing. You have the right to be represented by an attorney and may present and question witnesses and evidence, however, formal rules of evidence shall not apply. Failure to appear at the hearing will result in the matter being heard in your absence. Please be advised that, if someone other than an attorney will be attending the hearing on your behalf, he or she must provide a power of attorney from you at the time of the hearing. Requests for continuance must be made in writing to Belkys Garcia, Secretary to the Board, at City of Coral Gables, Development Services Department, 405 Biltmore Way, 3rd Floor, Coral Gables, FL 33134, <a href="mailto:bgarcia@coralgables.com">bgarcia@coralgables.com</a>, tel: (305) 460-5229.

If the Required Action is not completed before the above hearing date, the Building Official may order that the structure be vacated, boarded, secured, and posted to prevent further occupancy until the Required Action is completed. The Building Official may also order demolition of the Structure and recover the costs incurred against the Property and the Owner of record.

If the Property Owner or other interested party does not take all Required Action or appeal the decision of the Building Official, the Construction Regulation Board may enter an order of demolition and assess all costs of the proceedings and demolition and other Required Action for which the City shall have a lien against the Property and the Property Owner.

Please contact Virginia Goizueta, Building Services Coordinator, tel.: (305) 460-5250, email: <a href="mailto:vgoizueta@coralgables.com">vgoizueta@coralgables.com</a>, or Manuel Z. Lopez, P.E., Building Official, tel.: (305) 460-5242, email: <a href="mailto:mlopez@coralgables.com">mlopez@coralgables.com</a>. The Development Services Department's hours are Monday though Friday, 7:30 a.m. to 3:30 p.m.

Please govern yourself accordingly.

Building Official

#### CERTIFICATE OF SERVICE

I HEREBY CERTIFY that, on January 22, 2016, a true and correct copy of the foregoing notice was served via certified mail, return receipt requested, by first class mail, via email at any e-mail address indicated above, and by hand-delivery or posting at the Property.

#### **NOTICES**

Any person who acts as a lobbyist pursuant to the City of Coral Gables Ordinance No. 2006-11, must register with the City Clerk, prior to engaging in lobbying activities before the city staff, boards, committees and/or the City Commission. A copy of the Ordinance is available in the Office of the City Clerk, City Hall,

Pursuant to Section 286.0105, Florida Statutes, if a person decides to appeal any decision made by the Board, with respect to any matter considered at such hearing or meeting, he or she will need a record of the proceedings, and that, for such purpose, he or she may need to ensure that a verbatim record of the proceedings is made; which record includes the testimony and evidence upon which the appeal is to be based. Although a court reporter usually attends the hearing at the City's cost, the City is not required to provide a transcript of the hearing, which the Respondent may request at the Respondent's cost.


ADA Assistance: The City complies with the provisions of the American with Disabilities Act. Individuals with disabilities requiring special accommodations or assistance should contact Ernesto Pino, Assistant Public Works Director, at (305) 460-5004, with requests for auxiliary aids or services at least one business day before the hearing in order to request such assistance.



# CITY OF CORAL GABLES DEVELOPMENT SERVICES DEPARTMENT Affidavit of Posting

Complaint/Case #: 16-4688
Title of Document Posted: Construction Regulation Board Case
I, <u>EDUANOD MAYATIN</u> , DO HEREBY SWEAR/AFFIRM THAT
THE AFOREMENTIONED NOTICE WAS PERSONALLY POSTED, BY ME, AT THE
ADDRESS OF <u>241 Almeria aue</u> , on 1-22-16 AT 9:20 a.m.
Employee's Printed Name  Employee's Signature  Employee's Signature
STATE OF FLORIDA ) ss. COUNTY OF MIAMI-DADE )
Sworn to (or affirmed) and subscribed before me this 22 day of January, in the year 20 6, by Eduardo Martin who is personally known to me.
My Commission Expires:
BELKYS GARCIA Commission # FF 186232 Expires April 29, 2019 Notary Public

#### 241 Almeria Avenue





95R214847

2,3500

0.19-CAND DEE

RANCO PORM S

£ 12575 £ 1399

This Calt-Claim Detal. Executed this 28th day of December

1 1) 10 44 by

BROCKWAY ENT

BROCKWAY ENTERPRISES, INC., a Florida corporation

BROCKWAY, LTD., a Florida limited partnership

whose pastoffice address to

297 Almeria Avenue, Coral Gables, Florida

(Missiones used favour the speams first party and strong party shall include unusual and plant have legal approximations, and protes of inter-study, and the incremes and steps of terporations, whereave the recent

in hand paid by the said second party, the occupt whereof it hereby manuscledged, does hereby remise relesse and guit claim unto the said second party foreier all the right title interest claim and domaind which the said lives party has in and to the following described by piece or vector of land, situate, lying and being in the Causty of Daile State of Floride to will

SEE ATTACHED EXHIBIT "A" FOR LEGAL DESCRIPTION.

2)50: CO

Entra Security Flores Conse Consessed

To have and to Hold the same together with all and singular the appuri nances thereunio holonging or in enjurise apperaining and all the estete right title interest lies, equity and claim whatsoever of the said first party, either in low or equity, to the only proper use hencht and behoof of the said second party foreser.

In these witten, The said first party has signed and seeled there presents the day and year first above written.

Signed, realed and delivered in presence of

Brockway Enterprises, Inc.

Withess / Class & C.

JOHN BROCKWIN, President

- TANKS

TATE OF PLONIDA

I HEREBY CERTIFY that me this day, brinch me, an

officer duly authorized in the State absorbed and in the County abstract to take acknowledgement, pro-Nohin Brockway, President of Brockway Enterprises, Eps.

to us brown to be do press described to and who ascends the integrating traverses before one that he convents the name on behalf of said corporate within my bank and official seal in the County and happy in DESCRIBER; A. D. 18 54

My Commission Expiras:

Ching Ridle, Hote of Florida Sty Generaliza Replica Int. 10, 701

The Lateral panel by: CHARLES D. RUBIN

Pine Jacobson Schwartz Hash Block & England
2301 Couples Road, Missi, Florida 33134

gry's

**EXHIBIT** 

# # 12575 / 1480

#### EXHIBIT "A"

Lots 11, 34, 35 in Block 10 of CORAL GABLES CRAPTS SECTION, according to the Plat thereof, as recorded in Plat Book 16 at Page 40 of the Public Records of Dade County, Florida, but not including any improvements presently existing on such property.

NAME COUNTY, PARTIES AND SAME PARTY OF THE COUNTY, PARTIES AND PARTY OF THE COUNTY OF T

# FLORIDA DEPARTMENT OF STATE DIVISION OF CORPORATIONS



## **Detail by Entity Name**

#### Florida Limited Partnership

BROCKWAY LTD., LLLP

#### Filing Information

**Document Number** 

A18721

FEI/EIN Number

59-2513462

Date Filed

12/28/1984

State

FL

Status

**ACTIVE** 

Last Event

LP AMENDMENT

**Event Date Filed** 

07/29/2008

**Event Effective Date** 

NONE

#### **Principal Address**

300 ALMERIA AVE.

CORAL GABLES, FL 33134

Changed: 10/13/1995

#### **Mailing Address**

300 ALMERIA AVE.

CORAL GABLES, FL 33134

Changed: 10/13/1995

#### Registered Agent Name & Address

CANET, RONIT

300 ALMERIA AVE.

CORAL GABLES, FL 33134

Name Changed: 06/08/2006

Address Changed: 10/13/1995

#### General Partner Detail

Name & Address

BROCKWAY, ROBERT WTRUSTEE 300 ALMERIA AVE. CORAL GABLES, FL 33134 BROCKWAY, PAULA LTRUSTEE 300 ALMERIA AVE. CORAL GABLES, FL 33134

#### **Annual Reports**

Report Year	Filed Date
2013	01/28/2013
2014	01/21/2014
2015	02/23/2015

### **Document Images**

02/23/2015 ANNUAL REPORT	View image in PDF format
01/21/2014 ANNUAL REPORT	View image in PDF format
01/28/2013 ANNUAL REPORT	View image in PDF format
02/15/2012 ANNUAL REPORT	View image in PDF format
04/12/2011 ANNUAL REPORT	View image in PDF format
04/22/2010 ANNUAL REPORT	View image in PDF format
04/29/2009 ANNUAL REPORT	View image in PDF format
07/29/2008 LP Amendment	View image in PDF format
04/28/2008 ANNUAL REPORT	View image in PDF format
04/23/2007 ANNUAL REPORT	View image in PDF format
06/08/2006 LTD Amended/Restated Cert/NC	View image in PDF format
04/28/2006 ANNUAL REPORT	View image in PDF format
05/11/2005 ANNUAL REPORT	View image in PDF format
04/22/2004 ANNUAL REPORT	View image in PDF format
05/19/2003 ANNUAL REPORT	View image in PDF format
02/18/2002 ANNUAL REPORT	View image in PDF format
05/01/2001 ANNUAL REPORT	View image in PDF format
02/24/2000 ANNUAL REPORT	View image in PDF format
12/07/1998 ANNUAL REPORT	View image in PDF format
10/31/1997 ANNUAL REPORT	View image in PDF format
11/18/1996 ANNUAL REPORT	View image in PDF format

Copyright of and incomey Position Page of the day programme of State



CFN 2010R0817940

OR Bk 27511 Pss 4344 - 4362; (19pss)
RECORDED 12/07/2010 11:19:27
HARVEY RUVIN: CLERK OF COURT
HIAMI-DADE COUNTY: FLORIDA

THIS INSTRUMENT PREPARED BY & RETURN TO: Manuel A. Perez, Esq.
Harper Meyer Perez Hagen O'Connor Albert & Dribin LLP 201 S. Biscayne Blvd., Suite 800
Miami, Florida 33131
Telephone (305) 577-3443

#### MORTGAGE

THIS MORTGAGE (this "Mortgage") is made and delivered effective as of the 22<sup>nd</sup> day of November, 2010, by and between BROCKWAY LTD., LLLP, a Florida limited liability limited partnership with a mailing address at 300 Almeria Avenue, Coral Gables, Florida 33134 (hereinafter called the "Mortgagor"), and NORTHERN TRUST, NA, a national banking association formerly known as Northern Trust Bank of Florida, N.A., having an office at 700 Brickell Avenue, Miami, Florida 33131, (hereinafter called the "Mortgagee").

#### WITNESSETH:

WHEREAS, on May 31, 2007, Robert W. Brockway and Paula L. Brockway, as husband and wife (collectively, the "Brockways"), and Mortgagee entered into an agreement, pursuant to which Mortgagee agreed to extend to the Brockways a loan in the original principal amount of Five Million Six Hundred Twenty Five Thousand and No/100 United States Dollars (U.S. \$5,625,000.00) (the "Original Loan"); and

WHEREAS, the Original Loan is evidenced by that certain Interest Only Balloon Note dated effective as of May 31, 2007 in the original principal amount of Five Million Six Hundred Twenty Five Thousand and No/100 United States Dollars (U.S. \$5,625,000.00) from the Brockways in favor of the Mortgagee and by that certain Renewal of the Interest Only Balloon Note dated effective as of June 1, 2010, in the original principal amount of Five Million Six Hundred Twenty Five Thousand and No/100 United States Dollars (U.S. \$5,625,000.00) from the Brockways in favor of the Mortgagee (collectively, the "Original Note"); and

WHEREAS, the Brockways' obligations under the Original Loan and the Original Note are secured by that certain Mortgage dated effective as of May 31, 2007, by and between the Brockways and Mortgage (the "Original Mortgage"), such Original Mortgage having been recorded June 1, 2007, in Official Records Book 25665, at Page 1750, of the Public Records of Miami-Dade County, Florida; and

WHEREAS, the Brockways and Mortgagee have amended the Original Loan pursuant to the terms of that certain Security and Term Loan Agreement of even date herewith (the "Loan Agreement") in order to, inter alia, (i) pay down the principal amount of the Original Loan to FIVE MILLION SIXTY-TWO THOUSAND FIVE HUNDRED AND 00/100 UNITED STATES DOLLARS (U.S. \$5,062,500.00) (the "Loan"), (ii) extend the maturity date of the Loan, all as more particularly set forth in the Loan Agreement; and (iii) include additional collateral; and

FLORIDA DOCUMENTARY STAMP AND INTANGIBLE TAXES HAVE BEEN PAID WITH RESPECT TO THE ORIGINAL INDEBTEDNESS DESCRIBED IN THE ORIGINAL MORTGAGE, AND EVIDENCE OF SUCH PAYMENT APPEARS ON THE ORIGINAL MORTGAGE. THIS INSTRUMENT SECURES A FUTURE ADVANCE UNDER THE ORIGINAL MORTGAGE AND, PURSUANT TO SECTION 199.143(1), FLORIDA STATUTES, ADDITIONAL TAXATION IS ONLY DUE ON THE AMOUNT OF SUCH FUTURE ADVANCE.

Page 1 of Mortgage

00063445

#### **BALLOON PAYMENT RIDER**

THIS BALLOON PAYMENT RIDER (this "Rider") is made effective as of the 22<sup>nd</sup> day of November, 2010, and amends that certain Amended and Restated Interest Only Balloon Note in the amount of \$5,625,000.00 (the "Note") made by Robert W. Brockway and Paula L. Brockway, as husband and wife (collectively, the "Borrower") to NORTHERN TRUST, NA (the "Mortgagee"), and that certain Mortgage of even date therewith by and between Brockway Ltd., LLLP (the "Mortgagor") and Lender (the "Mortgage"), to secure repayment of the Note.

In addition to the agreements and provisions made in the Mortgage, both Mortgagor and Mortgagee further agree as follows:

IF NOT PAID EARLIER, THIS LOAN IS PAYABLE IN FULL ON AUGUST 31, 2011 (THE "MATURITY DATE"). BORROWER MUST REPAY THE ENTIRE UNPAID PRINCIPAL BALANCE OF THE LOAN AND INTEREST THEN DUE. THIS IS CALLED A "BALLOON PAYMENT." THE LENDER IS UNDER NO OBLIGATION TO REFINANCE THE LOAN AT THAT TIME.

At least ninety (90) but not more than one hundred twenty (120) days prior to the Maturity Date, Mortgagee must send the Borrower a notice which states the Maturity Date and the amount of the "balloon payment" which will be due on the Maturity Date (assuming all scheduled payments due between the date of the notice and the Maturity Date are made on time).

BROCKWAY LTD., LLLP

Name: Robert W. Brockway

Title: General Partner

Title: General Partner

NORTHERN TRUST, NA

Name: Michael J. Villasana

Title: Senior Vice President

Page 19 of Mortgage

00063445

JUN 35 1991 DANELOWARY WHOLES

## 艇 15082 1374

EXHIBIT A

Lots 1, 2, 3, 4, 5, 6, 7, 8, 9, 12, 33, 34, 35, 37, 38, 39, '40, 41, 42, 43, 44, 45 and 46, in Block 10, and Lots 1, 2, 3 and 4 in Block 15, of COPAL GABLES CRAFTE SECTION, according to the plat thereof, as recorded at Plat Book 10, at Page 40, of the Public Records of Dade County, Florida.

Promotic printerior records adds of the account, floating records stated Clerk of Count's County Courts

18607-49 Ploxh:wpl16

#### Federal Deposit Insurance Corporation

Each depositor insured to at least \$250,000 per insured bank

## The Northern Trust Company (FDIC #: 913)

Status: Active • Insured Since January 1, 1934 The Northern Trust Company is an active bank

Date of all dentities, these

Overview

Locations

History

Identifications

Financials

**Northern Trust** Corporation

Bank Holding Company

The Northern Trust Company has 73 domestic locations in 18 states, 0 locations in territories, and 2 foreign locations

The Northern Trust Company **Banking Institution** 

73 Locations

Branches (Offices)

FDIC Certificate #:

Established:

January 1, 1889

913

Insured:

January 1, 1934

Bank Charter Class:

Member of the Federal

Reserve System

Headquarters:

50 South Lasalle Street

Chicago, IL 60603 Cook County

Regulated By:

Federal Reserve Board

Consumer

http://www.FederalReserveConsumerHelp.gov Assistance:

Corporate Website:

http://www.northerntrust.com

Contact the FDIC about The Northern Trust Company

Federal Deposit Internation Compagnation Each depositor insurer Le si leasi \$250 000 per insured bente

## Northern Trust, National Association (FDIC #: 24185)

Status: Inactive • Inactive as of October 1, 2011 Northern Trust, National Association was merged or acquired without government assistance

Overview

) excellens

History

Manufactions.

Einomoteks

N/A

Bank Holding Company

Northern Trust, National Association

Banking Institution

Branches (Offices)

Inactive as of October 1, 2011

Northern Trust, National Association is no longer doing business under that name because it has been merged or acquired without government assistance. See the successor institution The Northern Trust Company (FDIC #: 913)

Established:

November 1, 1982

FDIC Certificate #:

24185

Insured:

November 1, 1982

Bank Charter Class: National Bank

Headquarters:

700 Brickell Avenue

Miami, FL 33131 Miami-Dade County

Contact the FDIC about Northern Trust, National Association or The Northern Trust Company

#### 19858PG4187

PREPARED BY: Richard H. Bergman, Esq. Bergman and Jacobs, P.A. Suite 780 777 Brickell Avenue Miami, Florida 33131

01R459485 2001 AUG 22 14:02

#### AGREEMENT FOR SUBORDINATION OF MORTGAGE

THIS AGREEMENT is made and entered into this Aday of A. (..., 2001, by and between BILL USSERY MOTORS, INC., 6/k/a Brockway Enterprises, Inc. (the "Existing Mortgagee"), with an address at 300 Almeria Avenue, Coral Gables, Florida 33134; SunTrust Bank, (the "New Mortgagee"), 777 Brickell Avenue, Miami, Florida 33131; and Brockway, LTD, (the "Owner"), 300 Almeria Avenue, Coral Gables, Florida 33134.

#### Recitals

Owner is the owner of a certain parcel of land, situated in the County of Miami- Dade, Florida, fully described in <u>Exhibit "A"</u> which is attached hereto and made a part hereof and of certain buildings and improvements on the parcel (the "Property").

Owner, by an instrument dated December 28, 1984, granted and conveyed to Bill Ussery Motors, Inc. a mortgage encumbering the Property(the "Existing Mortgage"), securing the payment of \$\$3,361,050.633, with interest. The Existing Mortgage was recorded on July 17, 1985, in Official Records Book 12575 at Page 1396 of the Public Records of Miami-Dade County, Florida.

Owner, by an instrument is granting and conveying to the New Mortgagee a lien by way of a Future Advance Agreement encumbering the Property (the "New Mortgage"), securing the payment of \$1,000,000.00, with interest, evidenced by a future advance promissory note in the amount of \$1,000,000.00. The New Mortgage is to be recorded in the office of the Clerk of the Circuit Court in and for Miami-Dade County, Florida prior to the recording of this Agreement.

The parties desire that the lien of the Existing Mortgage shall be subordinated in the full amount to the lien of the New Mortgage (Future Advance).

In consideration of the sum of \$10.00 and other good and valuable consideration, the receipt of which is acknowledged by the Existing Mortgagee, the parties, intending to be legally bound, agree as follows:

 The Existing Mortgage is subordinated to the lien of the New Mortgage to the full extent and in the aggregate amount of all advances made or to be made by the New Mortgagee not to exceed \$1,000,000.00, except

1

Bergman and Jacobs, P.A.

777 BRICKELL AVENUE, SUITE 780. MIAMI. FLORIDA 33131





#### OFF. REC BK.

#### 19858964188

for payment of real estate taxes and insurance, if any.

- The subordination of the Existing Mortgage to the lien of the New Mortgage shall have the same force and effect as though the New Mortgage had been executed, delivered, and recorded in the Clerk's office prior to the execution, delivery, and recording of the Existing Mortgage.
- 3. If any proceedings are brought by the Existing Mortgagee or his successors or assigns against the Property, including foreclosure proceedings on the Existing Mortgage or to execute any judgment on the note or bond that it secures, the judicial sale in connection with the proceedings shall not discharge the lien of the New Mortgage.
- 4. This subordination also subordinates the lien of any security agreement or UCC-I Financing Statement filed in connection with the Existing Mortgage.
- 5. This Agreement shall be binding on and inure to the benefit of the respective heirs, successors and assigns of the parties hereto.

Executed and delivered, this 21 day of 4, 2001.

OWNER:

Witness Signature

Witness Signature

Print: Gregery W. Barnes

y Joh (Molec

Brockway, LTD., a Florida limited partnership

John C! Brockway, General Partner

Patricia A. Brockwa;y, General Partner

ADDITIONAL SIGNATURES ON NEXT PAGE

2

Bergman and Jacobs, P.A.

777 BRICKELL AVENUE, SUITE 780 HIAMI, FLORIDA 33 131

OFF. REC BK.

### 19858PG4189

**NEW MORTGAGEE:** 

Witness Signature Print  Dame Liberty Witness Signature Print:	BY: DELEPERCHE TESCH  print: DELEPERCHE TESCH  as its: Celumora Cial Prantitum Office
	EXISTING MORTGAGEE:
Witness Signature Print: Konst Canct	Bill Ussery Motors, Inc.,  By Rollent Brockway, President
Witness Signature Print: Gregory W. Borns	
STATE OF TOOK )	Oth A
The foregoing instrument was acknowled	
	artiers of prockway, L1D., a Florida hanted partnership who n and who did not take an oath.
	NOTARY PUBLIC Print Name: Commission #:
OTHER PLANTS	OFFICIAL NOTABY BEAL NETTE FERNANDEZ COMMISSION HUMBER COSMOSE MY COMMISSION EXPRIES CT, 3.2004
	9

Bergman and Jacobs, P.A.

### 19858PG4190

STATE OF FLORIDA )	
COUNTY OF MIAMI- DADE )	
The foregoing instrument Nell-Peache Texett as (rums) did not take an oath.	NOTARY PUBLIC, STATE OF FLORIDA Print Name: Commission Number:  Bether Herrers Expires October 09, 2004
Brockway as President of Bill	as acknowledged before me this day of 2001 by Rober Ussery Motors, Inc., a Florida corporation who has produced
	NOTARY PUBLIC, STATE OF FLORIDA Print Name WAL - COMMISSION Number:
	COMMISSION NUMBER:  OF PLOT OF

Bergman and Jacobs, P.A.

#### OFF. REC BY

# 19858PG4191

#### EXHIBIT "A"

#### **LEGAL DESCRIPTION**

Lots 1,2,3,4,7,8,9,33,34,37,38,39,40,41,42,43,44,45 and 46, all in Block 10, and Lots 1,2,3 and 4 in Block 15, of CORAL GABLES CRAFTS SECTION, according to the Plat thereof, as recorded in Plat Book 10, Page 40 of the Public Records of Miami-Dade County, Florida.

RETORDED IN DEFICIAL RECORDS BOOK DE DADE COLATY, FLORIDA RECORD VERNEGO HARVEY RUYIN CLERK DIRCUIT COURT

**徳道 17 集わ 19** 

858214848

MORTGAGE

₩ 12575 F 1396

. THIS MESTGAGE DEED services the Jath day of Docember \_\_\_\_\_ & D. 14\_ <u>d 4</u>pe BROCKWAY, LTD., a Plorida limited partnership

purple of the fire past (hurdeshee called "Managem"), as BROCKWAY ENTERPRISES, INC., a Plorida corporation

portag of the second part (investeber colled "Managemen"), WITSTREETIN:

Ther for diver game and valuable mendiorestee, and also in econoloruses of the approprie sum named in the precisionly ness or ness, hardenfore described, the Marquiger date great, harging, tell, allow, realise, release, nearby and exadest ness du Marquige, in the study, all of that correle true of land of orders also Marquiger is now count and parameted and in across proention revers to ... Dade...... 

> Lots 1.2, 3, 4, 33, 34, 35, 37, 38, 39, 40, 41, 42, 43, 44, 45 and 46 in Block 10 and Lots 1, 2, 3, and 4 in Block 15, of CORAL GABLES GRAPTS SECTION, according to the Plat therwof, as recorded in Plat Book 10 at Page 46 of the Public Records of Dade County, Florida, but not including any improvements presently existing on such property.

Together with all and magular the tenescoop, herefitaments and appurentances thereton beforiging or in anywise aparttuning, and ingether with all agricultural, homocultural and fruit grops, now planted and or growing, and hereafter planted, grown or fated, in the abbet-closerabed land, and the bil buildings, neuttures additions and inspravments, now or at any time hartafter proceed thereon, reporter with and including all of the building mechanics, nevering plant, lighting print and gil plumbing opporatus finturen, appliance, rintelanog ned bie ennettineing equipment, theiris, battel, rivelete hanting and lighting plants, lighting lictures. power machiners, plant or pigen for running and operation of yestrager or other elevators including passanger and other elevators haw ar nerrafter leasted in the building upon and land, and all other meaniners, appliances and apparatus com ar bereatter placed on said previous, other in conserval or replacement at lineary, mechanics, appliances and apparenunces ariginally shoulded on said promoses to convertion with this oursplotten thereof or in addition theirs, which may beconfer be glated upon the above described land, and vibrals and filmyon, machiners, appliances and apparementer the Mangagar macteria shall be free them any entur-brances, common of talls or other classes in facts of any other person and that this deed shall be a time upon thereton.

TO HAVE AND TO HOLD all and augular the earl property breshy conveyed, marigaged, piedged or exciption by the hilvergague, or intended on to be, unto the Marryague, in for araple.

And the Moranger coverage with the Moranger that the Moranger and full power and confut right or conver and moranged property in otherwise, there is shall be justed for the November or all upon pagestally and enterly to other upon held, are uponed on ones and managed property; there are now few form all equations on sample at herein openionally on famb, then the Manager will make much factors assument to provide the site to and startegaged property in the Manager to may recommon to required; and that the Manager books, fully increases the sole to mad startegaged property and will defend the same agency into confut defend the same agency in the Manager to the same agency in the Manager to the same agency in the same of all process to be same agency in the same of all process to be same agency in the same of all process to be same agency in the same of all process to be same agency in the same of all process to be same agency in the same of all process to be same agency and the same of all process to be same agency in the same of all process to be same agency and the same agency and the same of all process to be same agency and the same agency agency and the same agency agency agency and the same agency agency agency and the same agency and agency the named the laterals interest

PROVIDED, ALWAYS, that if the Manager shell got wine the Managers the addresses avidenced by a Promissory THIS INSTRUMENT PREPARED BY:

> Fine, Jacobson, Schwartz, Jash, Block & England 2401 Douglas Road Miami, Plozida 13134

## 點 12575 元 1398

The rorms "Margager" and "Margager" whenever used in this contratum shall cartade the neces, present represents their successors and cought of the tempoters parent breats. Wherever used the magnine number shall include the glurks and the plants the magnine, and the use of any guider shall rectude on graders.

IN WITNESS WHUREOF, the Mortgagor has hereto sec its hand this with day of December, 1984.

MORTGAGOR: BROCKWAY, LTD. a Florida limited

BRUCKWAY, Joneral

Partnership

Partner

MORTGAGLE-EROCKWAY ENTERPRISES, INC., a florida corporation

BY: SOIN C. BROCKWAY, F esident

STATE OF FLORIDA COUNTY OF DADE

Bibit me, the undersigned subbiting this day permastly appeared John Brockway , in General Partner of Brockway, Ltd., and President of Brockway Enterprises, Inc., and Patricia A. Brockway, a General Partner of Brockway Ltd.

described in and was executed the foregoing instrument, and admostisded before my fact they executed resemble freely and voluntarily for the purposes therein expressed.

\*\*WITHERA on here of the purposes therein expressed.

same freely and voluntarily for the purpose therein exprised, WITHESh my knot and efficial only at Maoma.

December

, and County and State, this 28th also of

Nonery Puelles Sense of Floriday's Large 

STATE OF FLORIDA COUNTY OF

I HEREBY CERTIFY that po this day of authority, personally appeared and to be the persons who exercised the foregoing imministration

in 19 ...... , befare the, the undereigned , to the become , respectively.

a corporation, and each poverally acknowledged the rectures of such instrument to such effects, for and on the east and dead of said corporation, for the sum and purposes thoroug supremed, pursuant to authority lawfully conferred agenthem by acid corporation; and that the said affilted therein is true and growing corporate cell of said proporation, and were affiliable theorems by mid affiliable.

WITHOUT my band and official and at

, and County and Stein, the date placement.

Metary Public, Store of Florids or Large. My Continues Espen:

Federal Sepacit
Insurance Corporation
Each depositor broken in a loser \$250,000 per insured lands

### SunTrust Bank (FDIC #: 867)

Status: Active • Insured Since January 1, 1934

SunTrust Bank is an active bank

Overview

Locations

History

kirmilius Senta

Figure 198

Suntrust Banks, Inc. Bank Holding Company

**SunTrust Bank** has 1473 domestic locations in 12 states, 0 locations in territories, and 5 foreign locations

SunTrust Bank Banking Institution

1473 Locations

Branches (Offices)

Established:

September 21, 1891

FDIC Certificate #:

867

Insured:

January 1, 1934

Bank Charter Class:

Member of the Federal

Reserve System

Headquarters:

303 Peachtreet Street,

Northeast

Atlanta, GA 30308 Fulton County

Regulated By:

Federal Reserve Board

Consumer Assistance:

http://www.FederalReserveConsumerHelp.gov

**Corporate Website:** 

http://WWW.SUNTRUST.COM

Contact the FDIC about SunTrust Bank

### 熙 15082元 1354

#### HORTGAGE AND SECURITY AGREEMENT

Date:

June <u>/7</u>, 1991

91R216808 1991 JUN 25 16:54

Mortgagor:

BROCKWAY, LTD., a Florida limited partnership 297 Almeria Avenue Coral Gables, Florida 33234

Mortgagce:

SUN BANK/HIAMI, N.A., a national banking association 777 Brickell Avenue Miami, Florida 33131

This Mortgage and Security Agreement (the "Mortgage") is given to secure the payment, performance and observance by MORTGAGOR of all the covenants and conditions contained in this Mortgage, and in the Net Worth Guaranty from MORTGAGOR to MORTGAGEE of even date herewith (the "Net Worth Guaranty") given to Mortgagee in connection with that cortain loan (the "Loan") in the amount of \$12,000,000.00 made by MORTGAGOR to "Loan") in the amount of \$12,000,000.00 made by MORTGAGOR to "Horn" in the amount of \$12,000,000.00 made by MORTGAGOR to "Construction Loan Agreement by and among, inter alia, Borrower, MORTGAGOR and MORTGAGEE, of even date herewith (the "Construction Loan Agreement") as evidenced by that certain promissory note from Borrower to MORTGAGEE of even date (the "Note"), and in order to charge the properties, interests and rights hereinafter described with such payment, performance and observance, and for and in consideration of the sum of Ten Dollars (\$10.00) to MORTGAGOR duly paid by MORTGAGEE on or Defore the ensealment and delivery of this Mortgage and for other valuable consideration, the receipt of which is hereby acknowledged, MORTGAGOR has executed and delivered this Mortgage and has mortgaged to MORTGAGEE and its successors and assigns all of MORTGAGOR's interest in the following-described real property, buildings, improvements, appurtenances, tangible property, rents, contract rights, other intangibles and recondary financing (which, together with any additional such property hereafter acquired by MORTGAGOR and subjected to the "Mortgaged Property"), to-wit:

- (A) The Land. A parcel of land situate, lying and being in the county of Dade, State of Florida, described and set forth in EXHIBIT "A" attached hereto and made a part hereof, and the benefit of all casements and other agreements, if any (the "Land").
- (B) Improvements. All buildings, structures, betterments and other improvements of any nature new or hereafter situated, or intended to be situated, in whole or in part upon the Land, regardless of whother physically affixed or now or hereafter severed or capable of severance from the Land, except for such of the foregoing as are located on Parcel 1 and are owned by John C. Brockway and Patricia A. Brockway (the "Improvements").
- (C) Appurtonances. All casements, rights of way, gores of land, streets, ways, alleys, passages, sower rights, waters, water courses, water rights and powers and all tenements, hereditaments and appurtenances whatsoever, in any way belonging, relating or appertaining to the Land, or which hereafter shall in any way belong, relate to or be appurtenant

THIS INSTRUMENT PREPARED BY AND RETURN TO: Robert H. Smith, Esq. Holland & Knight 1200 Brickell Avenue Miami, Florida 33131

9600

JUNE 25 1991 DANELOUNTY - CONTROLLED

### 殿 15082 1374

EXHIBIT A

Lots 1, 2, 3, 4, 5, 6, 7, 8, 9, 12, 33, 34, 35, 37, 38, 39, '40, 41, 42, 43, 44, 45 and 46, in Block 10, and Lots 1, 2, 3 and 4 in Block 15, of COPAL GABLES CRAFTS SECTION, according to the plat thereof, as recorded at Plat Book 10, at page 40, of the Public Records of Dade County, Florida.

Property in the first receipt grown Clerk of Creat Caracter receipt grown and the contract of the contract of

18607-49 Ploxh: wp116

Federal Deposit Insurance Corporation Each depositor intered to at least \$250,000 per insured oracle.

## Sun Bank/Miami, National Association (FDIC #: 3578)

Status: Inactive • Inactive as of January 1, 2000 Sun Bank/Miami, National Association was merged or acquired without government assistance

Overview

i cualitura

Phaine.

destinations.

distributed:

N/A

Bank Holding Company

Sun Bank/Miami. National Association Banking Institution

Branches (Offices)

Inactive as of January 1, 2000

Sun Bank/Miami, National Association is no longer doing business under that name because it has been merged or acquired without government assistance. See the successor institution SunTrust Bank (FDIC #: 867)

Established:

January 1, 1934

FDIC Certificate #:

3578

Insured:

January 1, 1934

Bank Charter Class: National Bank

Headquarters:

777 Brickell Avenue Miami, FL 33131 Miami-Dade County

Contact the FDIC about Sun Bank/Miami, National Association or SunTrust <u>Bank</u>

Federal Deposit Insurance Cornoration Each depositor insured to at least \$250,000 per testined with

### SunTrust Bank (FDIC #: 867)

Status: Active • Insured Since January 1, 1934

SunTrust Bank is an active bank

Overview

Locations

History

Identifications

FREEDOM

Suntrust Banks, inc. Bank Holding Company

SunTrust Bank has 1473 domestic locations in 12 states, 0 locations in territories, and 5 foreign locations

SunTrust Bank Banking Institution

1473 Locations

Branches (Offices)

Established:

September 21, 1891

FDIC Certificate #:

867

Insured:

January 1, 1934

Bank Charter Class: Member of the Federal

Reserve System

Headquarters:

303 Peachtreet Street,

Northeast

Atlanta, GA 30308 **Fulton County** 

Regulated By:

Federal Reserve Board

Consumer Assistance:

http://www.FederalReserveConsumerHelp.gov

Corporate Website:

http://www.suntrust.com

Contact the FDIC about SunTrust Bank

Search Results Page 1 of 1



Home

Citizen Services

**Business Services** 

Back to Coral Gables.com

**Permits and Inspections: Search Results** 

Logon Help Contact

**M** New Permit Search

#### **Permit Search Results**

Permit#:	App. Date	Street Address	Туре	Description	Status	Issue Date	Final Date	Fees Due
EL-12-03-7862	03/09/2012	241 ALMERIA AVE	ELEC LOW VOLTAGE SYSTEM	SECURITY SYSTEM INSTALLATION \$800	final	03/12/2012	04/16/2012	0.00
RC-15-10-5755	10/27/2015	241 ALMERIA AVE	BUILDING RE CERTIFICATION	40 YEAR BUILDING RECERTIFICATION OR OLDER BUILT (1955)	issued	10/28/2015		600,00

The City's online services are protected with an **SSL encryption certificate**. For technical assistance, please call 305-569-2448 (8am-5pm, M-F).

CITY'S EXHIBIT



### **City of Coral Gables Fire Department**

**Fire Prevention Division** 2815 Salzedo Street, Coral Gables, FL 33134 Fax (305) 460-5598

The items noted below are in violation of the Florida Fire Prevention Code and/or the Florida Administrative Code. Nothing in this report supersedes any previously written, still existing violations for this occupancy/building. You are directed to comply with corrective measures as indicated.

Occupant Name: Mercedes Benz of Coral

Gables

241 Almeria Avenue

City:

Address:

Coral Gables

Inspection Date:

6/15/2015

InspectionType:

Inspected By:

AA-Tactical, Business (Annual Fire Inspection) Madelaine Mendez

305-460-5563

mmendez@coralgables.com

Suite:

Occ. Sq. Ft.:

1000

#### No violations noted at this time.

Signature on file

Company

Representative:

Robert Juan 6/15/2015

Signature on file

Inspector:

Madelaine Mendez

6/15/2015