



1. Northwest building perspective, camera facing southeast. Photo taken October 2023.



2. Northwest building perspective, camera facing southeast. Photo taken October 2023.



3. Partial north elevation, camera facing southeast. Photo taken October 2023.



4. Partial north elevation, camera facing southwest. Photo taken October 2023.



5. Partial west elevation, camera facing northeast. Photo taken October 2023.



6. Partial west elevation, camera facing east toward courtyard. Photo taken October 2023.



7. Partial west elevation, camera facing southeast. Photo taken October 2023.



8. Southwest building perspective, camera facing northeast. Photo taken May 2023.



9. Northeast building corner, camera facing southeast down alley between adjacent building and east elevation of Cla-Reina. Photo taken May 2023.



10. Courtyard, south elevation, camera facing north. Photo taken May 2023.



11. Courtyard, west elevation, camera facing southeast. Photo taken May 2023.



12. Courtyard, east elevation of entrance, camera facing up and northwest. Photo taken May 2023



13. Courtyard, south elevation, camera facing north toward lobby. Photo taken May 2023.



14. Courtyard, partial north elevation, camera facing south. Bouchon outdoor dining space. Photo taken May 2023.



15. Courtyard, partial north elevation, camera facing southwest. View of Bouchon outdoor dining area. Photo taken May 2023.



16. Courtyard, camera facing northwest. Photo taken October 2023.



17. Courtyard, camera facing northwest. Photo taken October 2023.



18. Courtyard, camera facing southeast. View of Bouchon outdoor dining area. Photo taken October 2023.



19. Courtyard, camera facing southwest. Photo taken October 2023.



20. Courtyard, partial west elevation, camera facing southwest. Photo taken October 2023.



21. Courtyard, north elevation, camera facing northwest. Photo taken October 2023.



22. Courtyard, partial south elevation, camera facing north.



23. Courtyard, west elevation, entrance from Courtyard to Bouchon service corridor, camera facing southeast. Photo taken May 2023.



24. Courtyard, partial west elevation, camera facing southeast. Photo taken October 2023.



25. 1st floor interior, lobby area just inside the entrance from the north elevation. Camera facing southeast. Photo taken October 2023.



26. 1st floor interior, north wing, lobby. Camera facing north. Photo taken July 2023.



27. 1st floor interior, north wing, lobby. Camera facing east. Photo taken May 2023.



28. 1st floor interior, lobby area just inside the entrance from the north elevation. Camera facing southwest. Photo taken May 2023.



29. 1st floor interior, lobby, camera facing south toward Courtyard. Photo taken October 2023.




30. 1st floor interior, lobby and main stair, camera facing southwest. Photo taken October 2023.



31. 1st floor, Shingo, northwest corner of building, east wing, camera facing east.
Photo taken May 2023.



32. 1st floor, Shingo, northwest corner of building, east wing, camera facing southwest.
Photo taken May 2023.



33. 1st floor, Shingo, east wing; camera facing north, showing entrance to dinning area. Photo taken May 2023.



34. 1st floor, Shingo, east wing; camera facing southeast, showing waiting area. Photo taken May 2023.



35. 1st floor, Shingo, east wing; camera facing northwest, showing just inside main entrance. Photo taken May 2023.



36. 1st floor, Shingo, east wing; camera facing east, showing kitchen. Photo taken May 2023.



37. 1st floor, Bouchon, south wing; camera facing northeast, transition area between kitchen and dinning area. Photo taken May 2023.



38. 1st floor, Bouchon, south wing; camera facing northwest, showing restroom hall. Photo taken May 2023.



39. 1st floor, Bouchon, south wing; camera facing southeast, showing dinning area. Photo taken October 2023.



40. 1st floor, Bouchon, south wing; camera facing southwest, showing bar area. Photo taken October 2023.



41. 1st floor, Bouchon, south wing; camera facing east, showing dinning area. Photo taken October 2023.



42. 1st floor, Bouchon, south wing; camera facing west, showing length dining and bar area. Photo taken October 2023.



43. 1st floor, Bouchon, south wing; camera facing northeast, showing restroom. Photo taken May 2023



44. 1st floor, Bouchon, south wing; camera facing southwest, showing view of “Receiving Breakdown”; note the doors to the cooler and fire stars are on the right-hand side. Photo taken May 2023.



45. 1st floor, Bouchon, south wing; camera facing south; showing “Dish Wash Room,” “Receiving Breakdown” areas. Photo taken May 2023.



46. 1st floor, Bouchon, camera facing south. View of back of “Receiving Breakdown,” and note the door to “Existing Porch.” Photo taken May 2023.



47. 2nd floor, stair, camera facing down and southwest. Photo taken October 2023.



48. 2nd floor stair, camera facing down and west. Photo taken October 2023.



49. 1st floor, Bouchon, south wing; camera facing northwest, showing prep station next to main kitchens. Photo taken May 2023.



50. 1st floor, Bouchon, south wing; camera facing northwest. Photo taken May 2023.



51. 1st floor, Bouchon, south wing; camera facing northwest showing “Finishing Kitchen.” Photo taken May 2023.



52. 1st floor, Bouchon, south wing; camera facing southwest showing “Prep Kitchen.” Photo taken May 2023.



53. 1st floor, Bouchon, the east wing; camera facing south, showing "Pot Wash" area. Photo taken May 2023.



54. 2nd floor, Bouchon, north wing, access to Courtyard Camera facing southwest.



55. 1st floor, Bouchon, south wing; camera facing east, showing service area. Photo taken May 2023.



56. 1st floor, Bouchon, south wing; camera facing southwest, showing "Dining Room 2". Photo taken July 2023.



57. 1st floor, Bouchon, south wing; camera facing northwest, showing "Dining Room 2". Photo taken July 2023



58. 1st floor, Bouchon, south wing; camera facing northwest, showing view from kitchen corridor; note “Dry Storage” door at the end of the hall. Photo taken May 2023.



59. 1st floor, Bouchon, camera facing southwest. View of “Janitor” space, with mop sink. Photo taken May 2023.




60. 1st floor, Bouchon, camera facing northwest. View into “Dry Storage.”
Photo taken July 2023.



61. 2nd floor lobby; camera facing northeast toward entrance to east wing. Photo taken October 2023.



62. 2nd floor elevator lobby, north wing, camera facing southeast.
Photo taken May 2023.



63. 2nd floor interior, north wing, corridor, restrooms on the right. Camera facing south. Photo taken May 2023.



64. 2nd floor, restroom, camera facing northwest. Photo taken May 2023.



65. 2nd floor lobby, camera facing northeast. Photo taken October 2023.



66. 2nd floor, office 203, camera facing south. Photo taken October 2023.



67. 2nd floor, north wing; camera facing north, showing office 203. Photo taken October 2023.



68. 2nd floor, north wing; camera facing south, showing office 203. Photo taken October 2023.



69. 2nd floor, office 203, camera facing up and south. Photo taken October 2023.



70. 2nd floor lobby, north wing, camera facing west toward office 202.
Phot taken May 2023.




71. 2nd floor, north wing, office 202, camera facing southwest. Photo taken October 2023.




72. 2nd floor, north wing, office 202, camera facing south, southwest. Photo taken October 2023.



73. 2nd floor, north wing. Camera facing southeast, extended view of emergency exit hallway in Office 202.



74. 2nd floor, north wing; camera facing northeast, showing view of Office 204. Photo taken July 2023.



75. 2nd floor, north wing; camera facing southwest, showing view of Office 204. Photo taken July 2023.



76. 2nd floor, east wing; camera facing southeast, showing view of Office 206. Photo taken October 2023.



77. 2nd floor, east wing; camera facing north, showing view of Office 206. Photo taken October 2023.



78. 2nd floor interior, east wing. Camera facing northeast, showing view of Office 208.
Photo taken October 2023.



79. 2nd floor interior, east wing. Camera facing east, showing view of Office 208.
Photo taken October 2023.



80. 2nd floor interior, east wing. Camera facing northwest, showing view of Office 210. Photo taken October 2023.



81. 2nd floor interior, east wing. Camera facing southwest, showing view of Office 210. Photo taken October 2023.



82. 2nd floor interior, south wing. Camera facing southwest, showing view of Office 212. Photo taken October 2023.



83. 2nd floor, south wing. Camera facing southeast, showing view of Office 212. Photo taken July 2023.



84. 2nd floor, south wing. Camera facing northeast, showing view of Office 212. Photo taken July 2023.



85. 2nd floor interior, south wing. Camera facing southwest, showing view of Office 214. Photo taken October 2023.



86. 2nd floor interior, south wing. Camera facing northeast, showing view of Office 214. Photo taken October 2023.



87. 2nd floor interior, east wing; camera facing southeast; showing second floor corridor 213. Photo taken October 2023.



88. 2nd floor, corridor 213, east wing; camera facing northwest.
Photo taken July 2023.



89. Taken July 2023, 1st floor interior, west wing; camera facing southwest, showing future interior design space. Photo taken October 2023.



90. Taken July 2023, 1st floor interior, west wing; camera facing northwest, showing future interior design space. Photo taken October 2023.