

INTERIOR ARCHITECTURAL FEATURES

FEATURE 1: ORIGINAL MARBLE FLOORS



PHOTO #7

PHOTO #8



FEATURE 2: ORIGINAL TERRAZZO FLOORS



PHOTO #9

FEATURE 3: ORIGINAL WOOD FLOORS



PHOTO # 10

PHOTO #11



FEATURE # 4 : ORIGINAL STAIRCASE



PHOTO #12

FEATURE #5: RE-ESTABLISHING ORIGINAL FOYER HEIGHT



PHOTO #13



PHOTO #14

FEATURE #5 : RE-ESTABLISHING ORIGINAL FOYER HEIGHT (CONTINUED)




PHOTO #15

FEATURE #6: RE-ESTABLISHING ORIGINAL SUNROOM ON SECOND FLOOR



PHOTO #16



PHOTO #17

FEATURE #6: RE-ESTABLISHING ORIGINAL JNRoom ON SECOND FLOOR (CONTINUED)



PHOTO #18