MIAMI-DADE COUNTY HISTORIC PRESERVATION AD-VALOREM TAX EXEMPTION

PART 1 – PRECONSTRUCTION APPLICATION

INSTRUCTIONS:

Type or print clearly in black ink. You may attach additional sheets if more space is needed.

I. PROPERTY IDENTIFICATION AND LOCATION

Historic/Site Name:	1206 Cordova Street		
Property Address:	1206 Cordova Street		
Folio Number:	03-4107-005-0051		
Legal Description:	Lot 7 & S 1/2 of Lot 8, Block , Granada Place Amended Plat, according to		

the Plat thereof, as recorded in Plat Book 13, at page 51 of the public records of Miami-Dade County, Florida.

Please check all that apply:

[Х	
]
]

Designated as a local historic landmark or site Designated as a contributing structure within a local historic district Individually listed in the National Register of Historic Places Is a contributing structure in a National Register District

Name of District Coral Gables

Please attach the designation report and resolution as proof the property is designated.

II. OWNER INFORMATION:

Name(s) of Owner(s):	Jeffrey	D. Robboy & Marlene F	Roppor
Mailing Address:	1206 Cordova Street		
Phone: 305-448-5	642	2 nd Phone: 305-687-9031	
Email: jeff@remc		2 ·	<u> </u>
If the property has mult	iple owners, p	lease attach a list of all owners and	their mailin

If the property has multiple owners, please attach a list of all owners and their mailing addresses.

III. CURRENT PHYSICAL DESCRIPTION OF PROPERTY:

A. General Information

Date of Construction: 1925 Architect (if known): Sutton & Routt

Alterations: Please provide the date and description of any physical alterations to the property. [*Example: Original casement windows were replaced with jalousie windows around 1974.*]

The original windows were replaced with single hung windows in 2012

Additions: Please provide date and description of any additions which may have been made. [*Example: A rear bedroom and bath were added to the house in 1981.*]

A block-walled, screened porch was added to the back of the house in 1954.

B. Exterior Description

Roof Type:	flat with barrel tile	Roof Material: Membra	ne
		Example: barrel tile, asphalt shir	ngle, etc
Number of	Stories:	_ Detached Garage? (Y/N)	Y
	Plan: Rectangula		
Example: sq	uare, "L" shaped, "U" sh	aped, rectangular, irregular, etc	
Main Windo	ow Type(s): single I	nung	
Example: ca	isement, fixed, single hur	ng sash, jalousie, awning, etc	
Siding Mate	rial(s): Stucco		
Example: stucco, wood frame, brick			

Briefly describe any distinguishing Exterior Architectural Features:

[Example: the placement of the windows, chimneys, porches, columns, etc] Thick masonary walls, light colored stucco, projecting covered porch, rectilinear floor plan, roofs of varying heights and types, projecting facade planes, a prominent chimney, decorative grouped vents, as well as projecting masonry lintels and recessed windows.

C. Interior

Please list any distinguishing Interior Architectural Features found in the home that are original to the house, by room: [Example: The dining room retains the original decorative crown molding and tile floor. The living room retains the original limestone fireplace.]

There are limited interior acrchitctural featires to this house. The fireplace is really the only distinctive interior feature. There is a arched cove in one of the walls, but we are not sure if it is an original feature.

D. Auxiliary Structures

restorations.

Please describe the present appearance of any auxiliary structures on the property, such as garages, cabanas, outbuildings, perimeter walls, etc.

There is a detached garage on the northwest corner facing east. The gamage hasb two wooden hinged swing doors enclosed in a large central opening. with a parapet that is edged with "S" tile.

IV. DESCRIPTION OF PROPOSED IMPROVEMENTS

All improvements to historic properties will be evaluated for their consistency with the Secretary of Interior Standards for Rehabilitation. The application must include labeled photographs of both the interior and exterior of the property which clearly show the property and its characteristics.

What was the or	riginal use of the building?	residen	tial home	
What will the bu	uilding be used for after im	provements?	residential	home
What is the estir	mated start date of constr	uction? Jul	y 2019	
	mated completion date?			
What is the estir	mated cost of restoration/	rehabilitation	, 150,000.0	0
	e your project, includi			

A. EXTERIOR ARCHITECTURAL FEATURES

The following represents an itemization of work to be accomplished. List each principal architectural feature affected and describe the impact that restoration/rehabilitation will have on it. Label which elevation(s) contains that feature, and include a corresponding photograph for each. Please attach additional sheets if necessary.

FEATURE 1: Front Facade Elevation: East Photo Number: 1 and 2 Plan Number: A-05, A-10, A-2

Describe Work and Impact on Existing Feature: Remove door and frame that thensitions an arched door space to a rectangular door. Replace with a custom arched door. Retain the current parapet, edged with "S" tile Detached Garage FEATURE 2: Elevation: SXMXN East Photo Number: 3 and 4 Plan Number: A-09, A-05, A-10 **Describe Work and Impact on Existing Feature:** Remove garage doors and replace with hurricane rated similar to the existing feature. Raise the floor above flood level. Retain the current parapet edged with "S" tile. FEATURE 3: Port Cochere Elevation: North Photo Number: ⁵ Plan Number: A-05 **Describe Work and Impact on Existing Feature:** Remove Port Cochere (it was an addition). By removing the port corchere we showcase the fireplace, chiminy and garage doors.

800 square ft. addition in the Mediterranian Revival Style.

B. INTERIOR ARCHITECTURAL FEATURES

FEATURE 1: Fireplace

Room: Living room Photo Number: 7 Plan Number: A-03 Describe Work and Impact on

Describe Work and Impact on Existing Feature:

The fireplace will be re-faced and the mantle woll be replaced.

It will have no impact on the historical signifigance,

FEATURE 2: Arched wall cove

Room: Living Room

Photo Number: 8

Plan Number: Not called out in plans

Describe Work and Impact on Existing Feature:

There is an arched cove in the wall opposite of the fireplace. We are not sure if it was an original feature of the house but it does reflect the Mediteranian revivalist look that Merric envisioned. It will remain.

FEATURE 3:

Room: Photo Number: Plan Number: Describe Work and Impact on Existing Feature:

FEATURE 4: Room: Photo Number: Plan Number: Describe Work and Impact on Existing Feature:

C. LANDSCAPE FEATURES

Please list any restorative work to be done to **original landscape features**, including pathways, walls, fountains, etc. Include a site plan or sketch if necessary.

FEATURE 1: Pathways

Photo Number: 1

Describe Work and Impact on Existing Feature:

Poured concrete pathways will be replaced with brick paversthat represent the look of the era.

FEATURE 2: Original built in planter

Photo Number: ¹¹

Describe Work and Impact on Existing Feature:

The built in planter will remain aXXXXXX feature of the front of the house.

FEATURE 3: Photo Number: Describe Work and Impact on Existing Feature: **OWNER ATTESTATION:** I hereby attest that the information provided in this application is, to the best of my knowledge, correct, and that I own the property described above or that I am legally the authority in charge of the property. Further, by submission of this Application, I agree to allow access to the property by representatives of the appropriate official in which the property is located, for the purpose of information provided in this Application. I also understand that, if the requested exemption is granted, I will be required to enter into a Covenant with the municipality and Miami-Dade County in which I must agree to maintain the character of the property and the qualifying improvements for the term of the exemption.

 $\frac{O6/07/19}{Date}$ Signature

[Please attach the photographic documentation on subsequent pages. Submit a copy of all photographs on a CD as well, if possible.]

Page 12 of 16

PRE-CONSTRUCTION APPLICATION REVIEW TO BE FILLED OUT BY THE LOCAL HISTORIC PRESERVATION OFFICER

Street Address of prop	erty 1206 CORDOVAST.REET	
Folio number0	3-4107-005-0051	_

The local Historic Preservation Officer has reviewed Part 1 (Preconstruction Application) of the Historic Preservation Property Tax Exemption Application for the above named property and hereby:

Certifies that the above referenced property <u>qualifies as a historic property</u> consistent with the provisions of s. 196.1997 (11), F.S.

[] Certifies that the above referenced property <u>does not qualify</u> as a historic property consistent with the provisions of s. 196.1997 (11), F.S.

[Determines that improvements to the above referenced property <u>are consistent</u> with the Secretary of Interior Standard's for Rehabilitation and Guidelines for Rehabilitating Historic Buildings and the criteria set forth in Chapter 1A-38, F.A.C.

[] Determines that improvements to the above referenced property <u>are not consistent</u> with the Secretary of Interior Standard's for Rehabilitation and Guidelines for Rehabilitating Historic Buildings and the criteria set forth in Chapter 1A-38, F.A.C.

Please list any Review Comments here:		
Additional Review Comments attached? Yes No V		
Signature: Dona M. Gui		
Typed or printed name:		
Title: HISTORIC PRESERVATION OFFICER		
Date of Review: ID · 17 - 19		

Page 13 of 16



Photo # 1 Arched front door frame

C

(




Photo # 2 Closeup of arched front door

C

(



Photo # 3


0

(

()

Detached garage with two wooden, hinged, swing doors.








Photo # 5

C

(

Remove the port corchere to allow the chimney and garage doors to be highlighted




Photo # 6

(

(

Remove the covered porch addition from the 1950s and replace it with a new Medeterannian Revival style addition.



Photo # 7

0

(

Fireplace will be re-surfaced and the mantle will be replaced.




Picture # 8

Arched cove in living room wall shall remain.

C

(








Photo # 10

 \bigcirc

(

Decorative grouped vents on all sides.




Photo #11 Built in planter