



# City of Coral Gables INSPECTOR'S REPORT

Building, Code Enforcement and Public Works

3 | 20 | 2018

Date

2:20 PM

Time

Permit No:

Project Name:

Address:

3511 Alhambra C

**Department:**

**Purpose of visit:**

**Action taken:**

Building

Code Enforcement

Public Works

Random or periodic check

Scheduled inspection

Investigate reported problem

MOT

Meeting at Department

Other: \_\_\_\_\_

No action

Warning (see below)

Red tag

STOP WORK

Other: \_\_\_\_\_

Individuals present:

Jose A. Rovira

Photos taken:  Yes

No

Quantity:


2

Summary of findings:

Obstruction of the Right of Way,  
Ferns on the sidewalk path that  
need to be trimmed.

Action required:

To trim ferns  
Max allowed 3 feet radius from  
City Tree.



**ACKNOWLEDGEMENT OF WARNING**

\_\_\_\_\_  
Qualifier / Agent signature

\_\_\_\_\_  
Print name and title

Jose A. Rovira

Inspector name 78 734-4851

Rovira

Signature