


Property Photo

- New door
- Removed brick façade
- Removed decorative window elements (including the shutters)
- Lighting fixtures
- Modified landing
- Painted the property (including garage doors)




Before Photos (Google Images)

January 2019



Before Photos (Google Images)

July 2013



After Photos (Google Images)


September 2024



Property Photo


New door and landing (June 2026)

Old door and landing (Google Images
2019 and 2013)



Property Photo

Removed brick façade, added new light fixtures, and removed decorative window elements - including the shutters (June 2026)



With brick façade, 1 light fixture and with window elements and shutters (Google Images January 2022)



Property Photo

Removed decorative window elements - including the shutters (June 2026)




Removed decorative window elements with the shutters (Google Images January 2022)



Property Photo

Painted property - including the garage doors
(March/June 2026)



Old paint on the property – including garage doors
(Google Images January 2022)

