# **City of Coral Gables**

405 Biltmore Way Coral Gables, FL 33134 www.coralgables.com



## **Meeting Minutes**

Wednesday, April 20, 2022 8:30 AM

City Hall, Commission Chambers

## **Code Enforcement Board**

Chairperson Andres Murai, Jr Vice Chairperson George Kakouris Board Member Ignacio Borbolla Board Member Maria Cruz Board Member Jeffrey Flanagan Board Member J.M. Guarch, Jr. Board Member Christopher Zoller

#### **CALL TO ORDER**

### **APPROVAL OF MINUTES**

#### **ROLL CALL**

Present: 4 - Chairperson Murai Jr, Board Member Cruz, Board Member Guarch and

**Board Member Zoller** 

Excused: 3 - Vice Chair Kakouris, Board Member Borbolla and Board Member Flanagan

### **PUBLIC HEARING**

#### **NEW CASES**

1819

CE290133-12 1206 Douglas Road

Violation Description - Ch. 105-29 City Code (CPM): Property in need of maintenance (buildings at 3 SIDONIA, 1210 DOUGLAS, 1208 DOUGLAS, 1206 DOUGLAS, and 4 ANTILLA): damaged soffit/fascia, dirty roof, dirty exterior walls, and dirty sidewalks/walkways/entryways.

Remedy - Please obtain the necessary permit(s) and make all the required repairs/ replacements to bring the property into compliance

Owner - Fipro Holdings LLC/c/o Jose Baloyra, Esquire

Code Enforcement Officer Delgado

Guilty/30 days to comply/\$250.00 a day/\$108.75 Admin. Fee

Yeas: 4 - Chairperson Murai Jr, Board Member Cruz, Board Member Guarch and

**Board Member Zoller** 

Excused: 3 - Vice Chair Kakouris, Board Member Borbolla and Board Member Flanagan

2921

CE303962-06 15 Santillane Avenue

Violation Description - Exterior of property requires maintenance: Roof, awnings, walls, front stairs, steps on west side and walkway are dirty. There are also some cracks on wall in the front of property.

Remedy - Must clean and repair cracks. Obtain approval and permit.

Owner - Fipro Holdings LLC c/o Jose Baloyra Esquire

Code Enforcement Officer Delgado

Guilty/30 days to comply/\$250.00 a day/\$108.75 Admin. Fee

This Code Enforcement Board Violation was found Guilty

CE306210-11 2921

228 Madeira Avenue

Violation Description - Exterior of property requires maintenance: Roof, walls, front porch, walkway, sidewalk and lion statues are dirty. Soffit and fascia in disrepair. Sewage backup on private property causing backup onto city right of way.

Remedy - Must clean and/or paint property. Repair septic issue. Obtain approvals and permits.

Owner -Epulare LLC

Code Enforcement Officer Delgado

Guilty/30 days to comply/\$250.00 a day/\$108.75 Admin. Fee

This Code Enforcement Board Violation was found Guilty

2521

CE302771-05 455 Amalfi Avenue

Violation Description - Installation of artificial grass without approval or permit. Swale in need of maintenance/missing grass all dirt.

Remedy - Must obtain approval and permit (Artificial grass) or re-sod with new grass. Swale must be re-sod.

Owner - Floral Mayoral Trs Flor Mayoral Residence Trust

Code Enforcement Officer Roman

This Code Enforcement Board Violation was Continued prior to hearing

1621

CE305733-10 6900 Barquera Street

Violation Description - Installation of artificial grass on property without approval or permits.

Remedy - Must obtain approval and permit or resod area.

Owner - Deliah Angela Alonso

Code Enforcement Officer Roman

Guilty/2 weeks to apply/60 days to finalize/\$150.00 a day/\$108.75 Admin. Fee

This Code Enforcement Board Violation was found Guilty

CE305096-08 1510 Pizarro Street

1921

Violation Description - Installation of wooden structure (Pergola) in backyard and brick pavers under and around structure without a permit.

Remedy - Must obtain all permits and approvals.

Owner - Daniel J. Fernandez

Magaly Fernandez

Code Enforcement Officer Vilato

Guilty/90 days to comply/\$150.00 a day/\$108.75 Admin. Fee

This Code Enforcement Board Violation was found Guilty

CE290667-01 1620

CE290667-01 820 Tangier Street

Violation Description - Expired Permit on Property

BL-16-08-7145

- \*\* Change of Contractor to permit BL-20-03-6693
- \*\* expires 9/2/21 will re inspect\*\*

Remedy -Must Re-activate permit and obtain all required inspections to close.

Owner - Madhavan Nair & W Rema

Code Enforcement Officer Schwartz

Guilty/60 days to comply/\$150.00 a day/\$108.75 Admin. Fee

This Code Enforcement Board Violation was found Guilty

CE298937-12 1720 1615 Ferdinand Street

Violation Description - WWP- Pool work started prior to permit being issued.

PWP - Sidewalk work started prior to permit being issued.

Remedy - STOP WORK ON POOL AND SIDEWALK.

Do no continue until permits have been issued.

Owner - Muster Investment LLC

Code Enforcement Officer Schwartz

Agreed Order entered

This Code Enforcement Board Violation was found Guilty

2121

CE305802-10 241 Romano Avenue

Violation Description - Exterior painting without a color palate approval.

Remedy - Must obtain a color palate approval card prior to completion.

Owner - Migdalia Gonzalez

Code Enforcement Officer Juan Garcia

Agreed Order entered

This Code Enforcement Board Violation was found Guilty

CE306987-12 3021

241 Romano Avenue

Violation Description - Windows replaced without a permit.

Remedy - Must obtain necessary permits and inspections.

Owner - Migdalia Gonzalez/ Fernando E. Heria

Code Enforcement Officer Juan Garcia

Agreed Order entered

This Code Enforcement Board Violation was found Guilty

CE305474-09 2721

172 Paloma Avenue

Violation Description - Dock repaired without approval and permits.

Remedy - Need to obtain approval and permits.

Owner - Carla Quispez Asin &

Code Enforcement Officer Quintana

Guilty/90 days to comply/\$150.00 a day/\$108.75 Admin. Fee

This Code Enforcement Board Violation was found Guilty

#### **CONTINUED CASES**

CE289688-11 2519 422 Catalonia Avenue

Violation Description - Roof is in disrepair and has large tarp with sandbags.

Remedy - Must obtain re roof, or repair permit.

Owner - Gonzalo Goicochea

Code Enforcement Officer Juan Garcia

Guilty/7 days to apply/90 days to finalize/\$150.00 a day/\$108.75 Admin Fee

This Code Enforcement Board Violation was found Guilty

CE300788-03 1021 4700 SW 8 Street

Violation Description - Installation of new sign on business "Gables Cove".

Remedy - Must obtain "after the fact" permit for installed sign.

Owner - Cuernos Management LLC

Code Enforcement Officer Schwartz

This Code Enforcement Board Violation was Continued prior to hearing

## **HISTORIC CASES**

CE291298-0 2020

CE291298-02 217 Florida Avenue

Violation Description - Installation/removal of Concrete slab, air condition unit, removal of asphalt driveway, removal of exterior railings from concrete walkways steps, plumbing work being performed, replacements of exterior doors (3) without approval or permits.

Remedy - Must obtain approval and permit(s) upon any and pass inspections for all work done on property.

Owner - Melissa Martin

Code Enforcement Officer Roman

Agreed Ordered entered

This Code Enforcement Board Violation was found Guilty

REQUEST TO BE HEARD ON EXTENSION OF TIME

**STATUS** 

**ADJOURNMENT**