



City of Coral Gables
INSPECTOR'S REPORT

Building, Code Enforcement and Public Works

INSPECTION NO.: _____

3 | 11 | 2022

Date
8:30AM
Time

Permit No: _____ Project Name: 115 Frow Ave Address: Coral Gables, FL.

Department: Building Code Enforcement Public Works

Purpose of visit: Random or periodic check Scheduled inspection Investigate reported problem MOT Meeting at Department Other: _____

Action taken: No action Warning Red tag STOP WORK Other: _____

Individuals present: Noel Polo (P.W.) P.W. SANITARY Division Photos taken: Yes No Quantity: _____

Summary of findings: (REQUIRED)

① PUBLIC WORKS SEWER DIVISION CONDUCTED A MAIN SEWER LINE LOCATION FOR THE LATERAL BRANCH TO 115 FROW AVE.

② LATERAL DOES EXISTING BUT, NO SEWAGE FLOWS TO SEWER DUE TO BROKEN SANITARY DRAINAGE PIPING UNDER RESIDENCE.

Action required: (REQUIRED)

① Required Plans & Permit For Plumbing Repairs.

② Advise Code Enforcement To Site Property & Development Services

ACKNOWLEDGEMENT OF WARNING

Qualifier / Agent signature

Print name and title

R. Perez # 9462 Inspector name

[Signature] Signature