

HISTORIC PRESERVATION BOARD

MAY 15, 2024

CORAL
GABLES®
THE CITY BEAUTIFUL




CASE FILE

AV 2020-02

An application requesting ad valorem tax relief for the property at **112 Alhambra Circle**, a Local Historic Landmark, legally described as Lots 1 and 2, Block 22, Coral Gables Section “L,” according to the Plat thereof, as recorded in Plat Book 8, at Page 85 of the Public Records of Miami-Dade County, Florida.

The related Special Certificated of Appropriateness, COA (SP) 2019-009 and COA (SP) 2019-015, were granted design approval by the Historic Preservation Board on July 18, 2019 and October 17, 2019.



Location of property
at 112-116
Alhambra Circle
The Cla-Reina /
La Palma Hotel

*Aerial Photograph
Courtesy Miami-Dade
County Property
Appraiser*

FISHBAUGH
SAMPLE ALBUM

**112-116
Alhambra
Circle**

Historic Photo
July 15, 1926





112-116 Alhambra Circle

Photo
May 15, 2024



North Façade Main Entry - Before



North Façade Main Entry - After



Northwest Corner – Before



Northwest Corner – After



Northwest Corner Detail – Before



Northwest Corner Detail – After



West Façade – Before



West Façade – After



North Façade (east end) – Before

North Façade
(east end) – After





West Façade – Before



West Façade – After



West Façade / Southwest Corner – Before



West Façade / Southwest Corner – After



South Façade (Alley) – Before



South Façade (Alley)– After



West Façade (looking into courtyard) – Before



West Façade (looking into courtyard) – After



Courtyard Looking North – Before (Left) and After (Right)



Courtyard Looking East – 1920s



East Facade – After



Courtyard Looking North – Before (Left) and After (Right)



Courtyard Looking South –
Before



Courtyard Looking South –After



Entrance Lobby – Before and After



Northwest Corner Interior (Typical First Floor Condition) – Before



Northwest Corner Interior (Tenant Buildout) – After



South Wing
(Southwest Corner) –
Before & After

Second Floor Near
Lobby (Typical
Second Floor
Condition Before -
Left) & After
(Right)





Second Floor Looking North (Typical Second Floor Condition Before - Left) & After (Right)



Second Floor Offices – After

