# **Code Enforcement Board Agenda Minutes**

4/20/16, 8:30 A.M.

Commission Chambers 405 Biltmore Way Coral Gables, FL 33134

| <u>Members</u>              | 1/20/2016 | 2/17/2016               | 3/16/2016 | 4/20/2016 |  |
|-----------------------------|-----------|-------------------------|-----------|-----------|--|
| 1. Chandra Iglesias-Balsera | Р         | Р                       | UE        | Р         |  |
| 2. Richard DeWitt           |           | P - New board<br>member | Р         | E         |  |
| 3. J.M. Guarch              | Р         | Р                       | Р         | Р         |  |
| 4. George Kakouris          | Р         | Р                       | Р         | Р         |  |
| 5. Andres Murai Jr.         | Р         | Р                       | Р         | Р         |  |
| 6. Maria Velez              | Р         | E                       | Р         | Р         |  |
| 7. Christopher Zoller       | Р         | Р                       | E         | Р         |  |

 $P = Present \quad E = Excused \quad \begin{array}{c} UE = & C = Meeting \\ Unexcused & Cancelled \end{array}$ 

### Representing the City of Coral Gables as Code Enforcement prosecutor:

1. Miriam Ramos, Deputy City Attorney

| Case<br>Number | Address In<br>Violation | Owner                 | Owner Address        | Violation Description   | Remedy   | C.E.O.             |
|----------------|-------------------------|-----------------------|----------------------|---|--|--------------------|
| CE259376       | 4930<br>BILTMORE DR     | ERNESTO<br>VALDES     | 1235 MARIOLA<br>CT   | Repairs to dock without approval and a permit.                                    | Need to obtain all<br>approvals and<br>permits from Public<br>Works, DERM and<br>Building<br>Department. | Terri<br>Sheppard  |
| CE259382       | 6965<br>GRANADA<br>BLVD | LUIS CRUZ &W<br>MARIA | 6965 GRANADA<br>BLVD | Planting with rocks on the swale/public right of way without approval and permit. | Obtain required permit from the Public Works Department or remove planting/rocks.                        | Amparo<br>Quintana |

| CE261166 | 240 MAJORCA<br>AVE      | MARIA VELEZ<br>COUTO                        | 240 MAJORCA<br>AVE   | Tiled exterior front walkway without approval and permit.   | Must obtain approval and permit.   | Martha<br>Delgado            |
|----------|-------------------------|---|----------------------|---|--|------------------------------|
| CE261241 | 640<br>SANTANDER<br>AVE | K N L M INC                                 | 6365 COLLINS<br>AVE  | Roof has leaks and roof tiles are missing. Eaves/fascia boards are dirty. Exterior walls are dirty, paint is chipped, paint at rear is not uniform in color with the building and walls are discolored. Decorative iron gate is rusted. Walkway on the second floor is dirty. | Must repair roof. Clean and/or paint eaves/fascia boards, exterior walls and walkway on second floor. Paint and/or repair decorative iron gate. Obtain permits for work, if necessary. | Cristina<br>Perez-<br>Thayer |
| CE259348 | 835<br>ANASTASIA<br>AVE | MIGUEL<br>MENDEZ-<br>GERVAIS &W<br>GLORIA I | 835 ANASTASIA<br>AVE | Transferred from Comply<br>Complaint #1204576<br>Case#12889 Open permits for<br>over 1 year.  | Reactivate permits<br>open for over 1 year,<br>perform all<br>inspections, and<br>close out permits.   | Carlos<br>Correa             |

| CE261994 | 817<br>ALHAMBRA<br>CIR | ZHUOYAN<br>ZHANG                   | 817 ALHAMBRA<br>CIRCLE   | Exterior walls and CBS perimeter wall are dirty. Decorative iron gate on CBS wall has paint that is peeling. | Must clean and/or paint exterior walls, CBS perimeter wall, and decorative iron gate on CBS wall. Obtain permit for work, if necessary. | Cristina<br>Perez-<br>Thayer |
|----------|------------------------|------------------------------------|--------------------------|--|---|------------------------------|
| CE262315 | 2509 Red<br>Road       | FVP Red Road<br>LLC                | 15500 NEW<br>BARN RD 104 | Temporary chain link fence<br>installed without a approval and<br>a permit.                                  | Need to obtain necessary permit.  | Terri<br>Sheppard            |
| CE256721 | 1414 Galiano<br>St.    | NICOLAS F<br>TRUJILLO &W<br>BRENDA | 5160 ALTON RD            | Property is in need of maintenance. Exterior walls, awnings, walkway and front steps are dirty.              | Must clean and/or paint. Obtain necessary permits.  | Martha<br>Delgado            |

## **Appointment**

Commissioner Lago

Commissioner Slesnick

> Mayor Cason

Vice-Mayor Quesada

Commission-As-A-Whole

Commissioner Keon

> Mayor Cason

Board Action and/or Comments

### **Board motion:**

No Contest/30 days to comply/\$150 per day fine thereafter/ \$108.75 administrative fee

### **Board motion:**

Guilty/90 days to comply/\$150 per day fine thereafter/\$108.75 administrative fee

### **Board motion:**

Guilty/30 days to comply/\$150 per day fine thereafter/\$108.75 administrative fee

# **Board motion:**

Guilty/60 days to comply/\$150 per day fine thereafter/\$108.75 administrative fee

#### **Board motion:**

Extension of time granted for 6 months (October hearing)

### **Board motion:**

Guilty/60 days to comply/\$150 per day fine thereafter/\$108.75 administrative fee

### **Board motion:**

Continued for 90 days (July hearing)

## **Board motion:**

Guilty/30 days to comply/\$150 per day fine thereafter/\$108.75 administrative fee