## Garcia, Adolfo

From: Sent: To: Cc: Subject: Attachments:	alp@alp-law.com Tuesday, September 29, 2020 11:21 AM Gonzalez, Christian Garcia, Adolfo; Garcia, Dayron 535 Caligula Ave IMG_20200925_170632_resized.jpg; IMG_20200925_170641_resized.jpg; IMG_20200925_ 170655_resized.jpg; IMG_20200925_170701_resized.jpg; IMG_20200925_170710 _resized.jpg; IMG_20200925_170718_resized.jpg; IMG_20200925_170735.jpg; IMG_ 20200925_170809_resized.jpg
Follow Up Flag:	Follow up
Flag Status:	Flagged

**CAUTION:** External email. Do not click links or open attachments unless you recognize the sender and know the content is safe.

## Dear Christian:

As we just discussed, please see the attached photographs and correct the inspection results to show that the work has not been done. Also, please advise whether the permit, not having an approved inspection, would now have expired.

Thanks!

Very truly yours,

Alexander L. Palenzuela Law Office of Alexander L. Palenzuela, P.A. 1200 Brickell Avenue, Suite 1950 Miami, FL 33131-3298 tel: (305) 333-0467 alp@alp-law.com www.alp-law.com

**CONFIDENTIAL COMMUNICATION:** This message, together with any attachments, is intended only for the addressee. It may contain information which is legally privileged, confidential, and exempt from disclosure. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, use, or any action or reliance on this communication is strictly prohibited. If you have received this e-mail in error, please notify the sender immediately by telephone, at (305) 333-0467 and by return e-mail and double delete this message, along with any reply and attachments.