



## Legislation Details (With Text)

**File #:** CE279822    **Version:** 1    **Name:**  
**Type:** Code Enforcement Board    **Status:** Noted and Filed  
 Violation  
**File created:** 12/10/2018    **In control:** Code Enforcement Board  
**On agenda:** 1/16/2019    **Final action:** 1/16/2019  
**Enactment date:**    **Enactment #:**

**Title:** 5 Alcantarra Avenue  
 Violation Description - Broken concrete wall, standing water in decorative fountain.  
 Remedy - Repair wall and remove and maintain fountain free from standing water.  
 Owner -Maria L Lopez  
 Code Enforcement Officer J. Garcia

**Sponsors:**

**Indexes:**

**Code sections:**

**Attachments:** 1. Violation Photos, 2. 5 Alcantarra Violation photos, 3. 5 Alcantarra Postings and Documents

Date	Ver.	Action By	Action	Result
1/16/2019	1	Code Enforcement Board	found Guilty	Pass

5 Alcantarra Avenue  
 Violation Description - Broken concrete wall, standing water in decorative fountain.  
 Remedy - Repair wall and remove and maintain fountain free from standing water.  
 Owner -Maria L Lopez  
 Code Enforcement Officer J. Garcia