



Legislation Text

File #: CE285332, **Version:** 1

603 Minorca Avenue

Violation Description - Work done on property without obtaining approvals and permits. (i.e. iron fence installed along SW corner of property, gazebo installed at NW corner of property, in side and rear setbacks, and 2 roofed structures, attached to rear of home). There are also 2 storage sheds on N side of home.

Remedy - Must obtain necessary permits to keep on property or permit for demolition of aforementioned items, as well as passing all pertinent inspections. Must also remove storage sheds from exterior of home.

Owner - GG Property Holdings LLC

Code Enforcement Officer Bermudez