



Legislation Text

File #: CE290302-123019, **Version:** 1

570 University Drive

Violation Description - Property has expired Mechanical permit # ME-09-10-3702.

Remedy - Must reactive permit, call for all inspections and pass all pending inspection to close permit.

Owner - Camille Chung

Code Enforcement Officer Bermudez