



Legislation Details (With Text)

File #: CE274994 **Version:** 1 **Name:**
Type: Code Enforcement Board Violation **Status:** Withdrawn
File created: 6/11/2018 **In control:** Code Enforcement Board
On agenda: 1/16/2019 **Final action:** 12/31/2018
Enactment date: **Enactment #:**
Title: 5301 Riviera Drive

Violation Description: MIN Violation CC 105-5 (I.E. Roof, front fascia and drip rail on corner of property in disrepair.

Remedy: Must repair roof, front fascia and drip rail on corner of property. Must obtain all necessary permits and inspections.

Owner: Edward Fyfe & W/Maria J

Code Enforcement Officer: Joseph Paz

Sponsors:

Indexes:

Code sections:

Attachments: 1. 5301 Riviera BL-18-03-4140, 2. 5301 Riviera- MIN NOV Posting (1), 3. 5301 Riviera- MIN NOV Posting (2), 4. 5301 Riviera- MIN Remains (2), 5. 5301 Riviera- MIN Remains (3), 6. 5301 Riviera- MIN Remains (4), 7. 5301 Riviera- MIN Remains, 8. 5301 Riviera- MIN Violation (1), 9. 5301 Riviera- MIN Violation (2), 10. 5301 Riviera- MIN Violation (3), 11. 5301 Riviera- MIN Violation (4), 12. 5301 Riviera- MIN Violation (5), 13. 5301 Riviera- MIN Violation (6), 14. 5301 Riviera- MIN Warning Posting (1), 15. 5301 Riviera- MIN Warning Posting (2), 16. 5301 Riviera- Permit for Roof (Pending Approval and being Issued), 17. 5301 Riviera- SUM Inspection (1), 18. 5301 Riviera- SUM Inspection (2), 19. 5301 Riviera- Summons Posting (1), 20. 5301 Riviera- Summons Posting (2), 21. Email from Contractor requesting extension- 2.11.2018, 22. Email to Ivonne Cutie- Summons Request, 23. Ownership

Date	Ver.	Action By	Action	Result
7/18/2018	1	Code Enforcement Board		
6/20/2018	1	Code Enforcement Board		

5301 Riviera Drive

Violation Description: MIN Violation CC 105-5 (I.E. Roof, front fascia and drip rail on corner of property in disrepair.

Remedy: Must repair roof, front fascia and drip rail on corner of property. Must obtain all necessary permits and inspections.

Owner: Edward Fyfe & W/Maria J

Code Enforcement Officer: Joseph Paz