



## Legislation Details (With Text)

**File #:** CE277850 **Version:** 1 **Name:**  
**Type:** Code Enforcement Board **Status:** Noted and Filed  
Violation  
**File created:** 9/12/2018 **In control:** Code Enforcement Board  
**On agenda:** 10/17/2018 **Final action:** 10/17/2018  
**Enactment date:** **Enactment #:**  
**Title:** COMPLIED - 102 Menores Avenue

Violation Description - Laminate floor installed without a permit. Power meter enclosure in first floor hallway built without a permit. Washer and dryer installed without a permit. Termite infestation throughout building .

Remedy - Must obtain all necessary permits and inspections. Must remove termite infestation.

Owner - San Bernardo Investment LLC

Code Enforcement Officer J. Garcia

### Sponsors:

### Indexes:

### Code sections:

**Attachments:** 1. Warning signed, 2. Warning Posting (2), 3. Warning Posting (1), 4. Warning Affidavit, 5. sunbiz, 6. Summons\_to\_Appear, 7. Posting\_From\_inspector\_Rudy\_Perez, 8. ownership, 9. NOV affidavit, 10. Notice\_of\_Violation-signed, 11. Letters\_of\_termite\_infestation, 12. letter\_from\_fire\_inspector, 13. IMG\_3119, 14. IMG\_3117, 15. IMG\_3116, 16. IMG\_3113, 17. IMG\_3112, 18. IMG\_3111, 19. Email from J. Pino for 102 Menores, 20. Complainant documentation (2), 21. Complainant documentation (1), 22. 102\_Menores\_NOV\_Posting\_(2), 23. 102\_Menores\_NOV\_Posting\_(1), 24. 102 Menores Summons posting(5), 25. 102 Menores Summons posting(4)

Date	Ver.	Action By	Action	Result
10/17/2018	1	Code Enforcement Board	Complied prior to hearing	

### COMPLIED - 102 Menores Avenue

Violation Description - Laminate floor installed without a permit. Power meter enclosure in first floor hallway built without a permit. Washer and dryer installed without a permit. Termite infestation throughout building .

Remedy - Must obtain all necessary permits and inspections. Must remove termite infestation.

Owner - San Bernardo Investment LLC

Code Enforcement Officer J. Garcia