



Legislation Details (With Text)

File #: CE279822 **Version:** 1 **Name:**
Type: Code Enforcement Board Violation **Status:** Noted and Filed
File created: 12/10/2018 **In control:** Code Enforcement Board
On agenda: 1/16/2019 **Final action:** 1/16/2019
Enactment date: **Enactment #:**

Title: 5 Alcantarra Avenue

Violation Description - Broken concrete wall, standing water in decorative fountain.

Remedy - Repair wall and remove and maintain fountain free from standing water.

Owner -Maria L Lopez

Code Enforcement Officer J. Garcia

Sponsors:

Indexes:

Code sections:

Attachments: 1. Violation Photos, 2. 5 Alcantarra Violation photos, 3. 5 Alcantarra Postings and Documents

Date	Ver.	Action By	Action	Result
1/16/2019	1	Code Enforcement Board	found Guilty	Pass

5 Alcantarra Avenue

Violation Description - Broken concrete wall, standing water in decorative fountain.

Remedy - Repair wall and remove and maintain fountain free from standing water.

Owner -Maria L Lopez

Code Enforcement Officer J. Garcia