



## Legislation Details (With Text)

**File #:** CE285932    **Version:** 1    **Name:**  
**Type:** Code Enforcement Board Violation    **Status:** Noted and Filed  
**File created:** 9/25/2019    **In control:** Code Enforcement Board  
**On agenda:** 10/16/2019    **Final action:** 10/16/2019  
**Enactment date:**    **Enactment #:**

**Title:** 628 Aledo Avenue

Violation Description - (EXP) Permit BL-13-06-0349 & BL-17-08-1882 are expired.

Remedy - Must reactivate building permit. Must pass all necessary inspection to close permit.

Owner - Jackeline Londono

Code Enforcement Officer Bermudez

### Sponsors:

### Indexes:

### Code sections:

**Attachments:** 1. Photos, 2. Expired Permits 101519, 3. Expired Permit, 4. Permit expired - BL13060349 - 061319, 5. Permit expired - BL17081882 - 061319, 6. EXP CODE, 7. Property owner, 8. Posting Pictures, 9. Code Enforcement Violation Warning signed, 10. Notice of Violation signed, 11. NOV Affidavit, 12. USPS Tracking (NOV), 13. Summons signed, 14. Summon Affidavit, 15. USPS Tracking (SUM)

Date	Ver.	Action By	Action	Result
10/16/2019	1	Code Enforcement Board	found Guilty	Pass

628 Aledo Avenue

Violation Description - (EXP) Permit BL-13-06-0349 & BL-17-08-1882 are expired.

Remedy - Must reactivate building permit. Must pass all necessary inspection to close permit.

Owner - Jackeline Londono

Code Enforcement Officer Bermudez