

Legislation Text

File #: CE278003, Version: 1

535 Caligula Avenue

Violation Description - MIN CC 105 - Sections of wall in backyard of property has collapsed and is in disrepair.

Remedy - Must repair wall in rear of property. Must seek all necessary permits and inspections prior to commencing work.

Owner - Sean Coutts

Code Enforcement Officer Paz