

## City of Coral Gables

405 Biltmore Way Coral Gables, FL 33134 www.coralgables.com

## Legislation Text

File #: CE283651, Version: 1

881 San Pedro Avenue

Violation Description - Roof, fascia, eaves, gutters, stonework are dirty, peeling, discolored and/or in need of paint. Front door, garage door, wooden trim(s) and window pane are in disrepair.

Remedy - Must make necessary repairs, clean and paint any and all items noted above. Obtain any required approvals and permits, if needed, prior to commencing work.

Owner - Dennis Deida LLC

Code Enforcement Officer A. Garcia