



Legislation Text

File #: CE302701-052321, **Version:** 1

1230 Genoa Street

Violation Description - 1) Sections 34-202 and 34-203 of the City Code - Failure to maintain (as set forth herein) and register vacant property.

2) Section 105-26 of the City Code and Section 105.1 of the Florida Building Code and Sections 3-207 and 3-208 and of the City Zoning Code - Installation of wall unit air conditioner, including opening cut into wall, without a permit.

3) Sections 224, 226, 227, 248, 250, 253, 254, 255, 275, 278, 280, and 281 of Chapter 105, Minimum Housing Code, of the City Code - As to the detached garage/accessory structure: Failure to maintain an accessory structure by allowing: rodent and termite infestation; the roof to collapse and for the structure to fall into disrepair, creating a hazard; an accumulation of trash and debris in the structure; cracks and loose plaster on the walls.

4) Sections 224, 248, 250, 253, 254, 255, 275, 278, 279, 280, and 281 of Chapter 105, Minimum Housing Code, of the City Code - As to the single-family home: Failure to maintain the structure by allowing: a structural beam in the living room to crack and sag; termite infestation; roof leaks; holes in car port ceiling; an accumulation of trash and debris in the structure; cracks and loose plaster to fall from the ceiling and walls; the exterior walls, walkway, pavers, front door, chimney, and concrete ribbons to become dirty or cracked; driveway approach to become pitted.

Remedy -1) Register the Property and apply for, obtain, and pass final inspection on all required permits to maintain the property.

2) Apply for, obtain, and pass final inspection on all required development approvals, including, but not limited to, building permits to legalize or demolish unpermitted work.

3) Tent and fumigate the structure to remove the rodent and termite infestation; remove all trash and debris and apply for, obtain, and pass final inspection on color pallet approval to paint the Structure and building permits for the repairs, as required.

4) Tent and fumigate the structure to remove the termite infestation; remove all trash and debris and apply for, obtain, and pass final inspection on color pallet approval to paint the Structure and building permits for the repairs, as required.

Owner - 1230 Genoa LLC

Code Enforcement Officer Schwartz